



SERVICE BULLETIN

| | | |
|------------------------------|--------------------------|---------------------------|
| Classification: FA05-002b | Reference: NTB05-097b | Date: January 12, 2009 |
|------------------------------|--------------------------|---------------------------|

2005-2009 TITAN AND ARMADA; CAM BOLTS FOR FRONT WHEEL ALIGNMENT

This bulletin has been amended. The Applied Vehicles model year range has been expanded. Please discard all previous copies of this bulletin.

- APPLIED VEHICLES:** 2005 - 2009 Titan (A60)
2005 - 2009 Armada (TA60)
- APPLIED VINS** 2005 Titan built after 1N6AA0(***)5N 566358
2005 Armada built after 5N1AA08(**)5N 733885
2006 - 2009 vehicles: All VINs
- APPLIED DATE** Vehicles built after June 2, 2005

IF YOU CONFIRM

An Applied Vehicle needs to have the front wheel alignment adjusted,

NOTE: Applied Vehicles listed above come from the factory with non-adjustable bolts (Not Cam Bolts) for the lower link (lower control arm) mounting.

ACTIONS

1. Remove the original lower link mounting bolts (cam bolts) and washers - 2 per side.
 - Refer to section **FSU** in the Electronic Service Manual (ESM) for lower link mounting bolt locations.
2. Install the new bolts (cam bolts) and cam washers listed in the Parts Information section of this bulletin.
 - Reuse the nuts you removed from the old bolts.

NOTE: Cam bolts are used to adjust caster and camber.

3. Perform front wheel alignment adjustment per the ESM.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

PARTS INFORMATION

| DESCRIPTION | PART # | QUANTITY |
|------------------------|-------------|----------|
| Cam Bolt | 54580-7S005 | 4 |
| Cam Washer (Eccentric) | 54559-7S005 | 4 |

CLAIMS INFORMATION

Submit a Primary Failed Part (PP) line claim using the following claims coding:

| DESCRIPTION | PFP | OP CODE | SYM | DIA | FRT |
|-------------------|-----|---------|-----|-----|-----|
| Install Cam Bolts | (1) | MX09AA | (2) | 44 | 0.5 |

- (1) Reference the Parts Information Table and use the Cam Bolt P/N as the PFP.
- (2) Reference the current Nissan Warranty Flat Rate Manual and use the symptom code that best matches the vehicle incident.

NOTE: This repair can only be used in conjunction with a claim for Front Wheel Alignment (Op-Code WD44AA) and must be submitted on a separate work order line.

