



SERVICE BULLETIN

Classification: WT08-005	Reference: NTB08-032	Date: March 10, 2008
-----------------------------	-------------------------	-------------------------

TPMS SENSOR SEAL LEAK




APPLIED VEHICLES: All Nissan 2004 – 2008 with TPMS

SERVICE INFORMATION

When repairing an air leak at a TPMS (Tire Pressure Monitor System) sensor seal, a seal is now available separately.

Do not replace the entire sensor when only a seal is needed.

PARTS INFORMATION

TPMS SENSOR PART NUMBER	USE SENSOR SEAL PART NUMBER
40700-CK002 (Gray)	40702-CK002 
40700-CD001 (Blue) 40700-CK001 (Moss green)	40702-CD001 
40700-JA01B (Yellow) 40700-JA00B (Light Green) 40700-JA00C (Orange)	40702-JA01A 

CLAIMS INFORMATION

Reference the current Nissan Warranty Flat Rate Manual for claims coding information.