

# WORK DESCRIPTION FOR FIELD MEASURE

Code: 20P5891201

Version: 2.0

## Enclose printed supplementary booklet, replace if necessary

Mode 205

- i** • Code 085 corresponds to WORLD MANUFACTURER CHANGEOVER TO MERCEDES-BENZ AG

## Work procedure

1. Check for presence of supplementary booklet in vehicle document wallet and check version.  
**i** If supplementary booklet is **not** present, a printed supplementary booklet must be placed in the vehicle document wallet.  
**i** Where present: Compare printed supplementary booklet with the parts table.
2. Enclose printed supplementary booklet, replace if necessary.

## Parts scope – printed supplementary booklet

Quantity	Part no.	Designation	Language	Code
1*	A 205 584 60 25	SUPPL. BOOK. MULTI-LANG 2019-09A	multilingual	085

\* The supplementary booklets must be procured through the usual replacement part ordering channels.

## Operation text and flat rate

Operation no.	Operation text	Flat rate	Accounting no./ damage code
02-9471	Check operator's manual, enclose if necessary	0.1 h	58 912 01

Mercedes-Benz  
Global Service & Parts