

WORK DESCRIPTION FOR FIELD MEASURE

Code: 21P7591001

Version: 2.0

Replace remote trunk closing control unit

Model 223

Work procedure

1. Replace remote trunk closing control unit.

i For basic data, see AR80.20-P-0001S.

Parts

Quantity	Designation	Part no.
1	Remote trunk closing control unit	A 223 900 35 30

i Small parts such as screws/bolts, lock nuts, sealing rings, cable ties, fluids, sealant, etc. are not listed in the parts list. The required small parts are taken into account in the budgeting.

Operation text and flat rate

Operation no.	Operation text	Flat rate	Accounting no./ damage code
02-4762*	Connect/disconnect diagnostic system (XENTRY Diagnosis)	0.1 h	75 910 01
02-5058*	Connect/disconnect starter battery charger (with XENTRY Diagnosis connected)	0.1 h	75 910 01
02-0422	Replace control unit for remote trunk closing	0.6 h	75 910 01

* Operation item may only be invoiced once for each workshop order!

Mercedes-Benz
Global Service & Parts