

	GROUP Body	MODEL All Models
	NUMBER PS290 (REV 1, 12/18/2015)	DATE January 2014
		
SUBJECT: SUCTION CUP RESIDUE ON WINDSHIELD		

Residue from installation of the glass may cause the appearance of circular markings, in the shape of suction cups, to appear on the surface of the glass (example shown below). This condition is more apparent when condensation occurs on the glass and the moisture evaporates at different rates. To correct this condition, spray rubbing alcohol over the affected glass surface. Then, wipe the surface with a cloth. If the markings are still evident, continue spraying rubbing alcohol over the marking(s) and wiping with the cloth until all markings are removed from the surface. **NOTE: do NOT replace any glass surface over this concern.**

