

Introduction Some 2002 and 2003 model year LX 470 vehicles may exhibit a flashing AHC (Active Height Control) "OFF" light with DTC C1743 in AHC ECU memory. A change has been made to the Active Height Control Main Relay to improve relay performance.

Applicable Vehicles 2002 – 2003 model year LX 470 vehicles produced BEFORE the Production Change Effective VIN shown below.

Production	MODEL	PRODUCTION CHANGE EFFECTIVE VIN
Change Information	LX 470	JTJHT00W*33531873

Parts Information	PREVIOUS PART NUMBER CURRENT PART NUMBER		PART NAME	QTY
	90987–02004	89278–60010	Relay, Height Control	1

Required SSTs	SPECIAL SERVICE TOOLS (SSTs)	PART NUMBER	QUANTITY
0013	Lexus Diagnostic Tester Kit*	01001270	1
	12 Megabyte Diagnostic Tester Program Card with version 10.0a Software (or later)*	01002593-005	1

Essential SSTs.

NOTE:

Additional Diagnostic Tester Kits, Program Cards or SSTs may be ordered by calling SPX/OTC at 1-800-933-8335.

Warranty Information	OP CODE	DESCRIPTION	TIME	OFP	T1	T2
	SU3003	Relay, Height Control	0.2	90987–02004	95	54

Applicable Warranty*:

This repair is covered under the Lexus Comprehensive Warranty. This warranty is in effect for 48 months or 50,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint.



Repair Refer to the Technical Information System (TIS) for Active Height Control Main Relay location and diagnostic procedures.

For Active Height Control Main Relay location:

Refer to 2002 or 2003 LX 470 Repair Manual: Diagnostics, Active Height Control Suspension & Adaptive Variable Suspension, Parts Location.

For Active Height Control Main Relay diagnostics:

Refer to 2002 or 2003 LX 470 Repair Manual: Diagnostics, Active Height Control Suspension & Adaptive Variable Suspension, C1743/43 AHC Main Relay.