



SUBARU SERVICE

TECHTIPS NEWSLETTER LOCATOR INDEX  
UPDATED THROUGH MARCH, 2019

***This list is most efficient when searched using CTRL+F***

## TABLE OF CONTENTS

*Click title below to jump to section*

[\*\*01 - General Information\*\*](#)

[\*\*02 - Engine\*\*](#)

[\*\*03 - Drive Train-Transaxle\*\*](#)

[\*\*04 - Steering\*\*](#)

[\*\*05 - Suspension-Wheels & Tires\*\*](#)

[\*\*06 - Brakes\*\*](#)

[\*\*07 - Electrical\*\*](#)

[\*\*08 - Instrument & Controls\*\*](#)

[\*\*09 - Cooling, Fuel, & Exhaust System\*\*](#)

[\*\*10 - Heating Ventilation & A/C Systems\*\*](#)

[\*\*11 - Emission Systems\*\*](#)

[\*\*12 - Body, Glass, & Upholstery\*\*](#)

[\*\*13 - Paint\*\*](#)

[\*\*14 - Special Tools\*\*](#)

[\*\*15 - Accessories\*\*](#)

[\*\*16 - Automatic Transmission\*\*](#)

[\*\*17 - SRS Air Bag\*\*](#)

[\*\*18 - Service Manual Corrections\*\*](#)

## 01-General Information

|   |       |
|---|-------|
| Legacy Knocking Noise, Rear of Vehicle When Driven Over Bumps.....                              | 07/91 |
| Justy Fuel Injection System Service Manual Supplement Section 2-7.....                          | 08/91 |
| In-transit Spark Plug Fouling Protection.....   | 09/91 |
| Kats Wax Transit Coating Remover Precautions.....   | 10/91 |
| Lemon Law Responsibilities.....   | 11/91 |
| PDI Coolant Check - All Models.....   | 11/91 |
| Parts Related Inquiries.....  | 02/92 |
| Legacy and Loyale Normal Operating Characteristics.....   | 04/92 |
| All SPI Models Throttle Body Gasket Replacement.....  | 05/92 |
| Towing a Front Wheel Drive 5-Speed Legacy.....  | 06/92 |
| Location of Engine, Transmission, and Production Date Information.....                          | 11/92 |
| Ordering “D” Check Manuals.....   | 02/93 |
| Odometer Labels.....  | 02/93 |
| Impreza Side Guard Moldings.....  | 03/93 |
| Impreza Key Codes.....  | 05/93 |
| Impreza Side Moldings.....  | 05/93 |
| 1993MY SVX Model Code PKB “LSL”.....  | 06/93 |
| All Models with PDI Connector for Storage.....  | 06/93 |
| Diagnostic Trouble Codes.....   | 07/93 |
| Flat Towing Subaru Vehicles.....  | 08/93 |
| All Models Lock Cylinder Key Coding.....  | 09/93 |
| Warranty Full History Inspection.....   | 09/93 |
| Towing.....   | 10/93 |
| Legacy Front Washer Nozzle Clogged.....   | 10/93 |
| All Models with All Wheel Drive Systems, Use of the Space Saver Spare Tire or T-Spare Tire..... | 11/93 |
| All Models Equipped with Knock Sensors.....   | 11/93 |
| Tool Ordering Procedures.....   | 12/93 |
| October Update Revision - Poor Radio Reception AM or FM.....                                    | 12/93 |
| 1993MY Legacy and Impreza ECU Operation with Select Monitor.....                                | 01/94 |
| Diagnosis of Noises Over the Phone.....   | 02/94 |
| Justy Diagnostics.....  | 03/94 |
| Recall Campaign Announcement – WZG-55.....  | 05/94 |
| Replacement of Ignition Relays.....   | 05/94 |
| Repair Information.....   | 05/94 |
| Requests to Return Parts for Inspection.....  | 05/94 |
| Use of Trouble Code Diagnostic Trees in Service Manuals.....                                    | 05/94 |
| 1994MY Impreza Equipment Changes.....   | 06/94 |
| Legacy, Impreza, and SVX Service Manual Supplements.....  | 06/94 |
| Select Monitor Cartridge-’95MY Impreza.....   | 10/94 |
| 1995MY Legacy Outback Wheel Cover Specifications.....   | 11/94 |
| 1995MY Legacy Service Manual.....   | 12/94 |
| 1995MY Impreza Select Monitor Update.....   | 12/94 |
| Parts Questions.....  | 01/95 |
| Legacy Service Manual Supplement.....   | 01/95 |
| Oil Leaks.....  | 01/95 |
| Obtaining Service Bulletins.....  | 03/95 |
| Diagnosing Noises Over the Phone.....   | 03/95 |
| Helpline Diagnostic Information.....  | 05/95 |
| Physically Damaged Warranty Returned Parts.....   | 05/95 |
| Kats Wax Removal Tips.....  | 06/95 |

## 01-General Information

|   |       |
|---|-------|
| Thinking, the Service Manual, and the use of Diagnostic Flow Charts .....                 | 06/95 |
| Vehicle Model Year .....  | 09/95 |
| 1996MY Subaru Legacy Select Monitor Cartridge .....                                       | 10/95 |
| Select Monitor Information Update .....   | 11/95 |
| Cooler Weather and Drivability .....  | 11/95 |
| Technical Assistance and the CDS 800 Phone Line .....                                     | 12/95 |
| Part Numbers for Electrical Condition Reports and Quality Monitoring Reports .....        | 12/95 |
| Training Test Answers .....   | 01/96 |
| Monroney Label Mismatches .....   | 01/96 |
| Technical Helpline Updates/Service Bulletins .....  | 02/96 |
| Impreza Key Code Location .....   | 02/96 |
| 1995MY & 1996MY Power Antenna Operation .....   | 02/96 |
| Service Bulletin Volume 17/Unlisted Bulletins .....                                       | 04/96 |
| Air Conditioning Reminder .....   | 05/96 |
| Technical Service Helpline Efficiency .....   | 05/96 |
| 1996MY Subaru Legacy VIN Change .....   | 06/96 |
| Location of Engine, Transmission and Production Date Information .....                    | 06/96 |
| Interactive Helpline Updates .....  | 07/96 |
| 1997MY Subaru Legacy-Retrieval of OBD-II Codes without '97 Select Monitor Cartridge ..... | 08/96 |
| Additional 1996MY Subaru Legacy VIN Change Information .....                              | 09/96 |
| "But, Its New....." .....   | 09/96 |
| 1997MY Legacy - Information for You .....   | 09/96 |
| Returning Your Calls .....  | 10/96 |
| Cooler Weather and Driveability .....   | 11/96 |
| Towing Vehicles behind Motor Home .....   | 02/97 |
| Frozen Wiper Blades .....   | 02/97 |
| Technical Helpline Updates/Service Bulletins .....  | 03/97 |
| State I/M 240 Emission Testing and Subaru AWD Vehicles .....                              | 04/97 |
| New Quality Monitoring Report (QMR) Form .....  | 05/97 |
| 1998 Subaru Forester Facts .....  | 07/97 |
| New Subaru Select Monitor .....   | 07/97 |
| 1997MY Subaru Legacy Service Manual Supplement Volume 7 .....                             | 08/97 |
| 1998MY Subaru Forester .....  | 09/97 |
| 1998MY Subaru Key Codes .....   | 09/97 |
| 1998MY Forester Flat Towing .....   | 10/97 |
| Customer Particulars .....  | 10/97 |
| Subaru Forester PDI Connectors .....  | 11/97 |
| Holiday Schedule For 1998 .....   | 01/98 |
| Marking Messages "Urgent" on the Helpline Answering Machine .....                         | 01/98 |
| Parts Collection Cancellation .....   | 01/98 |
| Technical Helpline Update Changes .....   | 02/98 |
| New Name.....Same Dedicated Service .....   | 02/98 |
| Technical Support Line Changes .....  | 02/98 |
| 30th Anniversary/WRC Emblems .....  | 03/98 |
| 1998MY Forester Key Blanks .....  | 03/98 |
| State Emission Testing .....  | 07/98 |
| Subaru AWD Vehicles Are Exempt from Two Wheel Dynamometer Emission Testing .....          | 07/98 |
| Subaru Technical Support Line and Independent Repair Shops .....                          | 07/98 |
| 1999MY... What's New .....  | 08/98 |
| We Need to Know .....   | 08/98 |
| The Support Line and Parts Questions .....  | 08/98 |
| Cooler Weather and Drivability .....  | 10/98 |

## 01-General Information

|   |          |
|---|----------|
| We Get Letters .....  | 01/99    |
| Magnetic Tip Screwdriver Caution.....                                     | 01/99    |
| Interior Trim Tool.....   | 01/99    |
| Other Protection Ideas.....   | 01/99    |
| Dash Noise.....   | 01/99    |
| Technical Service Support Efficiency .....                                | 02/99    |
| Location of Data Information for Engine, Trans., and Production Date..... | 03/99    |
| Quality Monitoring Reports (QMRs) and You .....                           | 03/99    |
| We Get Letters – Continued .....  | 04/99    |
| Parts Replacement.....  | 04/99    |
| Reference Materials .....   | 05/99    |
| Back to Basics – One More Time.....                                       | 05/99    |
| Support Line Case Numbers .....   | 07/99    |
| 2000MY Key Blanks .....   | 07/99    |
| Y2K Subaru Legacy.....  | 08/99    |
| Support Line Answering Machine.....                                       | 10/99    |
| New Area Code .....   | 11/99    |
| Vehicle Servicing.....  | 4/00     |
| Subaru Warranty Coverage Changes for 2001MY .....                         | 05/00    |
| 2001MY Forester Owner’s Manual Correction.....                            | 07/00    |
| Suggested Measuring Device.....   | 07/00    |
| Service Bulletin 12-68-00 .....   | 08/00    |
| Quality Monitoring Reports.....   | 08/00    |
| Required Fluid Use for Warranty Repairs.....                              | 08/00    |
| Cooler Weather and Drivability .....                                      | 10/00    |
| Impreza 2.5RS Modifications.....  | 11/00    |
| Quality Advice Forms for 2001 H6 Outback .....                            | 11/00    |
| Expanded Support Line Hours .....   | 01/01    |
| Parts Collection Center – Additional Location .....                       | 01/01    |
| AYES Program Participation.....   | 02/01    |
| Towing Vehicles behind Motor Homes .....                                  | 02/01    |
| Service Publications New 1-800 Number.....                                | 02/01    |
| Bulk Fluid Usage .....  | 02/01    |
| Ordering Technician Patches .....   | 03/01    |
| Answering Machine Reminder.....   | 03/01    |
| Key Codes – A Reminder .....  | 05/01    |
| 2002MY Impreza Sedan Valet Key Function.....                              | 09/01    |
| Service Manual Applicability .....  | 11/01    |
| Special Edition: 2003 Forester Accessory Installation.....                | 07/02    |
| Contacting the Technical Support Line.....                                | 09-10/02 |
| Information Requests .....  | 09-10/02 |
| 2003 Baja Owners Manual Supplement.....                                   | 03/03    |
| www.Subarunet.com Reminder.....   | 03/03    |
| Faded or Ghosted Fluke Original 80 Series Display.....                    | 04/03    |
| Modifications to Vehicles .....   | 07/03    |
| Electronic QMR .....  | 07/03    |
| SOA Publication MSA5B0403A.....   | 08/03    |
| Clamp-on Racks and Wind Noise .....                                       | 01/04    |
| Calling the Technical Support Line.....                                   | 03/04    |
| Service Manual Correction Labels .....                                    | 05/04    |
| 2005MY Legacy/Outback: Updated PDI Check Items and Notes .....            | 07/04    |
| Product Improvements .....  | 08/04    |

## 01-General Information

|   |       |
|---|-------|
| Subarunet and Service Technicians .....                                 | 10/04 |
| Updated Reprogramming Information .....                                 | 11/04 |
| Cold Weather and Drivability .....                                      | 11/04 |
| Enhanced EQMR.....  | 11/04 |
| Premium Ownership Delivery .....  | 12/04 |
| Technical Service Bulletins: A Recent List .....                        | 03/05 |
| Technical Service Bulletins: A Recent List .....                        | 04/05 |
| Tips from the Techs .....   | 04/05 |
| Technical Service Bulletins/Programs .....                              | 05/05 |
| Technical Service Bulletins, TechTIPS, and Other Publications .....     | 06/05 |
| 2006MY Mechanism and Function Service Manual .....                      | 06/05 |
| Recently Published Service Bulletins .....                              | 06/05 |
| Latest Service Bulletins Released .....                                 | 07/05 |
| STi – Towing Behind Motor Homes .....                                   | 07/05 |
| Latest Service Bulletins Released .....                                 | 08/05 |
| Subaru Warranty Wizard Update.....                                      | 09/05 |
| TechLine Pre-Call Worksheets .....                                      | 09/05 |
| Latest Service Bulletins Released .....                                 | 09/05 |
| Latest Service Bulletins Released .....                                 | 10/05 |
| In Case You Forgot.....   | 10/05 |
| Contacting the Technical Support Line.....                              | 11/05 |
| Come On Guys.....   | 11/05 |
| Latest Service Bulletins Released .....                                 | 11/05 |
| 2006MY Impreza Indicator Lights.....                                    | 11/05 |
| Technical HelpLine Efficiency.....                                      | 11/05 |
| Latest Service Bulletins Released .....                                 | 12/05 |
| Calling the TechLine...."Can You Hear Me Now?" .....                    | 12/05 |
| Latest Service Bulletins Released .....                                 | 01/06 |
| Latest Service Bulletins Released .....                                 | 03/06 |
| FYI – Replacement of the Neutral Switch on a 6MT Vehicle.....           | 03/06 |
| Service Information Availability on STIS.....                           | 06/06 |
| Techline Closing .....  | 06/06 |
| Techline Pre-Call Worksheets .....                                      | 06/06 |
| Immobilizer Codes & the Techline .....                                  | 06/06 |
| Vehicle Repair Escalation Process.....                                  | 06/06 |
| Calling the Techline.... Can You Hear Me Now???                         | 07/06 |
| 2007 Subaru B9 Tribeca Introduction TRB.....                            | 08/06 |
| Quickie "FYI" TIPS .....  | 08/06 |
| Latest SOA Service Documents Released.....                              | 08/06 |
| Latest SOA Service Documents Released.....                              | 09/06 |
| Subaru Chemical Information .....                                       | 10/06 |
| Cold Weather- Here We Go Again!.....                                    | 10/06 |
| Latest SOA Service Documents Released.....                              | 10/06 |
| Rear Differential Oil .....   | 11/06 |
| Quick Tip: "No Start" Complaint .....                                   | 11/06 |
| Power Steering Fluid Usage .....  | 11/06 |
| New Tech TIPS Editor: Don Bangs.....                                    | 12/06 |
| Quick TIP: Nox Rust .....   | 12/06 |
| Clarification of the "Valet Key" and "Master Key" Immobilizer Type..... | 12/06 |
| Automatic Transmission Fluid for All 5EAT and 4EAT Transmissions .....  | 12/06 |
| New Techline Representative .....                                       | 01/07 |
| A "Back To Basics" Reminder .....                                       | 01/07 |

## 01-General Information

|   |          |
|---|----------|
| Quick TIPS: Important Items to Note .....   | 02/07    |
| From The “Clarifications Department” .....  | 03/07    |
| Quick TIP – Forester Spare Tire Cover .....   | 03/07    |
| Techline Survey Results .....   | 04/07    |
| Gear Oil Specification Differences .....  | 06/07    |
| 2007 U.S. National Technician Competition .....   | 07/07    |
| Latest Service Bulletins Released .....   | 07/07    |
| SSM III, Reprogramming & You.....   | 08/07    |
| New 2008 M/Y Service Manuals on STIS .....  | 11&12/07 |
| U.S National and World Technician Troubleshooting Competitions.....                     | 12/07    |
| H-6 Engine Smoke from Exhaust on Start-Up.....  | 08/08    |
| Sending SSM-III Files.....  | 08/08    |
| Oil Filter Wrenches .....   | 12/08    |
| Calling the Techline: A Reminder about Cell Phones .....                                | 12/08    |
| Cold Weather Reminders .....  | 12/08    |
| Incentive Program for Technician TIPS Suggestions .....                                 | 01/09    |
| 2009 M/Y Forester & Impreza Protective Wheel Film .....                                 | 01/09    |
| 2010 M/Y Legacy / Outback Preliminary Information .....                                 | 05/09    |
| Use of Synthetic / Semi-Synthetic Engine Oils.....                                      | 05/09    |
| 2008-09 M/Y Impreza, Dim Headlights and / or Erratic Outside Temperature Display .....  | 06/09    |
| Help Us to Help You .....   | 07/09    |
| 2010 M/Y Legacy & Outback Reporting Requirements.....                                   | 07/09    |
| Subarunet & Subaru “SMART” System Login Information .....                               | 09/09    |
| Cell Phones, Air Tools & the Techline.....  | 09/09    |
| SSMIII Error Codes .....  | 11/09    |
| EQMR Authorization Requests... A Reminder .....   | 01/10    |
| First Annual Subaru / ASE Master Automotive Technician of the Year .....                | 02/10    |
| Techline Case Follow-Up and Call-In Tips.....   | 04/10    |
| EQMR’s and Photos .....   | 05/10    |
| Subaru / ASE Master Automobile Technician of the Year – 2010.....                       | 09/10    |
| 2nd Annual Subaru / ASE Master Automobile Technician of the Year Awards Announced ..... | 10/10    |
| New 2011 MY Forester Quality Reporting Information .....                                | 11/10    |
| 2011 Factory-Fill Synthetic Oil and Maintenance Information.....                        | 11/10    |
| Does Your Service Department Have A “What’s New” Bulletin Board? .....                  | 02/11    |
| Troubleshooting Guides - A Reminder .....   | 04/11    |
| “D-Check” Connector Locations.....  | 05/11    |
| Revised Service Bulletins.....  | 06/11    |
| Calling the Techline – Questions You Should Be Ready For.....                           | 07/11    |
| Use of Silicone Spray Precautions .....   | 07/11    |
| 2012 Impreza PDI Fuse Procedure.....  | 09/11    |
| Is This Clip Important? .....   | 10/11    |
| Change to Oil Fill Cap of FB Engine.....  | 11/11    |
| 2012 M/Y Oil Change Interval Information.....   | 11/11    |
| Turning Off Blinking “Check Engine” light on 2012 MY Vehicles .....                     | 12/11    |
| Valve Clearance Checking Procedures, A Reminder .....                                   | 01/12    |
| Yes, Another Sales Record Year for Subaru.....  | 02/12    |
| Techline Case Follow-Up.....  | 02/12    |
| Special Automatic Transmission Fluid for the New BRZ .....                              | 05/12    |
| Calibration Identification Numbers.....   | 05/12    |
| Techline Staffing changes .....   | 06/12    |
| 2013 BRZ PDI Procedure Information .....  | 06/12    |
| 2013 Legacy, Outback and BRZ Launch-Your Help Is Needed.....                            | 07/12    |

## 01-General Information

|  |       |
|--|-------|
| Techline Staffing Changes.....   | 09/12 |
| Subaru ASE Master Tech Of The Year 2012 .....                                | 11/12 |
| Addition To PDI Procedure For Impreza And Crosstrek .....                    | 12/12 |
| Additional Tie Down Plug for 12-13 Impreza Models .....                      | 01/13 |
| Thanks to You.....   | 02/13 |
| QMR Of The Month .....   | 02/13 |
| QMR Of The Month Winner.....   | 03/13 |
| New Model Launch Activities .....  | 03/13 |
| Information You Should Always Have When Calling Tech Line.....               | 04/13 |
| QMR Of The Month Winner.....   | 04/13 |
| QMR Of The Month Winner.....   | 05/13 |
| Recommended Materials Update .....   | 05/13 |
| QMR Of The Month Winner.....   | 06/13 |
| Authorization Requests .....   | 06/13 |
| 2013 National Technician Competition .....                                   | 08/13 |
| QMR of the Month .....   | 08/13 |
| Quality Monitoring Reports.....  | 08/13 |
| QMR of the Month .....   | 09/13 |
| Subaru-ASE Master Auto Technician of the year .....                          | 09/13 |
| Towing Subaru Vehicles-Revisited .....                                       | 09/13 |
| QMR of the Month .....   | 10/13 |
| New Tech line Fax Number and Pre-Call Worksheets .....                       | 10/13 |
| Friday November 29th 2013-Tech line open .....                               | 10/13 |
| Clarification on Towing.....   | 10/13 |
| QMR of the Month .....   | 11/13 |
| Don't Forget to check the basics when diagnosing Drivability Complaints..... | 11/13 |
| Troubleshooting Guides on STIS-Reminder.....                                 | 11/13 |
| BUI replacement and Key's .....  | 11/13 |
| QMR of the Month .....   | 12/13 |
| Fourth Bi-Annual Subaru international tech competition awards.....           | 12/13 |
| Subaru/ASE Master Tech of the Year .....                                     | 12/13 |
| 2014 XV-Crosstrek Hybrid Launch-Your Help Is needed.....                     | 12/13 |
| New Tech line hours of operation .....                                       | 12/13 |
| QMR of the Month .....   | 01/14 |
| 14Crosstrek Hybrid Launch Reminder.....                                      | 01/14 |
| QMR of the Month .....   | 02/14 |
| Authorization Request (AR) for Paint and Glass over 500.....                 | 02/14 |
| 2014 Hybrid Launch-Your Help is Needed.....                                  | 02/14 |
| QMR of the Month .....   | 03/14 |
| Tech line new hours of Operation.....  | 03/14 |
| 2015 WRX and WRX STI Launch-Your help is Needed .....                        | 03/14 |
| QMR of the Month .....   | 04/14 |
| New Tech line Pre-Call Worksheets .....                                      | 04/14 |
| Tech line Case Follow up-Revisited.....                                      | 04/14 |
| Authorization Request Pictures .....   | 04/14 |
| QMR of the Month .....   | 05/14 |
| Tech line case follow up-Revisited .....                                     | 05/14 |
| QMR of the Month .....   | 06/14 |
| 15MY Legacy and Outback Transit Fuse Information.....                        | 06/14 |
| QMR of the Month .....   | 07/14 |
| 2015 Legacy and Outback Launch Team Activity-Your Help is Needed.....        | 07/14 |
| New Subaru Oil Change Reference Cards.....                                   | 07/14 |

## 01-General Information

|   |       |
|---|-------|
| 2015 Legacy and Outback Fujitsu 10 Audio and Audio/Navigation Systems.....  | 07/14 |
| QMR of the Month .....  | 08/14 |
| Change to Spare Tire Retaining Bolt.....                                    | 08/14 |
| QMR of the Month .....  | 09/14 |
| Locating Flash write Reprogramming Files for 2015 WRX Models .....          | 09/14 |
| Calling the Tech line for Assistance.....                                   | 09/14 |
| QMR of the Month .....  | 10/14 |
| 5th Annual Subaru Technician Competition .....                              | 10/14 |
| QMR of the Month .....  | 11/14 |
| Interior Rear View Mirror Separation .....                                  | 11/14 |
| QMR of the Month .....  | 12/14 |
| Subaru of America’s ASE Master Tech of the Year .....                       | 12/14 |
| QMR of the Month .....  | 01/15 |
| Escalation Process What, Why, and How.....                                  | 01/15 |
| QMR Reporting, Do’s and Don’ts .....  | 01/15 |
| No Crank Condition on Push-Button Start-Equipped Model’s.....               | 01/15 |
| Techline Case Follow Up .....   | 01/15 |
| QMR of the Month .....  | 02/15 |
| Reminder: Sending Saved Freeze Frame (FFD) and SSM Data Files .....         | 02/15 |
| New Product Announcement (SOA868V9175) Silicone Gasket Remover.....         | 02/15 |
| Exciting Update to the “QMR of the Month” Award Program.....                | 02/15 |
| QMR of the Month .....  | 03/15 |
| Techline Phone System “Courtesy Call Back Feature”.....                     | 03/15 |
| QMR of the Month .....  | 04/15 |
| QMR of the Month Award Presentation .....                                   | 04/15 |
| Calling the Tech line Revisited.....  | 04/15 |
| QMR of the Month .....  | 05/15 |
| New Required Detail Fields Established for Claims Submission.....           | 05/15 |
| Explanation of New Required Fields in Quality Monitoring Report (QMR) ..... | 05/15 |
| QMR of the Month Award Presentation .....                                   | 05/15 |
| QMR of the Month .....  | 06/15 |
| Authorization Requests/Better Pictures Requested .....                      | 06/15 |
| Combination Meter and BIU shipments to SOA .....                            | 06/15 |
| QMR of the Month .....  | 07/15 |
| QMR of the Month Award Presentation .....                                   | 07/15 |
| Subaru Oil Consumption .....  | 07/15 |
| QMR of the Month .....  | 08/15 |
| Technician Submission of the Month.....                                     | 08/15 |
| EyeSight Charts.....  | 08/15 |
| 2016 Forester Service Manual-The next Generation .....                      | 08/15 |
| QMR of the Month .....  | 09/15 |
| QMR of the Month Award Presentation .....                                   | 09/15 |
| CPO procedure for turbocharged Subaru vehicles.....                         | 09/15 |
| Understanding DTC’s and how to proceed properly with repairs .....          | 09/15 |
| QMR of the Month .....  | 10/15 |
| QMR of the Month Award Presentation .....                                   | 10/15 |
| Remanufactured Transmission Replacements .....                              | 10/15 |
| 2015 Technician ASCENT Program-Important Enhancements .....                 | 10/15 |
| QMR of the Month .....  | 11/15 |
| QMR of the Month Award Presentation .....                                   | 11/15 |
| QMR of the Month .....  | 12/15 |
| QMR of the Month Award Presentation .....                                   | 12/15 |



## 01-General Information

|  |       |
|--|-------|
| Subaru World Technician Competition .....                          | 12/15 |
| Subaru Technical Training-Gaming Survey .....                      | 12/15 |
| QMR of the Month .....   | 01/16 |
| QMR of the Month Award Presentation .....                          | 01/16 |
| Pre-cut Keys .....   | 01/16 |
| 2016 Technical Training Curriculum Planning Workshops .....        | 01/16 |
| Fujitsu (F-10) Map Information .....                               | 01/16 |
| Towing Subaru Vehicles .....                                       | 01/16 |
| The New and Improved QMR of the Month Program .....                | 01/16 |
| QMR of the Month .....   | 02/16 |
| QMR of the Month Award Presentation .....                          | 02/16 |
| QMR of the Month .....   | 03/16 |
| QMR of the Month Award Presentation .....                          | 03/16 |
| QMR of the Month .....   | 04/16 |
| QMR of the Month Award Presentation .....                          | 04/16 |
| Subaru-U Announcement .....  | 04/16 |
| Saving and Printing Freeze Frame Data .....                        | 04/16 |
| Changes to Subaru-Net Links .....                                  | 04/16 |
| QMR of the Month .....   | 05/16 |
| QMR of the Month Award Presentation .....                          | 05/16 |
| American National Technician Competition .....                     | 05/16 |
| Subaru-U .....   | 05/16 |
| Stickers on the Windshield .....                                   | 05/16 |
| QMR of the Month .....   | 06/16 |
| QMR of the Month Award Presentation .....                          | 06/16 |
| Subaru-U .....   | 06/16 |
| New STIS User's .....  | 12/16 |
| Subaru-U .....   | 01/17 |
| QMR of the Month .....   | 01/17 |
| QMR of the Month Award Presentation .....                          | 01/17 |
| Subaru-U .....   | 02/17 |
| QMR of the Month .....   | 02/17 |
| QMR of the Month Award Presentation .....                          | 02/17 |
| Update to STIS .....   | 02/17 |
| QMR of the Month .....   | 03/17 |
| Subaru-U .....   | 03/17 |
| QMR of the Month .....   | 04/17 |
| QMR of the Month Award Presentation .....                          | 04/17 |
| Subaru-U .....   | 04/17 |
| Locating Tech Tips .....   | 04/17 |
| CPO Procedure for Turbocharged Subaru Vehicles .....               | 04/17 |
| Technicians: What Is Your Role in Product Quality? .....           | 04/17 |
| Lost keys? Contact the Subaru Techline .....                       | 05/17 |
| Application chart for Immobilizer .....                            | 06/17 |
| DCM and ECM swapping .....   | 08/17 |
| Authorization Requests .....                                       | 08/17 |
| CPO Procedure .....  | 08/17 |
| Calling the Techline Revisited .....                               | 08/17 |
| Lost Keys? + Immobilizer Chart .....                               | 09/17 |
| Understanding DTC's and How to Proceed Properly with Repairs ..... | 09/17 |
| Requesting Techline callback's .....                               | 09/17 |
| The Subaru Parts Collection Center .....                           | 09/17 |

## 01-General Information

|  |       |
|--|-------|
| The Key to the Highway.....  | 11/17 |
| Following the Service Manual for Repairs.....  | 11/17 |
| WQK-47 Equipment Cleaning Procedure.....   | 11/17 |
| Authorization Requests (AR) for Paint and Glass Over \$500.....                            | 12/17 |
| CPO Procedure for Turbocharged Subaru Vehicles.....  | 12/17 |
| Calling TechLine Revisited.....  | 12/17 |
| QMR of the Month Program Enhancement.....  | 01/18 |
| Reviewing Data Files.....  | 01/18 |
| Calling the TechLine Revisited.....  | 02/18 |
| Locating TechTIPS.....   | 02/18 |
| Understanding Power Supply.....  | 02/18 |
| Body Plug Relocation.....  | 02/18 |
| Calling Subaru TechLine.....   | 04/18 |
| Icy Road Warning Indicator Operation.....  | 04/18 |
| Clearing Trouble Codes.....  | 05/18 |
| Subaru Diagnostics.....  | 05/18 |
| 2019MY Ascent Owner’s Manual Utilization.....  | 05/18 |
| Understanding Readiness Codes.....   | 06/18 |
| Why Was That Part Replaced?.....   | 06/18 |
| System Owner Manuals.....  | 07/18 |
| Understanding DTCs and How to Proceed Properly with Repairs.....                           | 07/18 |
| Stickers on the Windshield.....  | 09/18 |
| Authorization Requests (AR) for Paint and Glass over \$500.....                            | 09/18 |
| QMR of the Month.....  | 10/18 |
| 2019MY Forester Quality Monitoring Team New Model Launch.....                              | 10/18 |
| 2019MY Forester: Auto Start-Stop and Driver Monitor System Diagnostic Information.....     | 10/18 |
| The Importance of Searching for TSBs and TechTips.....                                     | 12/18 |
| QMR of the Month.....  | 01/19 |
| Subaru Technicians Honored at ASE Annual Meeting.....                                      | 01/19 |
| TechLine Case Follow Up.....   | 01/19 |
| The Radio Keeps Playing and a “Turn Engine Off Before Exiting” Message Appears – Why?..... | 01/19 |
| QMR of the Month.....  | 02/19 |
| 2019 National Training Competition.....  | 02/19 |
| QMR of the Month – Trip Winner AnnouncementSE 02/19  |       |
| QMR of the Month.....  | 03/19 |
| 7th Annual National Technician Competition ConclusionSE.....                               | 03/19 |
| QMR of the Month – Trip Winner AnnouncementSE.....   | 03/19 |

### 02-Engine

|  |       |
|--|-------|
| 1.8 Engine Head Gasket Torque Change/Oil Leakage .....                         | 05/91 |
| Legacy Throttle Sensor Switch Adjustment.....                                  | 08/91 |
| Noisy Lash Adjusters .....   | 09/91 |
| Legacy Exhaust Valves .....  | 09/91 |
| Legacy Cylinder Head Resurfacing (Grinding) Specifications Clarification ..... | 10/91 |
| Justy Cylinder Head Installation and Retorquing Clarification.....             | 11/91 |
| Legacy Turbo Models - Oil In the Coolant .....                                 | 08/92 |
| Oil Leaks.....   | 09/92 |
| Correction to Legacy Turbo Oil Leaks in the September Update .....             | 10/92 |
| Justy Balancer Chain Replacement .....   | 11/92 |
| 1991MY-‘1992MY Legacy Turbo and All ‘92MY N.A. M/T “High Idle Complaint” ..... | 12/92 |
| 1992MY Legacy Turbo Stalls After Start-Up Hot or Cold.....                     | 12/92 |
| 1992MY SVX Trouble Code 56, EGR System .....                                   | 12/92 |
| Loyale “Engine Ping” Complaint SPI .....                                       | 01/93 |
| 1992MY SVX Auxiliary Air Valve Disconnection.....                              | 04/93 |
| All Justy Models Drivability Complaints.....                                   | 08/93 |
| Justy with Multiple Failure Codes Including Code 41 in ECU Memory.....         | 09/93 |
| L-Series/Loyale 1.8 Liter OHC Valve Servicing.....                             | 09/93 |
| Correction to All Justy Models Drivability Complaints, August Update .....     | 10/93 |
| 1993MY Legacy Models, Electronic Control Unit “Rom” Installation .....         | 10/93 |
| Replacement Engine Oil Filters .....   | 12/93 |
| Loyale and Legacy HLA Noise .....  | 04/94 |
| 1995MY Legacy Spark Plugs .....  | 10/94 |
| Synthetic Lubricant Usage.....   | 10/94 |
| Idle Quality Complaints On ‘95MY Legacy.....                                   | 02/95 |
| Synthetic Engine Oil .....   | 02/95 |
| Engine Testing-Back to Basics.....   | 04/95 |
| Synthetic Lubricant Usage - Updated Information.....                           | 07/95 |
| Oil Viscosity Change for 1996MY Subaru Vehicles.....                           | 10/95 |
| 2.5 Liter Motor Engine Knocking or Tapping Noise .....                         | 01/96 |
| 1997MY Engine Noise .....  | 09/96 |
| Legacy 2.2L and Impreza 1.8L, 2.2L Engine Oil Filling .....                    | 09/96 |
| Welcome To Shim City .....   | 10/96 |
| New Cambelt Tensioner .....  | 04/97 |
| Assembling 1997MY and Newer Engines.....                                       | 08/97 |
| Molybdenum Coating On Pistons.....   | 10/97 |
| Engine Noise .....   | 11/97 |
| 2.5L Engine Cylinder Head Bolt Tightening Sequence .....                       | 11/97 |
| Legacy Engine Belt Guides .....  | 05/98 |
| 1996MY 2.5L Exhaust Valves.....  | 09/98 |
| 2.2L Front Crankshaft Oil Seals .....  | 10/98 |
| 1999MY Legacy Short Blocks .....   | 11/98 |
| Leaking Front Crankshaft Oil Seals.....  | 01/99 |
| SIA Installed Engine Oil.....  | 03/99 |
| 2000MY Spark Plug Application Chart (revised 01-31-00) .....                   | 04/00 |
| Engine Noise when Cold .....   | 08/00 |
| Oil Pumps – Replacement vs. Resealing .....                                    | 01/01 |
| 3.0L 6 Cylinder Valve Train Servicing.....                                     | 02/01 |
| Subject: Engine Noise when Cold .....  | 02/01 |
| Three Bond 1280B .....   | 05/01 |

## 02-Engine

|   |          |
|---|----------|
| 2002MY WRX Turbo Cool Down Procedure .....  | 06/01    |
| Oil filters: H-4 versus H-6 Engines .....   | 03-04/02 |
| 2.0L Camshaft Cap Torque Correction.....  | 08/02    |
| DOHC Turbo Valve Specification.....   | 09-10/02 |
| Subject: Engine Noise when Cold .....   | 01-02/03 |
| Radiator Hose Leakage .....   | 01-02/03 |
| SOA Replacement Ignition Wire Set.....  | 01-02/03 |
| Coolant Seepage from Water Pump.....  | 05/03    |
| 2004 Baja and Forester Turbo Engine Oil Filters.....                                    | 05/03    |
| Cam Belt Tensioner Replacement.....   | 07/03    |
| Vehicle Re-engineering/modifying.....   | 07/03    |
| All Turbo Model Oil Filters .....   | 07/03    |
| Head Gasket Repairs .....   | 11/03    |
| Oil Filter Application Clarification.....   | 11/03    |
| Engine Noise – All H6 Vehicles .....  | 01/04    |
| H6 Cylinder Head Bolt Torqueing Procedures.....   | 02/04    |
| Cylinder Bore Size Location Information .....   | 03/04    |
| Cruise Control Cable Retainer Clip: WWQ-01.....   | 04/04    |
| Pressure Washing of Vehicle Engine Compartment – All Models.....                        | 08/04    |
| Intercooler Spray Tank.....   | 03/05    |
| Oil Classification Change for 2006MY Vehicles .....                                     | 07/05    |
| Shortblocks Replaced Under Warranty .....   | 08/05    |
| P/N 11063AB120: LH Cylinder Head Assembly.....  | 09/05    |
| Engine Testing – Back to the Basics .....   | 10/05    |
| Safe Handling of Sodium Filled Valves.....  | 10/05    |
| Coolant Seepage from Water Pumps.....   | 10/05    |
| Remanufactured SOHC Shortblocks and Bulletin 02-96-05 .....                             | 11/05    |
| Bank1, Bank 2 .....   | 01/06    |
| Valve Stem Oil Seals .....  | 02/06    |
| Rubbing Mark on Timing Belt .....   | 02/06    |
| Platinum Spark Plug Change Intervals.....   | 04/06    |
| Turbo Failures.....   | 05/06    |
| H6 Oil Level Explained .....  | 06/06    |
| Basics, Basics, Basics.....   | 06/06    |
| Turbocharger Oil Supply Filter.....   | 03/07    |
| Engine Oil Specification Information.....   | 05/07    |
| 3.6L H-6 Oil Filter Wrench Information .....  | 07/07    |
| Cranks Over But Won't Start? .....  | 10/07    |
| 2008 M/Y 3.6L Engine Oil Dipstick.....  | 11/07    |
| Tribeca Oil Cooler Line Clamps.....   | 11/07    |
| Revised Turbocharger Oil Supply Piping.....   | 01/08    |
| Subaru Valve Adjustment Information .....   | 02/08    |
| More Valve Adjustment Information.....  | 04/08    |
| Engine Oil Pan Drain Plug Gaskets: NOT All the Same! .....                              | 05/08    |
| Don't Forget To Check Those Banjo Bolt Filters.....                                     | 07/08    |
| WWM-96 Rear Suspension Sub-Frame Corrosion Campaign.....                                | 11/08    |
| Bank-Specific Misfires & Active Valve Control System (Variable Valve Timing- VVT) ..... | 01/09    |
| Oil Filter Replacement Precautions .....  | 02/09    |
| Important Short / Long-Block Replacement Reminder.....                                  | 03/09    |
| P0171, Rough Running Condition after Cold Start .....                                   | 04/09    |
| Turbocharged Engines: Oil Supply Reminder .....   | 08/09    |
| 2010 M/Y Legacy & Outback 3.6L Engine Cover Removal .....                               | 10/09    |

## 02-Engine

|  |       |
|--|-------|
| Engine Oil Leaks – A Reminder .....  | 05/10 |
| Valve Adjustment and Clearance Measurement the Right Way .....             | 06/10 |
| 4-Cylinder Crankshaft Oil Seal Replacement Procedures .....                | 07/10 |
| Don't Forget to Check the EGR Valve .....                                  | 12/10 |
| DTC P0128 Information .....  | 12/10 |
| 2011 M/Y Forester N/A Revised Oil Filler Cap.....                          | 02/11 |
| Leaking Engine Oil Seals? Don't Forget to Check the PCV! .....             | 02/11 |
| Fluid Leak Detection Made Easier.....                                      | 04/11 |
| Revised Cylinder Head Gasket Diagnostic Procedure .....                    | 05/11 |
| 2010 M/Y and Newer Oil Pan Damage.....                                     | 06/11 |
| 2011 M/Y Forester (FB Engine) Cam Position Sensor Information.....         | 06/11 |
| 2010 M/Y and Later Impreza WRX and STI Turbo Charger and Stay Bracket..... | 06/11 |
| FB25/20 Engine Crankshaft Sensor Reluctor Indexing .....                   | 10/11 |
| Excessive Noise from the Engine Under Boost.....                           | 02/12 |
| 2010 and Later Legacy and Outback 3.6 Engine Cover Removal .....           | 05/12 |
| 2007 to 2009 Cylinder Head Identification.....                             | 06/12 |
| BZR Fuel Injection Operational Characteristics.....                        | 06/12 |
| Turbo Charges And Piping.....  | 08/12 |
| Front Chain Cover Oil Leaks .....  | 12/12 |
| Too Much Oil in the Engine .....   | 03/13 |
| Understanding The Relationship Between Cam Crank Position Sensors .....    | 04/13 |
| 2013 Legacy/Outback Spec Change to Engine Under Cover.....                 | 04/13 |
| 2012 WRX and STI Motor Mounts .....  | 05/13 |
| Remanufactured Short Blocks.....   | 05/13 |
| 2.0 and 2.5 FA/FB Chain Driven Engine Timing Information .....             | 09/13 |
| Engine oil expansion, Fact or Fiction.....                                 | 12/13 |
| FA and FB Engine Connecting Rod Bolt Removal Tip .....                     | 02/14 |
| FA and FB Engine Timing Chain Tensioner Initial Setting Information .....  | 03/14 |
| Piston Ring Installation TIPS .....  | 03/14 |
| Discoloration of Cylinder Walls.....                                       | 04/14 |
| Too Much Oil In The Engine Revisited .....                                 | 06/14 |
| Hard Starting, Extended Engine Cranking Concerns Revisited .....           | 12/14 |
| FA and FB Engine Crank Sprocket Timing Mark Important Reminder .....       | 04/15 |
| 2015-16 MY WRX Engine Cover Removal Precaution .....                       | 09/15 |
| Cam Sprocket Replacement for P000A-P000D A Reminder .....                  | 10/15 |
| Addressing Accessory Drive Belt Noise .....                                | 02/16 |
| Timing Chain Cover Installation.....                                       | 04/16 |
| Smoke from Exhaust on DIT Turbo vehicles .....                             | 12/17 |
| Allowable Repairs to CVT Assemblies .....                                  | 03/18 |
| Engine Oil Pressure Specification Discrepancies.....                       | 07/18 |
| Fluid Leak Detection Made Easier.....                                      | 11/18 |

## 03-Drive Train-Transaxle

### 03-Drive Train-Transaxle

|   |          |
|---|----------|
| Shifter-Rattle "L" Series 4WD M/T and XT FWD or 4WD M/T .....               | 07/91    |
| Legacy Rear Diff.....   | 08/91    |
| Manual Transmission Gear Oil .....  | 01/92    |
| L-Series and XT Models With Stepped Flywheels .....                         | 04/92    |
| All Subaru Models Rear Differential Assembly Replacement.....               | 05/92    |
| Legacy/SVX Limited-Slip Rear Differential .....                             | 06/92    |
| 1992MY Loyale Shifter Rattle On 4WD 5-Speed Models .....                    | 08/92    |
| All Four-Wheel Drive Vehicles .....   | 11/92    |
| All Subaru Models Wheel Bearing Replacement.....                            | 06/93    |
| Legacy Axle Repairs .....   | 07/93    |
| Justy Drive Axle Installation .....   | 09/93    |
| Diagnosing 3SP Automatic Transmissions Starting In Second Gear .....        | 11/93    |
| Justy ECVT Transmissions That Won't Up-Ratio After Rebuild .....            | 11/93    |
| Rear Differential Replacement .....   | 12/93    |
| 3 Speed Automatic Clutch Drum Wear.....                                     | 01/94    |
| Manual Shift Lock Release on '94MY SVX .....                                | 02/94    |
| 3-Speed Automatic Differential Rebuilding.....                              | 05/94    |
| Replacing AWD Rear Wheel Bearings on Legacy, Impreza, and SVX.....          | 04/95    |
| Inspection of Clutch Free Play During PDI .....                             | 07/95    |
| Automatic Impreza Rear Differentials .....                                  | 05/96    |
| Outback Gear Ratios .....   | 05/96    |
| Where's The Hill Holder?.....   | 10/96    |
| Inspection of Clutch Free Play During PDI .....                             | 11/96    |
| Noise from Rear Axle Oil Seal-Legacy Models .....                           | 01/97    |
| '97MY Legacy Rear Differential Crossmember Bracket Noise & Vibration .....  | 01/97    |
| Rear Differential Modifications.....  | 04/97    |
| All Subaru Models with Stepped & Flat Flywheels .....                       | 07/97    |
| Additional Parts Information on Differential Modifications .....            | 07/97    |
| Identifying 1997 Subaru Legacy Propeller Shafts.....                        | 07/97    |
| 1997MY Legacy Rear Differential Crossmember Bracket Noise & Vibration ..... | 10/97    |
| Grease Leaking From Inner Axle Joints .....                                 | 02/98    |
| Rear Differential Vent Oil Leakage .....                                    | 04/98    |
| Legacy Engine Belt Guides .....   | 05/98    |
| 1998MY Vehicles Leaking Axle Grease .....                                   | 09/98    |
| M/T Case Boss Wear .....  | 09/98    |
| 5MT Popping Out Of First Gear.....  | 10/98    |
| Shifter Rattle.....   | 02/99    |
| All 1999MY Manual Transmission Vehicle.....                                 | 03/99    |
| Transmission/Rear Differential Gear Ratios .....                            | 06/99    |
| Popping Out Of Fifth Gear.....  | 01/00    |
| 1999/2000MY Manual Transmissions Popping Out Of 1st Gear .....              | 04/00    |
| 2001MY Outback H6-3.0 VDC Precautions.....                                  | 11/00    |
| Variable Torque Distribution .....  | 05/01    |
| All Subaru Rear Differentials .....   | 10/01    |
| Use of Correct Fluids.....  | 08/02    |
| Parts Supersession 2002MY Outback & Impreza 1st Driven Gear .....           | 09-10/02 |
| Transmission Popping Out of 3rd Gear .....                                  | 05/03    |
| On The Car Rear Wheel Bearing Replacement Procedure.....                    | 09/03    |
| Impreza WRX Driveability.....   | 04/04    |
| 2005MY Manual Transmission Speedometer Gears.....                           | 06/05    |

## 03-Drive Train-Transaxle

|   |       |
|---|-------|
| STi Rear Differential Oil.....  | 07/05 |
| Impreza STI Characteristics .....   | 01/06 |
| Clutch Pedal Squeak .....   | 05/06 |
| Manual Transmission Center Differential Damage .....  | 10/06 |
| STI / DCCD “Klunking Noise” .....   | 02/08 |
| 6 M/T “Quick TIPS” .....  | 03/08 |
| DTC P1720, DCCD Code in Memory, 2008 STI .....  | 09/08 |
| Squeaking Noise When Operating the Clutch Pedal.....  | 02/09 |
| 2010 M/Y Legacy & Outback Sound at Initial Start-Up.....                                    | 08/09 |
| Tribeca Rear Differential Temp Light Flickering.....  | 04/10 |
| Updated M/T Transmission Drain Plug Gasket Information.....                                 | 06/10 |
| 2010-11 M/Y Legacy / Outback “Howling” from Under the Vehicle.....                          | 01/11 |
| 2010 M/Y & Later Legacy / Outback 6 M/T Reverse Gear Damage.....                            | 01/12 |
| BRZ Manual Transmission Sounds .....  | 06/12 |
| Color Change To Manual Trans Oil Level Dipstick .....                                       | 10/12 |
| All Manual Transmission Equipped Vehicles .....   | 11/12 |
| 2015 WRX Short Throw Shifter Precautions .....  | 05/14 |
| Transmission Cooler Flushing .....  | 08/15 |
| BRZ 6M/T Rattling Sound on Deceleration w/AC On.....  | 09/15 |
| Reminder-Cleaning and Lubrication of Clutch Release Components .....                        | 11/15 |
| P2751 and no CVT Engagement.....  | 05/16 |
| AT Learning Control Information.....  | 06/16 |
| Transmission Replacement Procedures.....  | 06/16 |
| No Movement after Valve Body Replacement on 10-12 Legacy/Outback CVT .....                  | 08/16 |
| Clutch Release Component Lubrication.....   | 10/16 |
| Clutch Release Component Lubrication and Inspection Revisited.....                          | 11/16 |
| Unnecessary CVT Replacement’s .....   | 12/16 |
| 2017 MY Impreza: Audio Volume Turned To Max When Monitoring Infotainment Data Monitor ..... | 03/17 |
| AT Learning Control Information.....  | 11/17 |
| Smoke from Exhaust on DIT Vehicles .....  | 12/17 |
| P2751 and no CVT Engagement.....  | 09/18 |
| Selectable Shift Fork Identification Marks .....  | 01/19 |

### 04-Steering

|   |       |
|---|-------|
| Loyale Power Steering Pump Failures.....  | 05/91 |
| XT-6 Mps Controller Set .....   | 01/92 |
| XT-6 Electronic Controlled Motor Drive Power Steering Service Manual Supplement ..... | 04/92 |
| XT-6 Motor Power Steering “Motor Pump” .....  | 05/92 |
| All Models Power Steering Pumps .....   | 06/92 |
| Testing Power Steering Pumps.....   | 06/93 |
| SVX Power Steering Pump Replacement .....   | 02/94 |
| Steering Rack Noise.....  | 01/97 |
| Power Steering Pump Replacement.....  | 03/97 |
| 2004MY Impreza and Forester Steering Column Cover.....                                | 10/03 |
| Parts Ordering Update for VSC Steering Angle Sensor .....                             | 10/03 |
| Power Steering Rack Repairs.....  | 11/05 |
| 2006MY STI Steering Angle Sensor.....   | 02/06 |
| Power Steering Pump Noise.....  | 04/07 |
| 2005 & Later SIA-Built Steering Rack Rebuilding Tool Info.....                        | 10/08 |
| Power Steering Rack Serviceability.....   | 06/11 |
| Electronic Power Steering .....   | 10/14 |



## 05-Suspension-Wheels & Tires

### 05-Suspension-Wheels & Tires

|   |       |
|---|-------|
| Legacy Rear Stabilizer Link Bushing Seat Change .....                                       | 07/91 |
| Loyale Rear Alignment .....   | 10/91 |
| All Models Alignment (Front & Rear) Tips .....  | 02/92 |
| Legacy 4WD Noise Coming From Right or Left Rear Area .....                                  | 10/92 |
| Legacy Front End "Pop" Noise .....  | 10/92 |
| All Four-Wheel Drive Vehicles .....   | 11/92 |
| All Models Wheel Lug Torque .....   | 11/92 |
| 1993MY Impreza Rear Suspension "Passive Four Wheel Steering" .....                          | 05/93 |
| All Subaru Models with Air Suspension, Including Legacy ("O" Rings) .....                   | 06/93 |
| Production Line Installation of Oil Filter and Power Steering Reservoir Filling .....       | 06/93 |
| All Subaru Models Front End Alignment .....   | 08/93 |
| 1992MY SVX Rear Suspension .....  | 08/93 |
| Impreza Wheels - 13" vs. 14" .....  | 01/94 |
| Impreza Rear Strut Noise Production Change .....  | 02/94 |
| 1991MY Legacy Complaint of Banging Over Bumps, Especially Prevalent In the Right Rear ..... | 03/94 |
| Impreza Rear Strut Noise Production Change .....  | 04/94 |
| Impreza Tire Rotation/Maintenance .....   | 06/94 |
| Procedures for Yokohama Tire Complaints .....   | 02/95 |
| Noisy Impreza Rear Struts .....   | 09/95 |
| Front Suspension Noise, 1995/96MY Subaru Legacy .....                                       | 04/96 |
| Impreza Outback Tires .....   | 09/96 |
| 1996MY & 1997MY 2.2L Manual Transmission Equipped Vehicle .....                             | 09/96 |
| Additional Tire Information For '97MY Impreza Outback .....                                 | 11/96 |
| Axle Shaft Grease .....   | 08/99 |
| Recommended Winter Tires for 2000MY Outback .....   | 01/00 |
| 2000MY Outback Winter (Snow) Tire Information (supplemental) .....                          | 03/00 |
| Tire Questions and Information Handling Procedures .....                                    | 09/01 |
| WRX and STI Recommended Winter/Snow Tires .....   | 11/03 |
| Stick-On Wheel Weights .....  | 09/04 |
| 2003MY Keyless Entry Control Module Interchangeability .....                                | 09/04 |
| Tire Pressure Monitoring System .....   | 10/04 |
| 2005MY Legacy/Outback – Use of Tire Chains .....  | 12/04 |
| Tire Pressure Monitoring System (TPMS) Equipped Vehicles .....                              | 12/04 |
| STi Clunk Noise in Rear .....   | 02/05 |
| Rear Stabilizer Link Positioning .....  | 10/05 |
| Tire Pressure Monitoring System – A Reminder .....  | 11/05 |
| B9 Tribeca Spare Tire Availability .....  | 02/06 |
| Tire Pressure Monitoring System (TPMS) – Additional Information .....                       | 03/06 |
| Tire Valve Stem Caps .....  | 03/06 |
| 2005~06MY Legacy/Outback Lower Control Arm Bushings .....                                   | 05/06 |
| TPMS Valve Core Tool .....  | 06/06 |
| B9 Tribeca Torque Support Plate Revised Torque Specification .....                          | 08/06 |
| Oil Seepage / Leaking From Struts .....   | 01/07 |
| Customer Concern about Tire Conicity & Vehicle Drift .....                                  | 02/07 |
| 2008 MY Tire Pressure Monitor (TPMS) Changes .....  | 05/07 |
| Emergency Wheel Lock Removal .....  | 06/07 |
| Wheel Lug Torque Specs .....  | 11/07 |
| Use of Nitrogen in the Tires of Subaru Vehicles .....                                       | 12/08 |
| 2010-11 Legacy / Outback Steering Vibration Updates: Helpful Hints .....                    | 09/10 |
| Tire Pressure Monitor System Reminders .....  | 10/10 |

## 05-Suspension-Wheels & Tires

|   |       |
|---|-------|
| 2011 M/Y Tire Pressure Monitor System “Quick TIP” ..... | 11/10 |
| Rear Stabilizer Bar Identification .....                | 03/11 |
| Front / Rear Suspension Strut Piston Seal Damage .....  | 11/11 |
| Front-End Rattling Noises Over Bumps.....               | 11/11 |
| Tribeca Spare Tire Color Change .....                   | 10/12 |
| 2005 And Up Front Lower Control Arm Bushings.....       | 05/13 |
| Tire Pressures-Check that Spare .....                   | 11/13 |
| Wheel Lug Socket Recommendation .....                   | 03/14 |
| Abnormal Noise Diagnosis .....                          | 07/16 |
| New Model Alignment Specifications .....                | 11/18 |
| Abnormal Noise Diagnosis .....                          | 12/18 |

**06-Brakes**

|   |       |
|---|-------|
| Legacy ABS Control Unit Code 10 .....   | 01/92 |
| ABS Light Illumination Code 16 (G-Sensor) .....   | 02/92 |
| Legacy Brake Vibration Complaints .....   | 06/92 |
| Legacy Front Disc Brake Pad Wear .....  | 11/92 |
| Legacy Right-Hand Drive Vehicles .....  | 12/92 |
| Legacy ABS-2E System .....  | 02/93 |
| Anti-Lock Brakes For Legacy .....   | 03/93 |
| Legacy Brake Pads .....   | 10/93 |
| 1994MY Impreza Hill Holder "Ghost Cars" .....   | 01/94 |
| Legacy Brake Rotors .....   | 02/94 |
| Impreza Throttle Position Switch Adjustment .....                                       | 06/94 |
| Non-Approved Adjustments on Legacy, Impreza, & SVX Throttle Plates and ISC Valves ..... | 06/94 |
| Rusty Brake Rotors .....  | 07/94 |
| Brake Rotor Machining With Pro-Cut Equipment .....                                      | 08/94 |
| TCS Operation with 'T-Type' Spare .....   | 10/94 |
| ABS Code 16 - Faulty ABS Control Unit or 'G' Sensor (AWD, M/T Model) .....              | 10/94 |
| Reading ABS Codes on Early Subaru Legacy Models .....                                   | 07/95 |
| Subaru Legacy - ABS Light on .....  | 08/95 |
| Brake Fluid Basics .....  | 09/95 |
| ABS And Select Monitor Usage .....  | 09/95 |
| ABS/TCS Equipped Legacy Vehicles .....  | 10/95 |
| 1995MY/1996MY Subaru Legacy with ABS .....  | 11/95 |
| 1996MY Subaru Legacy Equipped With ABS/5.3 System .....                                 | 11/95 |
| ABS-2E Control Units & ABS Code 23 .....  | 12/95 |
| Vehicle Not Complying With Federal & State Regulations .....                            | 12/95 |
| Intermittent Wheel Sensor Codes in Early Legacy ABS Systems (Non ABS-2E) .....          | 12/95 |
| Brake Noise...What Is Normal? .....   | 02/96 |
| 5.3 ABS System Service Manual .....   | 06/96 |
| Component Relocation with 5.3 ABS System .....  | 06/96 |
| ABS Equipped Subaru Vehicles System Check .....   | 08/96 |
| New 5.3I Type ABS System .....  | 02/97 |
| 5.3I ABS System Information Update .....  | 03/97 |
| ABS 5.3I Service Manual .....   | 04/97 |
| Identifying ABS Systems .....   | 05/97 |
| ABS 5.3I ABS Warning Light Operation .....  | 10/97 |
| ABS/TCS Code 57 .....   | 01/98 |
| Use of Non-Approved Brake Additives .....   | 05/98 |
| 1999MY Forester ABS .....   | 02/99 |
| Brake Judder & Noise; All Models .....  | 03/99 |
| 2002MY Impreza Brake Rotor Scoring.....   | 06/01 |
| Bulletin Numbers 03-31-03 & PT 370303.....  | 01/04 |
| Bleeding Brembo Brake System on WRX STI Models.....                                     | 03/04 |
| STI Brake Shim Kit .....  | 09/04 |
| Brake Pad Wear Indicator.....   | 03/05 |
| B9 Tribeca Brake Servicing .....  | 05/05 |
| Preventive Measure for Surface Rust around Disk Brake Pad.....                          | 05/06 |
| Brake Rotor Concentric Scaring.....   | 01/07 |
| VDC Control Module Servicing.....   | 09/07 |
| ABS Code C0111- ABS Motor Relay Function.....   | 12/07 |
| ABS / VDC Detail Codes and How to Use Them .....  | 03/08 |

## 06-Brakes

|  |       |
|--|-------|
| New TPMS Transmitter Design Reminders .....  | 06/08 |
| Brake Rotor Information.....   | 12/08 |
| Tapping or Clicking Noise, 2008-09 Impreza .....                                       | 03/09 |
| Brembo-Equipped Disc Brake Noise .....   | 03/09 |
| More C0054 & C0074 Information .....   | 04/09 |
| EPB Emergency Manual Release Procedure .....   | 11/09 |
| 2010 M/Y Legacy & Outback Master Cylinder Removal Precaution .....                     | 02/10 |
| “Click or Knock” Sound When Releasing the Brake Pedal.....                             | 05/10 |
| WVY-35 Master Cylinder Installation Precaution.....                                    | 01/12 |
| ABS Brake System Applied Model Information .....                                       | 03/12 |
| Vehicles Equipped with Eyesight.....   | 07/12 |
| Important Precautions For Eyesight Equipped Vehicles.....                              | 08/12 |
| 13 BRZ Revised Vehicle Stability Control Diagnostics .....                             | 11/12 |
| 12/13 Impreza Parking Brake Information.....   | 11/12 |
| EyeSight System Temporary Stop Information .....                                       | 02/13 |
| Click Or Knock Sound When Releasing The Brake Pedal (Reminder) .....                   | 02/13 |
| Proper Reporting of Eyesight Related Issues.....                                       | 04/13 |
| Precautions & Diagnostic Tips for Eyesight Equipped Vehicles .....                     | 04/13 |
| Brake Override System Operation and Hesitation Complaints.....                         | 11/13 |
| 2015 Legacy and Outback Electronic Parking Brake Codes C1956 or C1957 .....            | 08/14 |
| What’s That Green Stuff under the Master Cylinder Reservoir Cap.....                   | 05/15 |
| Brake Fluid Color Change .....   | 07/15 |
| Hill Holder ortarking Brake EPB Won’t Release .....                                    | 11/15 |
| Eyesight Replacement Parts .....   | 08/16 |
| 2017 Reverse Automatic Braking (RAB), Red Area Appears In Back-Up Camera Display ..... | 01/17 |
| Hill Start Assist Light On but No Codes.....   | 03/17 |
| 2017 Impreza Brake Caliper Oil Residue.....  | 11/17 |
| Tap or Click – Type Sound Heard When Coming to a Stop – 2019MY Ascent .....            | 01/19 |
| C0271 After Park Brake Actuator Replacement .....                                      | 02/19 |

**07-Electrical**

|   |       |
|---|-------|
| Justy ECVT/Ignition Relay .....   | 07/91 |
| Legacy Intermittent Hard Or No Start/Ground Shock Tower .....               | 07/91 |
| Legacy Ignition Relay .....   | 07/91 |
| Justy MPI Codes 11, 13 .....  | 07/91 |
| Phantom Code 22, Knock Sensor 87-89MY "L" And XT Series .....               | 09/91 |
| A/T Shift Lock System/Loyale .....  | 12/91 |
| L-Series OHV Engine-Engine Will Not Shut-Off .....                          | 01/92 |
| SVX and Legacy Brake Lights Staying On .....                                | 01/92 |
| Legacy Poor Radio Reception/Low Volume Output .....                         | 03/92 |
| 90MY to Present Justy MPI Distributor Wiring .....                          | 04/92 |
| Legacy S/W Fuse No.5 Continually Blows-Out .....                            | 05/92 |
| Legacy Sunvisor Lighted Mirror Wiring #15 Fuse .....                        | 05/92 |
| Legacy Starters .....   | 10/92 |
| 1992 MY Legacy & SVX Ignition Relay .....                                   | 10/92 |
| Aftermarket Batteries .....   | 11/92 |
| 1992MY SIA Legacy S/W Rear Gate Telltale Light Won't Go Out .....           | 11/92 |
| Justy Trouble Code 23: Pressure Sensor .....                                | 01/93 |
| 1993MY Impreza Relays .....   | 05/93 |
| Electrical Tips .....   | 07/93 |
| Legacy Sunroof Wiring Schematic & Switch Operation .....                    | 09/93 |
| Electrical Problems? Check the Fuse .....                                   | 10/93 |
| Impreza Headlamp Information .....  | 10/93 |
| 1990MY Legacy with Code 41 in ECU Memory .....                              | 11/93 |
| 1990MY Legacy Code 42 Throttle Position Switch from ECM .....               | 11/93 |
| ROM Application Chart .....   | 11/93 |
| 1993MY Loyale Intermittent Wiper Wiring Diagram .....                       | 01/94 |
| Six-Step Troubleshooting Method .....                                       | 02/94 |
| Rear Defogger Wiring & Terminal Repair Kit .....                            | 02/94 |
| 1990MY-Present Loyale Fuel Pump Control Unit Wiring Diagram .....           | 03/94 |
| 1992MY SVX ROMS .....   | 03/94 |
| Battery Charging .....  | 03/94 |
| ECVT Trouble Code 31 .....  | 04/94 |
| ECVT - Select Monitor Speed Sensor Reading .....                            | 04/94 |
| Impreza Headlights .....  | 04/94 |
| Legacy Fuel System Wiring Diagram .....                                     | 05/94 |
| Impreza Fuel Tank Sending Unit Specifications .....                         | 05/94 |
| 1995MY Legacy Electrical Component Location Quick Reference List .....      | 07/94 |
| Legacy Fuel System Wiring Diagram .....                                     | 08/94 |
| SVX Spark Plug Servicing .....  | 09/94 |
| Ignition Relays .....   | 10/94 |
| Ignition Relays - The Sequel .....  | 10/94 |
| 1995MY Legacy Speed Limiting Device .....                                   | 11/94 |
| SPI Trouble Code 13 (Crank Angle Sensor) From ECU .....                     | 11/94 |
| OBD II Check Engine Light .....   | 12/94 |
| Speed Sensor 2 .....  | 01/95 |
| 1994MY Legacy Seat Heaters .....  | 01/95 |
| Cold Shift Locks (Impreza Shift Locks That Won't Unlock When Cold) .....    | 02/95 |
| 1985MY & Later L-Series MPFI Improper Engine Operation above 2000 RPM ..... | 03/95 |
| Battery Replacement .....   | 03/95 |
| Electrical Diagnosis, the Helpline, & You .....                             | 04/95 |

## 07-Electrical

|   |          |
|---|----------|
| Battery Charging .....  | 05/95    |
| Electrical Condition Reporting .....  | 06/95    |
| ROM Installation .....  | 08/95    |
| 1 Mw Min. ....  | 09/95    |
| 1996MY Subaru Legacy Outback Fog Lamps .....  | 10/95    |
| 1995MY Subaru Legacy Outback Rear Power Outlet .....  | 11/95    |
| Identification of Cam and Crank Sensors .....   | 07/96    |
| 1995MY/96MY Subaru Legacy Blows Fuse SBF-2 .....  | 07/96    |
| 1997MY Legacy Power Door Lock System .....  | 09/96    |
| Sticking or Difficult Auto Down P/W Switch Buttons (Mistakenly Printed In Section 11) ..... | 10/96    |
| Diagnostic Trouble Code P0341 .....   | 10/96    |
| Loose Window Regulators .....   | 10/96    |
| Rear Defogger Timer .....   | 03/97    |
| Legacy Heater Control Panel Bulbs .....   | 03/97    |
| '98MY Forester Transit Connector Location .....   | 08/97    |
| '98MY Forester Trailer Hitch Wiring Harness .....   | 08/97    |
| '95MY-'97MY Legacy Moisture Accumulation in the Headlights .....                            | 04/98    |
| 2000MY Legacy Battery .....   | 09/99    |
| Wiring Harness Connector I5 .....   | 09/99    |
| Electrical Problems? Check The Alternator. ....   | 11/99    |
| 2000MY Legacy Blows Fuse #5 .....   | 01/00    |
| 2000MY Subaru Legacy Turn Signal Operation .....  | 02/00    |
| 2000MY Legacy & Outback Vehicles Fog Light Operation .....                                  | 04/00    |
| Grounds, Grounds, Grounds .....   | 07/00    |
| Daytime Running Lights .....  | 08/00    |
| Windshield Wiper Deicer System not Working .....  | 11/00    |
| Turn Signals Flashing Rapidly .....   | 11/00    |
| Blower Motor Resistor Repairs .....   | 01/01    |
| In-Dash Cigarette Lighter Usage .....   | 06/01    |
| Alternator Supplier Update .....  | 08/01    |
| Legacy Transit (D-check plug) Connectors .....  | 03-04/02 |
| Fuse 4 Blows-Out .....  | 03-04/02 |
| Legacy Rear Wiper Operation .....   | 03-04/02 |
| 2005MY Legacy/Outback Trailer Hitch Harness Location .....                                  | 07/05    |
| Backup Power Supply Fuse.....   | 10/05    |
| 2005MY Forester Diagnostic Connector .....  | 11/04    |
| 2005MY Legacy/Outback Electrical Diagnosis.....   | 02/05    |
| Body Integrated Unit (BIU) Replacement .....  | 03/05    |
| Fuse Label Correction .....   | 03/05    |
| HVAC & Audio Unit Inoperative After Wiring Harness Change .....                             | 04/05    |
| 2005MY Baja with Poor Radio Reception .....   | 04/05    |
| HVAC Inoperative After Wiring Harness Change—More Information .....                         | 05/05    |
| 2003MY Forester Fuse Information .....  | 08/05    |
| Battery Going Dead or Alarm Going Off.....  | 09/05    |
| Information Requested For Harness Repair Kits .....   | 11/05    |
| 2006MY Legacy/Outback and B9 Tribeca Combination Meter Self Diagnosis.....                  | 02/06    |
| Change of Seat Heater Relay .....   | 02/06    |
| Low Battery Voltage .....   | 06/06    |
| 2005MY Forester A/F & O2 Sensor Relay Location.....   | 06/06    |
| SBF-5 Fuse Blows On 2005 MY / 2006 MY Impreza Vehicles.....                                 | 07/06    |
| “Dark Current” Or Excessive Battery Draw .....  | 02/07    |
| Erratic Tail Light Operation .....  | 04/07    |

## 07-Electrical

|  |       |
|--|-------|
| More “Dark Current” Information .....                                  | 04/07 |
| Headlight Bulb Replacements –A Reminder .....                          | 05/07 |
| New Style 2008 MY Legacy, Outback & Tribeca Keys .....                 | 06/07 |
| Midtronics inTELLECT EXP Battery Tester Logic Update .....             | 06/07 |
| Headlight Bulb Socket Repairs.....                                     | 07/07 |
| 2008 MY High Security Keys.....  | 08/07 |
| 2008MY Impreza Headlight Switch Operation.....                         | 09/07 |
| 2008 Impreza Stop Light Switch C0074 and C0054.....                    | 01/08 |
| BIU Replacement and Keys.....  | 05/08 |
| 2008 Impreza Data Link Connector Color Change.....                     | 06/08 |
| Legacy & Outback Door Switch (Nov 2004 production & after).....        | 06/08 |
| Wiring Harness Connector Similarities & Cautions .....                 | 07/08 |
| Forester Sunroof Reverses When Closing .....                           | 12/08 |
| 2008-09 Impreza, Erratic Outside Temperature Gauge Operation.....      | 01/09 |
| Door & Ignition Lock Cylinder Replacement Clarification .....          | 02/09 |
| 2009 M/Y Forester Power Window Information.....                        | 03/09 |
| Power Door Locks Inoperative, 2009 M/Y Forester.....                   | 04/09 |
| “Dark Current” ....Revisited .....                                     | 06/09 |
| 2010 M/Y Legacy & Outback Auto Up / Down Feature Operation.....        | 08/09 |
| Speedometer Inoperative? Don’t Overlook the Sunroof Wiring .....       | 08/09 |
| 2010 M/Y Legacy & Outback Low-Beam Bulb Replacement .....              | 08/09 |
| 2010 M/Y Legacy & Outback Headlight Bulb Replacement Information ..... | 09/09 |
| 2010 M/Y Legacy & Outback Power Window Operation .....                 | 10/09 |
| Re-Coding Laser-Cut Keys.....  | 01/10 |
| 2010 M/Y Legacy & Outback Oil Level Warning Information.....           | 02/10 |
| 2010 M/Y Legacy & Outback BIU Interchangeability.....                  | 02/10 |
| 2010 M/Y Forester “Resonating” Noise When Using the Horn.....          | 03/10 |
| 2010 M/Y Forester Dome Light Erratic Operation.....                    | 05/10 |
| 2010 and 2011 Driver’s AUTO-UP Reset Information .....                 | 10/10 |
| 2008 – 2011 Impreza Front Turn Signals Blink Too Fast .....            | 01/11 |
| Remote Trunk Release Inoperative After BIU Replacement.....            | 05/11 |
| 2008 M/Y and Later Impreza Stop Light Switch Information .....         | 05/11 |
| Sunroof Operation Service Bulletins .....                              | 05/11 |
| New DTC’s After Bulkhead Harness Replacement.....                      | 06/11 |
| CAN System Diagnostic Information .....                                | 07/11 |
| Immobilizer Codes Stored, Engine Starts and Stalls Condition.....      | 08/11 |
| 2011 M/Y Impreza High Beams Not Bright Enough?.....                    | 10/11 |
| Headlight Aiming Precautions .....                                     | 11/11 |
| Tom-Tom Equipped Volume Control Information .....                      | 12/11 |
| 2012 M/Y Impreza No Start, SBF-6 Blown.....                            | 01/12 |
| 2012 Impreza Key Information .....                                     | 03/12 |
| Sunroofs and Car Washes.....   | 04/12 |
| Battery Testing, the Importance of Using the Right Standard .....      | 04/12 |
| Re-Programming Information for All 2011-12 M/Y Vehicles .....          | 05/12 |
| 2013 BRZ Auto Up/Down Window Feature.....                              | 09/12 |
| Hard To Fill Fuel Tank.....  | 09/12 |
| Eyesight Camera Adjustment .....                                       | 10/12 |
| 13 MY Legacy And Outback Accessory Charging.....                       | 11/12 |
| Electrical Devices And Air Bag Systems .....                           | 12/12 |
| 14 MY Forester Turbo Battery Cable Precaution/ DTC P0606 .....         | 02/13 |
| Appearance of Water in BRZ Back Up Light .....                         | 03/13 |
| Memory Height Learning Procedure.....                                  | 04/13 |

## 07-Electrical

|   |       |
|---|-------|
| Erratic Digital Fuel Gauge Operation, 2012 My and Later Impreza, BRZ, and 2014 Forester ..... | 04/13 |
| Immobilizer/ Key Registration Information .....   | 04/13 |
| 2014 Forester Information Display Selection Knob( or the Right Side or Other Trip Knob) ..... | 04/13 |
| Campaign WQF-42 Information.....  | 05/13 |
| Fuel Gauge Diagnostic's.....  | 05/13 |
| 2014 Forester Turbo, ECM Electrical Testing Reminder .....                                    | 06/13 |
| 2014 Forester Power Rear Gate (PRG) Initialization Procedure .....                            | 06/13 |
| 2014 Forester Non-Turbo ECM And BIU Locations .....   | 06/13 |
| 2014 Forester L/F Power Window auto up/down operation .....                                   | 08/13 |
| HVAC Electrical Connections .....   | 09/13 |
| BIU Replacement on all Push-button Start Vehicles .....                                       | 10/13 |
| 2014 Forester Seat heater Operation and Switch Functions .....                                | 11/13 |
| Headlight Adjustment Reminders .....  | 11/13 |
| ODS Code 29 or 37, Electrical Devices and Air Bags revisited.....                             | 12/13 |
| Appearance of Water Droplets in BRZ Exterior Lamps .....                                      | 01/14 |
| Important Hybrid Vehicle Aux Battery Precautions.....   | 01/14 |
| Operation of SI-Drive, Sport Sharp(S+) Mode after Cold Start.....                             | 02/14 |
| Midtronics GR8Use During Control unit Programming.....  | 02/14 |
| 2010-14 Legacy& Outback Fuse # 16 Failed in the Main Fuse Box.....                            | 03/14 |
| DTC P0724, Brake Switch Circuit High Input.....   | 03/14 |
| Passenger Side Power Window Auto Up/Down Function.....  | 08/14 |
| 2015 Legacy/Outback Power Window Auto Up/Down Operation Revisited .....                       | 09/14 |
| 2015MY Legacy and Outback Under Hood Main Fuse Box (M/B) Information.....                     | 09/14 |
| 2015 Legacy and Outback Cold Weather Light Operation .....                                    | 10/14 |
| 2015 Legacy and Outback Under-Hood Main Fuse Box (M/B) Information.....                       | 10/14 |
| 2015 Legacy and Outback Keyhole Shadow From Projector Beam Headlamp.....                      | 10/14 |
| Dark Current Draw Revisited .....   | 11/14 |
| Bluetooth Pre-Call Worksheet .....  | 11/14 |
| 2015 Legacy/Outback Unnecessary Power Window Switch Replacements .....                        | 12/14 |
| Body Integrated Unit (BIU) Replacement/ Interior Lights Flashing .....                        | 01/15 |
| Identifying Electrical Harness Connectors.....  | 04/15 |
| Electrical Diagnosis and Aftermarket Equipment .....  | 04/15 |
| DTC Diagnosis and Related Wiring Harness Checks.....  | 05/15 |
| 2010-2016 Forester TPMS light flashing, Sensor Registration Issues.....                       | 09/15 |
| Spark Plug Information a Reminder.....  | 03/16 |
| Battery Servicing Precautions .....   | 03/16 |
| GR-8 1100 EST Battery Diagnostic Station, Power Supply Mode.....                              | 05/16 |
| No Crank No Start Diagnosis .....   | 06/16 |
| Blue-Tooth Pre-call Worksheet .....   | 07/16 |
| Ignition Key Cannot Be Removed From Ignition Switch .....                                     | 10/16 |
| Quick Reference Immobilizer Type.....   | 10/16 |
| Replacing B-Type BIU .....  | 10/16 |
| Fuel Gauge Diagnosis Revisited .....  | 11/16 |
| Power Window erratic, cannot program memory.....  | 01/17 |
| No Hybrid Auto Start Stop or Ev Travel .....  | 01/17 |
| BIU replacement.....  | 01/17 |
| Satellite Signal Lost When Traveling South 2014-UP Forester .....                             | 02/17 |
| PAK file error messages .....   | 05/17 |
| B1650 Proper Diagnosis .....  | 06/17 |
| Blind Spot Detection Off .....  | 01/18 |
| Ground Circuit Identification .....   | 03/18 |
| No Hybrid Auto Start Stop or EV Travel.....   | 03/18 |



## 07-Electrical

|  |       |
|--|-------|
| ECM Reprogramming .....  | 05/18 |
| Audio Unit Service/Diagnostic Menu .....                                   | 06/18 |
| Quick Reference Immobilizer Type .....                                     | 08/18 |
| Replacing B-Type BIU .....   | 08/18 |
| Ascent Automatic Wiper Rain Sensor Initialization.....                     | 10/18 |
| 2019MY Forester, Driver Monitoring System (DMS) Inoperative .....          | 11/18 |
| 2019MY Forester, Loose Negative Battery Cable/Terminal Connections.....    | 11/18 |
| Performing Variant Work When Replacing Combination Meter .....             | 12/18 |
| Automatic Start-Stop System Enable Conditions .....                        | 12/18 |
| 2019MY Forester, Driver Monitoring System (DMS) Inoperative *UPDATE* ..... | 01/19 |
| Gen 3 Clock Related Concern.....   | 02/19 |
| 2018 – 19MY Legacy & Outback – B1650 .....                                 | 02/19 |
| 2019MY Forester- Rear Seat Heaters Inoperative.....                        | 03/19 |
| 2019MY Forester- Automatic Seat Retraction Feature Operation .....         | 03/19 |
| Electrical Diagnosis and Aftermarket Equipment .....                       | 03/19 |

### 08-Instrument & Controls

|   |       |
|---|-------|
| High Reading Temperature Gauge, Digital Dash 85MY & 86MY “L” Series, Including XT ..... | 08/91 |
| L-Series Speed Sensor Replacement .....   | 02/92 |
| 1992MY Legacy FWD Modified Fuel Tank Sender Unit .....                                  | 09/92 |
| Corrections to Previous Helpline Updates .....  | 11/92 |
| Odometer Labels .....   | 02/93 |
| Legacy Knock Sensor Testing .....   | 03/93 |
| Legacy All Wheel Drive Fuel Gauge .....   | 04/93 |
| Impreza Combination Meter Tachometer .....  | 05/93 |
| Legacy Postal Vehicles with Single Action Power Door Locks .....                        | 11/93 |
| Speedometer Inaccuracies .....  | 01/95 |
| Warning Light Operation .....   | 02/95 |
| Legacy and Impreza Fuel Tank Sending Units .....  | 05/95 |
| Instrument Cluster Circuit Boards .....   | 10/96 |
| Fuel Gauges on “E” .....  | 10/96 |
| 1998MY Subaru Forester/Impreza Digital Odometer .....                                   | 09/97 |
| Odometer Policy .....   | 02/01 |
| Ambient Temperature Sensor .....  | 04/04 |
| SI-Drive Multi-Information Clock Display Characteristics .....                          | 04/08 |
| 2010 M/Y Legacy & Outback Clock Setting Procedure .....                                 | 08/09 |
| Adjusting the Clock and Settings of the Multi-Function Display .....                    | 05/10 |
| Shift Indicator Light Applicability, 2012M/Y Impreza .....                              | 04/12 |
| BRZ Trunk Release Operation .....   | 07/12 |
| Navigation Screen Displaying The Language Menu .....                                    | 11/12 |
| 2014 Forester Multi Function Display Messages .....                                     | 08/13 |
| 2015MY Legacy/Outback, Journey Time Alert on Combination Meter Tell tail Display .....  | 09/15 |

## 09-Cooling, Fuel, & Exhaust System

### 09-Cooling, Fuel, & Exhaust System

|   |          |
|---|----------|
| Justy FWD-ECVT Noise from Exhaust Pipe Joint .....              | 05/91    |
| Legacy 4EAT Radiators .....                                     | 02/92    |
| Subaru Exhaust Systems .....                                    | 04/92    |
| 1992MY SIA Models Production Fuel Filter .....                  | 05/92    |
| Legacy Exhaust Whistle Turbo & Naturally Aspirated .....        | 06/92    |
| 1992MY Legacy FWD Modified Fuel Tank Sender Unit .....          | 09/92    |
| Corrections to Previous Helpline Updates .....                  | 11/92    |
| Coolant Recycling .....   | 06/93    |
| Summer Low RVP Fuels .....                                      | 06/94    |
| Fuel Quality Check .....  | 06/94    |
| Fuel Switching .....  | 09/94    |
| Impreza Fuel Tank Sending Unit Assemblies .....                 | 09/94    |
| Impreza Fuel Tank Capacity .....                                | 10/94    |
| Replacing Loyale Thermostats .....                              | 11/94    |
| 2.2L Impreza AWD Fuel Senders .....                             | 04/95    |
| Reformulated Gasoline .....                                     | 05/95    |
| Loyale Water Pump Leaks .....                                   | 07/95    |
| Modified Fuel Injectors .....                                   | 10/96    |
| Cooling Fan Operation .....                                     | 09/97    |
| 1999MY Legacy Excessive Crank Time .....                        | 03/99    |
| Vehicle Won't Take Fuel .....                                   | 03/99    |
| Vehicles That Won't Take Fuel .....                             | 09/99    |
| Fuel System Quick Connector .....                               | 10/99    |
| Don't Touch That Screw! .....                                   | 01/00    |
| Sulfur Smell from the Exhaust .....                             | 05/00    |
| Use of Genuine Air Cleaner Element.....                         | 11/00    |
| H-6 Extended Crank Time.....                                    | 01-02/02 |
| Forester Fuel Line Noise .....                                  | 09-10/02 |
| WRX STi Driveability .....                                      | 08/03    |
| 2004MY Legacy Fuel Filter Replacement.....                      | 09/03    |
| H6 Drivability .....  | 11/03    |
| New Product Orientation for the Cooling System Conditioner..... | 04/04    |
| 2004MY Legacy/Outback H-6 and H-4 (NA) Fuel Line Removal .....  | 05/04    |
| 2005MY Legacy Fuel Line Rattle .....                            | 11/04    |
| Fuel Order in Cold Weather (Service Bulletin Reminder) .....    | 11/04    |
| Fuel Line Tool .....  | 12/04    |
| Gas Mileage .....   | 03/05    |
| Fuel Hose Retainer Clips.....                                   | 06/05    |
| B9 Tribeca Fuel Line Tool.....                                  | 04/06    |
| Subaru Vehicles and Driveability .....                          | 09/06    |
| STI Models Fuel Recommendation .....                            | 11/06    |
| Fuel Odor on Initial Cold Starts .....                          | 02/07    |
| Engine Cooling System Service & Care Recommendations.....       | 06/07    |
| Fuel-Related Driveability Concerns.....                         | 08/07    |
| Genuine Subaru Cooling System Conditioner Information.....      | 10/07    |
| Subaru Super Coolant.....                                       | 11/07    |
| P0171 and "Hard Start" Concerns.....                            | 12/07    |
| More Subaru Super Coolant Information.....                      | 03/08    |
| Wynn's Cooling System Equipment Announcement .....              | 08/08    |
| "Back To Basics" Rattling Noises From Under the Car .....       | 02/09    |

## 09-Cooling, Fuel, & Exhaust System

|   |       |
|---|-------|
| 2009 M/Y Forester Fuel Gauge Inconsistency .....  | 02/09 |
| 2010 M/Y Impreza, Rattling Noise from Exhaust.....                                      | 10/09 |
| More "Super Coolant" Information.....   | 10/09 |
| WVJ-20 (Baja Fuel Pump Outlet Pipe) Revised Product Campaign Bulletin Information ..... | 11/09 |
| 2011 M/Y Impreza Fuel Door Update .....   | 12/10 |
| 2011 M/Y Forester Fuel Pressure Testing Information.....                                | 02/11 |
| Rough Idle Condition Following WVU-31 Reprogramming .....                               | 06/11 |
| DTC P0453 Diagnostic Information .....  | 11/11 |
| FB Engine Fuel Pressure Testing Information .....                                       | 03/12 |
| BRZ High Pressure Fuel Pump .....   | 07/12 |
| BRZ Exhaust System Hardware.....  | 08/12 |
| Radiator Leaks And Damage.....  | 08/12 |
| Locksmith Information .....   | 09/12 |
| Use of Dye In AC Systems .....  | 09/12 |
| 12 Impreza Muffler Appearance Change.....   | 10/12 |
| New Fuel With 15% Ethanol .....   | 10/12 |
| AF sensor and O2 sensor Removal.....  | 01/13 |
| New Fuel 15% Ethanol Reminder .....   | 08/13 |
| Hard to Fill Fuel Tank Revisited .....  | 12/14 |
| Cooling System Appears to be Overfilled at PDI.....                                     | 06/15 |
| P05A0 and Active Grill Shutter Inspection.....  | 01/17 |
| Fuel Tank Cannot be Filled.....   | 07/17 |

# 10-Heating Ventilation & A/C Systems

## 10-Heating Ventilation & A/C Systems

|  |       |
|--|-------|
| A/C Service Oil Adjustment .....   | 06/91 |
| A/C Diagnostic Aids .....  | 08/91 |
| A/C Pulser System Electrical Diagnosis 89MY & 90MY Loyale .....                          | 08/91 |
| 1992MY Legacy A/C Compressor Bracket Discontinuation .....                               | 11/91 |
| Justy Wynn's Air Conditioning Installation .....   | 03/92 |
| The Use of A/C Refrigerants Other Than R-12 .....  | 07/92 |
| Justy Air Conditioning Information .....   | 07/92 |
| Air Conditioning Evaporator Odor .....   | 08/92 |
| SVX Zexel Auto A/C .....   | 09/92 |
| Legacy A/C Compressor .....  | 10/92 |
| Legacy A/C Kit Supersession .....  | 10/92 |
| HFC134a Air Conditioning Refrigerant .....   | 02/93 |
| R134a Air Conditioner Refrigerant Service Bulletin .....                                 | 03/93 |
| Legacy Zexel Air Conditioning .....  | 04/93 |
| Legacy Compressor Belt Tension .....   | 04/93 |
| 1993 MY Impreza Air Conditioning Inoperative .....                                       | 07/93 |
| Loyale Factory Installed A/C Does Not Operate .....                                      | 07/93 |
| HFC 134a Air Conditioning Systems .....  | 07/93 |
| SVX Auto A/C Display Degrees Celsius to Degrees Fahrenheit .....                         | 11/93 |
| Bulletin 10-64-92 Heater Vent Door Binding or Leaking Air .....                          | 12/93 |
| Refrigerant Cross Contamination .....  | 01/94 |
| 0Z-12: The Facts .....   | 02/94 |
| SVX Complaints of No Heat from Dash Vents .....  | 04/94 |
| 1995MY Impreza Coupe - Bubbles from the Dash Vents .....                                 | 10/94 |
| A/C Reminder .....   | 05/95 |
| PAG Oils .....   | 05/95 |
| Air Conditioner Hoses .....  | 08/95 |
| 1995MY RHD Postal Legacy Air Conditioning System .....                                   | 08/95 |
| A/C System Diagnostic Tips .....   | 08/95 |
| A/C Testing For System Leakage .....   | 08/95 |
| SVX A/C Cutting out When Ambient Temperature Is Hot; SVX Engine Running Hot .....        | 09/95 |
| SVX Evaporator Thermo Sensor, Intake Sensor .....  | 10/95 |
| A/C Performance-All Models .....   | 10/95 |
| Refrigerant Recovery and Recycling Certification .....                                   | 06/96 |
| CFC R-12 Substitute Refrigerants .....   | 06/96 |
| Refrigerant Substitutions Warning .....  | 08/96 |
| SVX A/C Temperature Control Indicating Centigrade vs. Fahrenheit .....                   | 10/96 |
| A/C Odors .....  | 05/97 |
| 1997MY Legacy A/C Seal Ring (Axis Seal) Change .....                                     | 05/97 |
| 1998MY Subaru Forester Dash Vent Noise .....   | 09/97 |
| 1998MY Subaru Forester Squeaking Noise with A/C on .....                                 | 09/97 |
| Dust and Dirt Entering Rear of Vehicle .....   | 11/97 |
| Subaru Impreza Center Dash Vent Airflow .....  | 07/98 |
| Subaru A/C Retrofit Kits .....   | 09/98 |
| Use of A/C Dyes in Subaru Air Conditioning Systems, Manufacturer's Recommendations ..... | 09/98 |
| Seasonal Reminder .....  | 05/99 |
| A/C Retrofit Kit Information .....   | 07/99 |
| A/C Inoperative – Impreza/Forester Vehicles .....  | 10/99 |
| 2000MY Legacy Heater Control Cables .....  | 05/00 |
| 2001MY A/C Disconnect Procedure .....  | 07/00 |

## 10-Heating Ventilation & A/C Systems

|  |          |
|--|----------|
| Mode Control Panel Change .....  | 02/01    |
| 2001MY Legacy Evaporator Thermostat Probe Location .....                             | 07/01    |
| Legacy H6 A/C Compressor Cutting Out .....   | 08/01    |
| Valeo/Zexel A/C TXV Fastener Torque Specification .....                              | 08/01    |
| H6 Climate Control System Information .....  | 09/01    |
| Change To 2002MY Legacy/Outback A/C Information .....                                | 09/01    |
| 2001/2002MY Legacy Blower Motor Noise .....  | 11/01    |
| Blower Motor Noise .....   | 08/02    |
| Blower Motor Noise .....   | 01-02/03 |
| Auto. A/C System Aspirator Tubes .....   | 07/03    |
| Service Bulletin 10-72-02R – An Update .....   | 10/03    |
| B9 Tribeca Air Conditioning Information .....  | 09/05    |
| Water Leaking Onto Passenger Floor Board Area .....                                  | 09/05    |
| Water Leaking From A/C Evaporator.....   | 10/05    |
| 2005MY Legacy/Outback: Water Leaking from A/C Evaporator.....                        | 11/05    |
| 2005~06MY Legacy/Outback Center Dash Vent Temperature .....                          | 05/06    |
| B9 Tribeca Air Conditioning Information .....  | 06/06    |
| H6 A/C Compressors Cutting Off .....   | 06/06    |
| 06MY Impreza Models: Manual Climate Control System Air Flow Dial “Spring Back” ..... | 07/06    |
| Refrigerant Dye Use to Detect Refrigerant Leaks .....                                | 10/06    |
| A/C Operation Logic Change for 2007MY .....  | 11/06    |
| R134-A Recycling Recovery and Recharge Machines: New Manufacturing Standards.....    | 12/06    |
| 2007 MY Forester A/C Compressor Changes.....   | 04/07    |
| A/C Certification –It’s the Law .....  | 04/07    |
| Erratic Dash Vent Temperatures.....  | 02/08    |
| HVAC Servo Harness Connector Confusion .....   | 01/09    |
| 2010 – 11 Legacy / Outback Vibration Felt in the Brake Pedal.....                    | 11/10    |
| Reminder- Use of A/C Leak Detection Dyes .....                                       | 08/11    |
| Center Dash A/C Vents Closing, 2010-12 M/Y Legacy / Outback Models.....              | 11/11    |
| 2013-14 Legacy and Outback Center Console Rear Air Vent Function .....               | 03/14    |
| A/C Diagnosis.....   | 07/17    |
| Condensation Inside Vehicles .....   | 12/17    |
| R-134 A/C Oil Guidelines.....  | 07/18    |
| B2242 Set With no Trouble Symptom.....   | 02/19    |

## 11-Emission Systems

|  |              |
|--|--------------|
| Justy "Check Engine" Light On/EGR Hose Pulling Off .....                                   | 11/91        |
| ROM Reminder/Legacy A/T Vehicles .....   | 12/91        |
| SVX Trouble Code 12 .....  | 12/91        |
| SVX Code 37 O2 Sensor (LH) .....   | 01/92        |
| L-Series SPI Code 34 (EGR Solenoid) .....  | 02/92        |
| All Models False Trouble Codes .....   | 04/92        |
| Legacy Turbo Sport Sedan Code 45 (Pressure Sensor, Pressure Exchange Solenoid Valve) ..... | 06/92        |
| Legacy Code 32 O2 Sensor .....   | 06/92        |
| Justy Code 13 .....  | 08/92        |
| ROM Installation Tips .....  | 09/92        |
| ECU Memory-All Models .....  | 09/92        |
| Justy Trouble Code 23: Pressure Sensor .....   | 01/93        |
| O2 Sensors for XT4 and XT6 Vehicles .....  | 12/93        |
| Legacy Code 32 O2 Sensor .....   | 03/94        |
| Carbureted Vehicles with ID Codes While Engine Is Running .....                            | 06/94        |
| OBD II - DTC P0441 "Evaporative Emission Control System Incorrect Purge Flow" .....        | 11/94        |
| OBD II Test Drives .....   | 11/94        |
| Legacy and Impreza Engines with No Injection Pulse #1 Cylinder .....                       | 03/95        |
| Impreza Air Suction Valve Noise .....  | 03/95        |
| 1995MY Subaru Legacy DTC P0505 - Idle Control System Malfunction.....                      | 06/95        |
| 1995MY Subaru Legacy DTC P0325 - Knock Sensor Circuit Malfunction .....                    | 06/95        |
| 1995MY Subaru Legacy DTC P0130 - Front O2 Sensor Circuit Malfunction .....                 | 06/95        |
| Rough Idle on MPFI Vehicles .....  | 07/95        |
| 1994MY Impreza ROM Sockets .....   | 07/95        |
| DTC P0505 Idle Control System When Solenoid Measures 5w or Less .....                      | 09/95        |
| Extreme Cold Weather Engine Warm Up & OBD II .....   | 12/95        |
| Loose Fuel Caps & Trouble Code P0440 .....   | 07/96        |
| 1997MY Legacy Warranty Claims For Loose Fuel Caps .....                                    | 09/96        |
| Legacy (Non Turbo), SVX, & Impreza ISC Valves .....  | 09/96        |
| DTC P0440 & Legacy Fuel Caps .....   | 11/96        |
| Blue Vs. Gray Connectors during Diagnosis .....  | 11/96        |
| Extreme Cold Weather Engine Warm-Up & OBD-II .....   | 11/96        |
| DTC P1500 Radiator Fan Relay One Circuit .....   | 03/97        |
| 1997MY Subaru Impreza Outback Sport .....  | 03/97        |
| Understanding P0440 .....  | 04/97        |
| DTC P0507- Idle Control System RPM Higher Than Expected .....                              | 05/97        |
| DTC P0500 .....  | 07/97        |
| Additional Information regarding Code P0440 .....  | 07/97        |
| OBD-II Cylinder Misfire Codes .....  | 08/97        |
| More P0440 Information .....   | 10/97        |
| Exhaust Smell during Cold Start .....  | 01/98        |
| Model Year 1998 Changes In P0440 Evap. Operation .....                                     | 1/98 & 05/98 |
| DTC P0440 Revisited .....  | 05/98        |
| DTC P0440 Tip .....  | 11/98        |
| DTC P1507 .....  | 11/98        |
| DTC P0705 Diagnostics .....  | 05/99        |
| Freeze Frame Data .....  | 08/99        |
| Evaporative System Diagnosis .....   | 09/99        |
| OBD Readiness Codes .....  | 11/99        |

## 11-Emission Systems

|  |          |
|--|----------|
| DTC P0440 1998/1999MY Forester .....                             | 1/99     |
| WXV-79 Engine Control Module Service Program .....               | 11/00    |
| Freeze Frame Data.....   | 05/01    |
| Ignition Coil Service Precaution .....                           | 01-02/02 |
| 2002MY Legacy Atmospheric Pressure Solenoid Valve Operation..... | 03-04/02 |
| DTC P1591 2002MY Impreza WRX M/T .....                           | 03-04/02 |
| C.I.D. Number for Reprogramming.....                             | 03-04/02 |
| WWG-90 Campaign Bulletin Correction.....                         | 08/02    |
| ECM Reflashing Claim Coding .....                                | 01-02/03 |
| Diagnostic Trouble Codes After WWK-94 .....                      | 05/03    |
| ECM Calibration Identification Numbers.....                      | 05/03    |
| ECM Reflashing.....  | 05/03    |
| Control Unit Reflashing Information.....                         | 07/03    |
| Diagnostic Trouble Code (DTC) Detecting Criteria .....           | 08/03    |
| Rough Idle/Check Engine Light after Battery Disconnect .....     | 09/03    |
| Evaporative Canister Rattle Noise in '04MY Impreza .....         | 09/03    |
| ECM Reprogramming – A Reminder.....                              | 01/04    |
| 2004MY Legacy PZEV Vehicles.....                                 | 04/04    |
| DTC P1507 on 1996MY-1999MY Legacy Vehicles .....                 | 04/04    |
| Updated Reprogramming Sheet.....                                 | 05/04    |
| ECM Reprogramming Fax Forms.....                                 | 09/04    |
| Freeze Frame Data.....   | 09/04    |
| Air Fuel Ratio Sensor Kits.....                                  | 12/04    |
| 2005MY & Reflashing.....   | 12/04    |
| DTC P0171 .....  | 04/05    |
| Updated Reprogramming Sheet.....                                 | 08/05    |
| DTC P0171 .....  | 09/05    |
| Freeze Frame Data & Calling the TechLine .....                   | 09/05    |
| ECU Reflashing .....   | 10/05    |
| DTC P0715 .....  | 10/05    |
| DTC P0171 – 2006MY H4 Legacy/Outback .....                       | 11/05    |
| Throttle Sensor and Tumble Generator Valve (TGV) Sensors.....    | 11/05    |
| DTC P2097 & Reflashing.....                                      | 01/06    |
| 3.0L Models: Fuel Requirements Revised.....                      | 02/06    |
| DTC P0400 Diagnosis .....  | 06/06    |
| DTC P1443 .....  | 08/06    |
| DTC's & Reflashing.....  | 09/06    |
| Clearing DTC's on 2005-2007MY SIA-Built Vehicles .....           | 02/07    |
| Diagnostic Help for Evaporative System Codes .....               | 04/07    |
| Reprogramming Reminder: Jumper Harness Connectors .....          | 05/07    |
| DTC P0457 .....  | 09/07    |
| DTC P1443 and the 2008 M/Y Impreza.....                          | 11/07    |
| Misfire Codes “Don't Forget To Check...” .....                   | 01/08    |
| Secondary Air Injection System Codes .....                       | 12/08    |
| WVH-18 & WVI-19 Service Program Information.....                 | 07/09    |
| “Rusty” Appearance of the Exhaust System .....                   | 05/10    |
| 2010 Legacy GT DTC P0171 .....                                   | 05/10    |
| TIPS on Inspecting DTC P0171 or P0172.....                       | 07/10    |
| New 2011 M/Y Forester Evaporative System Testing.....            | 12/10    |
| 2011 M/Y Forester: Sound From Under the Rear of the Car .....    | 04/11    |
| Rust Stains on Stainless Steel Exhaust Systems.....              | 06/11    |
| DTC P0457 Information .....                                      | 07/11    |



## 11-Emission Systems

|  |       |
|--|-------|
| 2011 M/Y Forester, DTC P2610 .....   | 10/11 |
| Troubleshooting DTC P0457 on 08 and Later Model Years .....                  | 02/13 |
| Getting to the Bottom of Extended Cranking.....                              | 03/13 |
| WQD-40 A Reminder .....  | 04/13 |
| Repeat 420 Codes on High Mileage vehicles.....                               | 08/13 |
| More Information on Stainless Steel Exhaust System Surface Rust.....         | 05/14 |
| Secondary Air Injection DTC's P2441 and P2442 .....                          | 07/15 |
| DTC P0171 Diagnostics.....   | 07/16 |
| ELCM (Evaporative Leak Check Control Module) Self Testing for Diagnosis..... | 03/17 |
| DTC P0171 Diagnostics.....   | 12/17 |
| DTC P1378- "Pre-Ignition Detected" – 2019MY Ascent.....                      | 07/18 |
| 2019MY Ascent: DTC P0606, Control Module Processor: Diagnostic Hints .....   | 10/18 |
| 2015MY Legacy/Outback Seat Heater Operation Overview.....                    | 12/18 |

## 12-Body, Glass, & Upholstery

### 12-Body, Glass, & Upholstery

|   |       |
|---|-------|
| Legacy Glove Box Rattling Noise .....                             | 05/91 |
| Wiper Blades .....  | 08/91 |
| Legacy Sunroof Shade Servicing .....                              | 10/91 |
| Legacy Wiper Blade Improvements .....                             | 10/91 |
| Legacy Wind Noise .....   | 03/92 |
| Legacy Modified Wiper Arms .....                                  | 03/92 |
| SVX Glass Replacement .....                                       | 04/92 |
| Legacy Upper Windshield Molding Loose .....                       | 05/92 |
| Door Glass Squeaks Going Up & Down .....                          | 11/92 |
| Windshield Wiper Maintenance Tips .....                           | 12/92 |
| 1992MY SVX Interior Noise Complaints .....                        | 08/93 |
| 1992MY SVX Sunroof sticking (Difficult to Open) .....             | 08/93 |
| Customer Complaints of Whistle Noises .....                       | 12/93 |
| Seat Belts .....  | 01/94 |
| 1993MY SIA Built Legacy, Headliner Droop .....                    | 03/94 |
| 1993MY Legacy SIA Built Legacy, Headliner Droop .....             | 04/94 |
| Legacy Trim Item Characteristics .....                            | 04/94 |
| Legacy Door/Ignition Key Code Location .....                      | 04/94 |
| Sunroof Water Leak Diagnosis .....                                | 05/94 |
| Keys Plates .....   | 10/94 |
| Door Lock/Linkage Inoperative .....                               | 11/94 |
| 1995MY Legacy Wagon Rear Cargo Anchors .....                      | 12/94 |
| 1995MY Legacy Power Door Locks .....                              | 12/94 |
| Foggy Film on Windows .....                                       | 12/94 |
| 1995MY Subaru Legacy "Fluttering" Noise .....                     | 08/95 |
| Subaru Outback Front License Plate Mounting Kit .....             | 10/95 |
| Winter Driving Tip, Interior Window Fogging .....                 | 01/96 |
| Foggy Film on Windows .....                                       | 01/96 |
| Legacy Wind Noise .....   | 02/96 |
| Water in the Rocker Panels .....                                  | 07/96 |
| Loose Bolts on Window Regulators .....                            | 09/96 |
| Poor Drainage from Rocker Panels: 1995/96MY Legacy Models .....   | 09/96 |
| '97MY Legacy Body Creaking Noise, RH Side Rocker Panel Area ..... | 02/97 |
| Proper Operation of Seat Belts, ELR vs. ALR .....                 | 08/97 |
| New Cup Holder For '98MY Legacy .....                             | 11/97 |
| Replacement Wiper Blade Refills .....                             | 09/98 |
| Improper Driver's Side Window Operation .....                     | 10/98 |
| 1999MY Impreza Wind Noise .....                                   | 01/99 |
| Bumper Cover Installation Tip .....                               | 02/99 |
| Front Seat Tracks .....   | 04/99 |
| 1999MY Forester Radio Antenna .....                               | 04/99 |
| Tether Anchor Points 1995 – 1999MY Legacy Sedan/SUS .....         | 07/99 |
| 2000MY Legacy Front License Plate Mounting .....                  | 09/99 |
| 2000MY Wiper Washer System .....                                  | 09/99 |
| Upholstery Items – Repair/Replace .....                           | 10/99 |
| Forester Tailgate Squeaks/Rattles/Popping .....                   | 11/99 |
| Metallic Window Tint Films .....                                  | 04/00 |
| Front License Plate Mounting For 2001MY Forester .....            | 04/00 |
| Wind Noise/Crossbar Installation .....                            | 08/00 |
| Inoperative Windshield Washers .....                              | 02/01 |

## 12-Body, Glass, & Upholstery

|  |          |
|--|----------|
| WRX Aluminum Hood Precaution .....   | 10/01    |
| 2002MY Impreza Sedan Trunk Lock Cylinder .....   | 01-02/02 |
| Windshield Wiper Washer Connection .....   | 11/02    |
| Sound Dampening Pad .....  | 04/03    |
| Adhesive Residue on Painted Surfaces .....   | 08/03    |
| Creaking Noise from Door Checker.....  | 08/03    |
| 2003MY Forester Washer Nozzles.....  | 09/03    |
| 2003-04MY Front Seatback Cover Reinstallation .....  | 11/03    |
| 2001-02MY Forester Sunroof Leak .....  | 11/03    |
| 2004MY Forester Rear Gate Damper Stay .....  | 11/03    |
| Striker Color Change .....   | 02/04    |
| 2003MY Forester: Water Leak from Roof Rail Clip.....                                       | 03/04    |
| Forester Bumper Fastener Bolt Change .....   | 03/04    |
| 2005MY Legacy Seat Belt Chime Activation .....   | 08/04    |
| Seatbelt Reminder System Disablement.....  | 08/04    |
| ODS Code 29 .....  | 09/04    |
| Frozen Wiper Blades .....  | 12/04    |
| Wiper Blades & Winter Weather .....  | 01/05    |
| 2005MY Legacy/Outback Moon Roof Sunshade Block & Rod Assembly.....                         | 02/05    |
| B9 Tribeca Front License Plate Mounting.....   | 04/05    |
| Wiper Blades & Visibility.....   | 06/05    |
| Adhesive Residue On '06MY Forester Rear Tailgate Garnish .....                             | 07/05    |
| Wind Noise Diagnosis .....   | 10/05    |
| VIN Plate Location Change .....  | 10/05    |
| Wiper Blades – The Basics .....  | 10/05    |
| 2006MY Impreza Tool Tray.....  | 10/05    |
| Front Washer Nozzle Does Not Spray Properly .....  | 01/06    |
| Ashtray Door Paint.....  | 04/06    |
| 2005MY Legacy Repair Procedure of Overhead Console when the Lid is Hard to Open/Close..... | 04/06    |
| 2003~05MY Forester Sunroof Squeaks .....   | 05/06    |
| 2004-2007MY Forester Sunroof Operation .....   | 09/06    |
| Baja Factory Installed “Hard” Bed Cover Replacement Keys.....                              | 12/06    |
| Forester Rear Gate Handle Binding .....  | 01/07    |
| B9 Tribeca Body “Popping-Type” Noise From the Right Front Strut Area.....                  | 01/07    |
| 2007 MY Legacy & Outback Overhead Console Door Binding .....                               | 04/07    |
| 2003-2008 MY Forester Sunroof Squeak.....  | 04/08    |
| 2009 MY Forester Side View Mirror Torque .....   | 05/08    |
| 2009 MY Forester Undercoated Wheel Wells .....   | 06/08    |
| Rear Wiper Blade Refill .....  | 05/07    |
| Impreza, Water in the Trunk.....   | 03/07    |
| 2008 M/Y Impreza, Rattling Noise from the Right Front.....                                 | 09/08    |
| 2009 Forester Buzzing or Rattling Noise from the Front Doors.....                          | 11/08    |
| Forester Sunroof Not Closing Properly.....   | 11/08    |
| Subaru Genuine Wiper Blade Inserts.....  | 01/09    |
| 2009 M/Y Impreza Rear Seat Updates .....   | 02/09    |
| 2009 M/Y Forester Rear Combination Lamps.....  | 03/09    |
| 2009 M/Y Forester Tailgate Grommet Removal .....   | 03/09    |
| 2009 M/Y Forester Rattling Noise from Rear of Head Liner.....                              | 04/09    |
| 2010 M/Y Legacy & Outback Power Lumbar Support Operation .....                             | 09/09    |
| 2008-09 M/Y Impreza, Rattling or Vibration Noise from Right Front.....                     | 09/09    |
| 2009-10 M/Y Forester Rear Gate Creek.....  | 11/09    |
| 2010 M/Y Outback Flapping or Fluttering Noise.....   | 11/09    |

## 12-Body, Glass, & Upholstery

|   |       |
|---|-------|
| 2009-10 M/Y Forester Rear Seat Rattle / Squeak .....  | 01/10 |
| Buzzing / Vibration Noises from Inside the Doors .....  | 12/09 |
| 2010 Legacy / Outback Rattle From Overhead Console Area.....  | 04/10 |
| Whistling Noise from Windshield Area at Highway Speed .....   | 05/10 |
| Slow or Erratic Door Glass Operation .....  | 05/10 |
| Stained Rocker Sill Moldings.....   | 11/10 |
| Forester and Impreza Rear Quarter Glass Moldings.....   | 01/11 |
| Bare Metal Visible in Tie-Down Areas of Undercarriage .....   | 04/11 |
| Popping or Creaking Sound from L/Rear, 2010 M/Y Forester .....  | 05/11 |
| Buzzing / Vibration Noises Inside the Doors, 2008 and Later Impreza .....   | 07/11 |
| Windshield Cracks on the Inside .....   | 07/11 |
| 2011 M/Y Forester, Rattling Noise from the Rear Roof Area.....  | 10/11 |
| Heat-Damaged Plastic Parts .....  | 10/11 |
| WVV-32 Campaign, Cowling Clip Removal Tips .....  | 10/11 |
| Windshield Cracks on the Inside, A Reminder .....   | 11/11 |
| 2010-11 M/Y Outback “Popping” or “Tick” Noise from the “B” Pillar Area .....  | 11/11 |
| 2012 Impreza Glove Box Light.....   | 07/12 |
| Cleaning Spotted Window Glass .....   | 07/12 |
| BRZ Rear Fold Down Seats .....  | 07/12 |
| BRZ Protective Sun Visor Cover .....  | 08/12 |
| A-Pillar Trim Tether Clips .....  | 08/12 |
| Impreza Rear Package Shelf Rattling Noise .....   | 09/12 |
| 2010 to 2012 Headliners .....   | 09/12 |
| Removal of protective film on side sill plate cover 13 BRZ .....  | 10/12 |
| 12 MY Tribeca Roof Rail.....  | 11/12 |
| 09-13 MY Forester Rear Seat Reclining Button.....   | 11/12 |
| 13 MY BRZ Rear Bumper Removal.....  | 11/12 |
| Windshield Cracks on the Inside (Reminder) .....  | 01/13 |
| WQA-37 Campaign (Special Pliers) .....  | 03/13 |
| Melting Plastic Parts .....   | 05/13 |
| BRZ Front Bumper Cover Removal Precautions .....  | 01/14 |
| 2014 Forester Power Rear Tailgate.....  | 04/14 |
| Whitish Discoloration/ Deposits on Front Door Panels, 12MY and Later Impreza and Cross trek .....                   | 06/14 |
| 2015 Legacy and Outback Seat Heater Overview.....   | 08/14 |
| 2015 Legacy/ Outback Center Console Compartment Door Information .....  | 09/14 |
| Design Change to the Zippers Used On Front Seat Backrest Covers.....  | 09/14 |
| Rattle Sound from Right Side of Dash Area .....   | 01/15 |
| Whitish Discoloration/ Deposits on Front Door Panels, 12MY and Later Impreza and Crosstrek<br>2015 WRX and STI..... | 01/15 |
| Fuel Door Freeze Up .....   | 04/15 |
| Erratic Washer Fluid Level Warning Lamp Illumination .....  | 09/15 |
| Glass Authorization Request-Additional photo required .....   | 11/15 |
| 2015 Legacy/ Outback, Rattling Sound from Front of Vehicle .....  | 12/15 |
| Interior Rear View Mirror Separation Reminder.....  | 07/16 |
| Water Draining from Body Panels .....   | 11/18 |
| Snowflake Type Damage to Glass.....   | 01/19 |
| Cleaning Spotted Window Glass .....   | 02/19 |

## 13-Paint

### 13-Paint

|  |       |
|--|-------|
| 3M Paint Polishing Assistance .....                                    | 03/92 |
| '95MY Legacy Outback Paint .....                                       | 01/95 |
| Correction to Service Bulletin 13-67-95r .....                         | 11/95 |
| Helpline Update .....  | 01/96 |
| Water Spotting On Painted Surfaces .....                               | 09/96 |
| Paint Procedures for Subaru Bumpers .....                              | 08/01 |
| Trim and Paint Code Update .....                                       | 04/04 |
| 2005MY Forester LL Bean Models Color Code Information Correction ..... | 11/04 |
| Paint Discoloration in Wheel Opening Areas.....                        | 10/09 |
| Finishing Plastic Parts .....  | 04/10 |
| XV Crosstrek Paint Schemes/Under Hood Insulator .....                  | 11/12 |
| Paint Condition on Hood – Moisture Stain.....                          | 12/18 |

## 14-Special Tools

### 14-Special Tools

|   |          |
|---|----------|
| Select Monitor Cartridge .....  | 10/91    |
| 4EAT Valve Body Servicing .....   | 12/91    |
| 4EAT Band Servo Servicing .....   | 12/91    |
| System Check Units for '85MY, '86MY, and '87MY .....                                    | 04/92    |
| SVX Select Monitor Cartridge .....  | 04/92    |
| Select Monitor Repair .....   | 08/92    |
| Air Conditioning Refrigerant Recycler .....   | 08/92    |
| Special Tools for Rear Wheel Bearing Replacement on Legacy All-Wheel Drive Models ..... | 09/92    |
| Select Monitor Cartridge Application Chart .....  | 11/93    |
| Transmission Pressure Gauge Set .....   | 03/94    |
| Select Monitor Repair .....   | 11/96    |
| Subaru New Select Monitor Repairs .....   | 07/99    |
| 2001MY Subaru Forester select monitor cartridge .....                                   | 02/00    |
| New Select Monitor Repairs – An Update .....  | 11/00    |
| New Select Monitor Cartridge .....  | 01/01    |
| Subaru Fuel Injector Cleaner Tool .....   | 05/01    |
| Select Monitor Cables .....   | 10/01    |
| Select Monitor Image Loader Software/Hardware.....                                      | 03-04/02 |
| Oxygen Sensor Removing Tool.....  | 01-02/03 |
| 2003MY Impreza Select Monitor Cartridge Application.....                                | 01-02/03 |
| Select Monitor Repairs – An Update .....  | 10/03    |
| 2005MY Legacy/Outback Key Cutter .....  | 10/04    |
| Kent-Moore Website .....  | 11/04    |
| Select Monitor Repairs: Latest Information.....   | 03/05    |
| SDS (Subaru Diagnostic System) & Mode Files.....  | 02/06    |
| SDS Kit & Pre-Testing Your Subaru Select Monitor III.....                               | 03/06    |
| Subaru Select Monitor III & CID Numbers.....  | 03/06    |
| Updated Repair Center Phone Number for Kent-Moore.....                                  | 06/06    |
| New Menu Prompts When Calling the SDS Technical Support Helpline .....                  | 07/06    |
| Mid-Tronics EXP-1000 .....  | 08/06    |
| New Special Tool Kit SOA321064 Sent To All Subaru Dealers .....                         | 10/06    |
| Front Fender Insulator for WRX and STI (Excluding STI Limited) .....                    | 12/06    |
| Latest SSMIII Software Download Version.....  | 03/08    |
| Re-Booting Your SDS Notebook .....  | 04/08    |
| Latest SSMIII Software Download Version.....  | 06/08    |
| SDS Notebook (CF-18) Helpful Hints.....   | 07/08    |
| Latest SSM III Software Version Download.....   | 09/08    |
| Legacy / Outback M/T High Idle Re-Flash Clarification .....                             | 10/08    |
| SSM III Pulse / Analog Kit (Oscilloscope) Information .....                             | 10/08    |
| Issues with Using SMART (Subaru LMS System) .....                                       | 11/08    |
| Replacement Cables For Subaru Diagnostic System (SDS) .....                             | 03/09    |
| Fuel Alcohol Tester .....   | 04/09    |
| Fuel Pressure Tester Warning from SPX .....   | 09/09    |
| Select Monitor (SDS) Issues with Campaign WVM-23.....                                   | 12/09    |
| Important Engine Support Bracket Return Information.....                                | 04/10    |
| SDS Printer Problem... Who You Gonna' Call? .....                                       | 06/10    |
| Techline Pre-Call Worksheets .....  | 08/10    |
| CF-U1 Reprogramming Kit Monitor Use.....  | 07/11    |
| Flashwrite Error Code 4404.....   | 08/11    |
| Power Steering Rack Service Tool Information .....                                      | 09/11    |
| Using the Service-Techline Reporting Feature on Subarunet .....                         | 09/11    |

## 14-Special Tools

|   |       |
|---|-------|
| Body Repair Manual User Information .....                             | 11/11 |
| 2012 Impreza Special Tool Shipments .....                             | 12/11 |
| New Snap-On Ball Joint Remover Instructions .....                     | 04/12 |
| Connecting Rod Bolts on FA and FB Engines.....                        | 09/12 |
| Printing Freeze Frame Data.....                                       | 09/12 |
| Special Tools For The BRZ .....                                       | 09/12 |
| Engine Bridge Replacement Parts .....                                 | 11/12 |
| Test Harness Probes .....   | 12/12 |
| Using Your Oscilloscope.....  | 12/12 |
| SDI Interface Box and Self Shut Timer.....                            | 01/13 |
| 14MY Forester SSM3 Operation.....                                     | 01/13 |
| SSM3 Unit Of Measurement.....   | 08/13 |
| Subaru Special Tools Website URL Update .....                         | 01/14 |
| GR-8 Battery Testing Information .....                                | 03/14 |
| New SSM4 software on the C2 Toughbook.....                            | 06/15 |
| Recommendations for use of the Denso DST-I diagnostic interface ..... | 09/15 |
| Stopper Tool for CVT and Automatic Transmissions .....                | 11/15 |
| April 2016 SSM4 Changes .....   | 04/16 |
| Precautions When Using the DST-I Box.....                             | 08/16 |
| New Function SSM4 October Version .....                               | 11/16 |
| SSM3? SSM4? Generic? What Diagnostic Scan Tool Should I Use? .....    | 04/17 |
| New Special Tool – Relay Pliers.....                                  | 02/18 |

## 15-Accessories

|   |       |
|---|-------|
| Radio Display Interruption with Brake Pedal Application .....                                     | 05/91 |
| Justy Radio Display Fade .....  | 07/91 |
| SVX Security System .....   | 10/91 |
| Legacy, Noise Heard Through Speakers When the Illumination Control Is Varied, Clarion Radio ..... | 10/91 |
| Quick Cruise Control Check .....  | 12/91 |
| SVX Radio Servicing .....   | 12/91 |
| SVX Security System .....   | 01/92 |
| SVX Compact Disc Player .....   | 02/92 |
| SVX Security System Warning .....   | 02/92 |
| Legacy Cruise Control Installation .....  | 03/92 |
| Loyale Cruise Control for 92MY .....  | 03/92 |
| L-Series Poor Radio Reception .....   | 03/92 |
| L-Series Clarion 10 Watt ETR and Panasonic Elite LC Cassette Deck Incompatibility .....           | 03/92 |
| Radio/Cassette/CD Exchange Or Out Of Warranty Repair Programs .....                               | 04/92 |
| Accessory Cruise Control Installation in Rural RHD Legacy Postal Models .....                     | 04/92 |
| Legacy Security System Wiring Information .....   | 04/92 |
| 1992MY Legacy Cruise Control Installation .....   | 06/92 |
| Loyale SOA386C110 Cruise Control Installation Tips .....  | 06/92 |
| Legacy Station Wagon "LS" Power Antenna .....   | 07/92 |
| Legacy Security System Installation 1991MY to Present Station Wagon Models .....                  | 07/92 |
| Loyale (SOA386C110) Cruise Control Installation Tips Correction .....                             | 07/92 |
| Tips for Installing Security System SOA386R100 in A 1992MY Loyale .....                           | 03/93 |
| Impreza IAC Formerly Called FICD Adjustment .....   | 04/93 |
| SVX Audio Assembly Removal .....  | 06/93 |
| 1993MY SVX New Security System Installation Tips .....  | 08/93 |
| Legacy Panasonic 80 Watt Radio Noise in Speakers .....  | 08/93 |
| Poor Radio Reception AM or FM .....   | 10/93 |
| Legacy & SVX Security System Transmitter Battery Servicing .....                                  | 10/93 |
| SVX New Security System Programming Tips .....  | 10/93 |
| SVX Rear Speakers Buzzing .....   | 01/94 |
| 1995MY Legacy Security System .....   | 07/94 |
| 1995MY Legacy LSI Security System .....   | 09/94 |
| Accessory Block Heaters .....   | 10/94 |
| 1990MY-1994MY Legacy Security System Operation Q&A .....  | 10/94 |
| Installing 1995MY Legacy Roof Racks .....   | 11/94 |
| Impreza Accessory .....   | 01/95 |
| Hubcaps .....   | 01/95 |
| Accessory "Outback" Wheel Covers .....  | 03/95 |
| 1995MY Subaru Legacy Front End Cover (Bra) .....  | 03/95 |
| Installing Impreza Fog Lamp Kits .....  | 03/95 |
| Cruise Control & the Use of the Select Monitor .....  | 04/95 |
| 1995MY Legacy Cruise Control Corrections .....  | 04/95 |
| 1995MY Legacy LSI Security System Module I/O Chart .....  | 04/95 |
| 1995MY Legacy S/W Accessory Fork Mount Bike Carrier .....   | 05/95 |
| Impreza Foglight Installation .....   | 05/95 |
| Radio Noise .....   | 06/95 |
| 1995MY Subaru Legacy LSI Alarm System .....   | 06/95 |
| 1995 Subaru Legacy Cruise Control .....   | 06/95 |
| Testing Cruise Control Pumps .....  | 09/95 |
| Installation of Subaru Impreza 'LX' S/W Rear Spoiler .....  | 09/95 |



## 15-Accessories

|  |       |
|--|-------|
| 1995MY Subaru Legacy with Panasonic Radios .....   | 11/95 |
| 1995MY/1996MY Subaru Impreza & Legacy Cruise Control Applications .....  | 11/95 |
| Alloy Wheel Center Caps .....  | 12/95 |
| Impreza Fog Lamp Kit P. N. H4510FA100 Fuse Location & Wiring Changes For '96MY .....                                       | 12/95 |
| Outback Trailer Hitch Part Number L1010AS000 Change In Torque Spec. ....   | 12/95 |
| Cruise Control for 2.2 Liter '96 MY Impreza Manual Trans. Vehicles .....   | 12/95 |
| Cruise Control for Newer Legacy Models .....   | 12/95 |
| Legacy Remote Keyless Entry System .....   | 12/95 |
| Legacy Keyless Entry Diagnosis .....   | 01/96 |
| Legacy Accessory Keyless Entry System .....  | 01/96 |
| Legacy Roof Rack Installation Information .....  | 02/96 |
| Installation Instruction Supplement For '96MY Impreza Foglamp Kit #H4510FA100 .....  | 04/96 |
| Interior Lights Stay On When Leaving the Car .....   | 04/96 |
| 1995MY & Up Legacy LSI Keyless Remote System .....   | 04/96 |
| Keyless Entry Erratic Transmitter Operation .....  | 05/96 |
| Modification to Keyless Entry System Instructions .....  | 05/96 |
| Revised 1996 1/2MY and 1997MY Legacy Cruise Control Supplemental Installation Instructions .....                           | 07/96 |
| 1995 & 1996MY Subaru Legacy W/Power Antenna .....  | 08/96 |
| 1997 Legacy Keyless Entry .....  | 08/96 |
| Legacy Outback Trailer Hitch Harness .....   | 08/96 |
| Legacy Outback Crossbar Installation Tips .....  | 08/96 |
| Legacy LSI Security System .....   | 10/96 |
| 1996MY Impreza Accessory Keyless Entry Kit H7110FS000 .....  | 01/97 |
| 1997MY Impreza Accessory Cruise Control .....  | 01/97 |
| Outback Roof Rack Crossbar Bolt Part Number Correction .....   | 01/97 |
| Legacy Subwoofer/Preamp, P/N H6300AS030 .....  | 02/97 |
| Legacy Outback Trailer Hitch Wiring Harness .....  | 02/97 |
| Legacy Keyless Entry with Security Upgrade .....   | 02/97 |
| Correction to Installation Instructions for Keyless Entry Kits H7110AS000 & H7110AS300 For<br>1995MY & 1996MY Legacy ..... | 02/97 |
| 1997MY Impreza Keyless Entry Kit H7110FS000 with Incorrect Wiring Harness .....  | 02/97 |
| 1997MY Legacy Keyless Entry/ Security System Programming Button Locations .....  | 02/97 |
| 1997MY Legacy Keyless Entry & Security Upgrade Modifications .....   | 03/97 |
| Legacy Keyless Entry/ Security System Upgrade .....  | 04/97 |
| 1997MY Impreza Foglamp Installation Tips For Kit #H4510FA200 .....   | 05/97 |
| 1997MY Legacy; Programming Replacement Keyless Entry Control Unit .....  | 07/97 |
| New CD Changer Installation Procedures .....   | 08/97 |
| Forester Removable Antenna .....   | 09/97 |
| 1996MY Subaru Legacy Keyless Entry System Not Operating Correctly .....  | 09/97 |
| Subaru Keyless Entry Batteries .....   | 09/97 |
| Accessory Gauge Pack Information .....   | 10/97 |
| 1998MY Forester Keyless Entry System Information .....   | 10/97 |
| 1998MY Impreza Cruise Control Connector .....  | 01/98 |
| Keyless Entry System Operation .....   | 01/98 |
| Forester Accessory Brush Guard .....   | 01/98 |
| 1998 Impreza Foglight Kit #H4510FA200 .....  | 02/98 |
| 1998 Subaru Forester Power Mirror Kit .....  | 03/98 |
| Update of Keyless Entry Bulk Head Harness Change .....   | 04/98 |
| Keyless Entry/Alarm System Upgrade .....   | 04/98 |
| 1998MY Impreza Foglight Kit #H4510FA200/220 Correction .....   | 04/98 |
| Subaru Keyless Entry/ Security System Reference Guide .....  | 04/98 |
| Subaru Accessory Installation Manual .....   | 04/98 |

## 15-Accessories

|   |          |
|---|----------|
| Programming SVX Alarm Systems .....   | 04/98    |
| 1998MY Subaru Forester Power Mirror Kit P/N Correction .....                          | 05/98    |
| Legacy Station Wagon Audio Harness .....  | 05/98    |
| Accessory Operator Instructions for 1999MY .....                                      | 07/98    |
| 1999MY Legacy Accessory Changes and Corrections .....                                 | 07/98    |
| Rear Differential Protector .....   | 08/98    |
| Poor AM Radio Reception on Forester Vehicles .....                                    | 10/98    |
| 1999MY Legacy Accessory Cruise Control .....  | 11/98    |
| Keyless Entry/ Security System Transmitter Batteries .....                            | 01/99    |
| 1999MY Cal. Spec. Impreza Security Kit Availability .....                             | 01/99    |
| Shock Sensor Mounting for Forester/Impreza with Security Upgrade .....                | 01/99    |
| Keyless Entry into 1999MY Forester Vehicles with 'All Weather Package' .....          | 01/99    |
| Keyless and Security System Quality Improvements .....                                | 01/99    |
| 1999MY Forester Radio Noise/Poor Reception .....                                      | 04/99    |
| 1999MY Forester – Clicking Noise from Right Front Speaker .....                       | 05/99    |
| Alpine Keyless Entry with Security Upgrade System Operation Reminder .....            | 07/99    |
| Lighted Mirror Sunvisor Replacement Bulbs .....                                       | 08/99    |
| No Radio Volume – 2000MY Legacy Limited Model Wagons .....                            | 08/99    |
| 1999MY/2000MY Legacy Alpine Keyless Entry/ Security System Dome Light Operation ..... | 10/99    |
| Trailer Hitch Bike Attachment .....   | 11/99    |
| 2000MY Legacy Rear Spoiler .....  | 11/99    |
| Auto Dimming Mirror/Compass.....  | 01/00    |
| Rear Gate Bar P/N E7510IS001 2000MY Legacy Wagons .....                               | 05/00    |
| Compass Mirror 2000MY Legacy & 2001MY Forester .....                                  | 05/00    |
| Electrochromic Compass Mirror .....   | 05/00    |
| Accessory Installation Instructions on Web.....                                       | 05/00    |
| CD Player/Changer Visual Reference .....  | 05/00    |
| Performance Gauge Pack Operation .....  | 05/00    |
| 2000MY Legacy/Outback Hood Deflector 'W' Clips Installation.....                      | 07/00    |
| Replacing a Keyless Entry Transmitter Battery .....                                   | 08/00    |
| 2001MY Forester Front Splash Guard Installation (P/N J1010FC000).....                 | 08/00    |
| Accessory Block Heaters .....   | 10/00    |
| Internal Trunk Release Handle .....   | 01/01    |
| 2002MY Impreza Accessory Application – Compass Mirror .....                           | 03/01    |
| 2002MY Impreza Trailer Hitch P/N I1010SS000 .....                                     | 03/01    |
| 2002MY WRX/Impreza TechTIPS Special Edition .....                                     | 03/01    |
| Cross Bar Positioning .....   | 05/01    |
| Short Throw Shifter .....   | 05/01    |
| Accessory Updates .....   | 07/01    |
| Titanium Shift Knob (P/N C1010FA100) Shift Emblem Location.....                       | 09/01    |
| WRX Performance Gauge Pack.....   | 10/01    |
| Impreza Sedan Spoiler Installation Tips .....   | 10/01    |
| Forester Splash Guard Installation Tips .....   | 10/01    |
| WRX Steering Column Mounted Boost Gauge .....   | 11/01    |
| 2002MY Impreza Subwoofer/Amplifier Compatibility.....                                 | 11/01    |
| 2002MY Impreza Front Under-Spoiler Installation Change .....                          | 11-02/02 |
| 2002MY WRX Front End Cover.....   | 01-02/02 |
| 2002MY Impreza 120 Watt Subwoofer Bracket Change .....                                | 01-02/02 |
| EC Compass Mirror Calibration.....  | 03-04/02 |
| BAJA Bed Extender.....  | 09-10/02 |
| Seat Heater Information.....  | 03/03    |
| New Baja & Legacy Hood Deflector Installation .....                                   | 03/03    |

## 15-Accessories

|  |       |
|--|-------|
| Impreza Sedan Spoiler Changes.....   | 05/03 |
| Baja Bed Cover Replacement .....   | 05/03 |
| STI Security Module Torque Specifications.....                             | 07/03 |
| Bumper Beam Plug for Baja Trailer Hitch .....                              | 07/03 |
| 2004MY Forester Hood Deflector/Protector .....                             | 08/03 |
| Tonneau Cover Replacement Parts For Legacy 00MY~03MY .....                 | 08/03 |
| 2004MY STI Single Turbo Gauge Installation/Intercooler Removal .....       | 08/03 |
| Revised Electronic Control Compass Mirror.....                             | 08/03 |
| 2004MY Forester Single Turbo Gauge Installation/Interior Trim Removal..... | 08/03 |
| WRX STI Audio System .....   | 08/03 |
| WRX Performance Suspension Kit (STI).....                                  | 09/03 |
| Baja Sport Activity Lights.....  | 09/03 |
| Baja Sport Activity Lights - Relay Location.....                           | 01/04 |
| Forester Crossbar Design Revision.....                                     | 01/04 |
| Baja Bed Cover Replacement (Reprint from May 2003).....                    | 01/04 |
| Poor Radio Reception .....   | 02/04 |
| Baja Sport Activity Lights – Relay Location – Correction .....             | 02/04 |
| What’s That Noise? .....   | 04/04 |
| Poor Radio Reminder .....  | 04/04 |
| Cruise Control Actuator .....  | 04/04 |
| Trailer Hitch Installation .....   | 07/04 |
| '05MY Sedan Spoiler Template .....   | 07/04 |
| '05MY Splash Guard Tape Area.....  | 07/04 |
| '05MY Cargo Net Anchors.....   | 07/04 |
| '05MY Legacy & Outback Hood Protector Mounting Points .....                | 07/04 |
| 2005MY Legacy and Outback Crossbar Positioning .....                       | 07/04 |
| EC Compass Mirror Mounting .....   | 07/04 |
| 2005MY Legacy & Outback Ambient Temperature Sensor .....                   | 07/04 |
| Subwoofer .....  | 07/04 |
| Rear Cargo Net Pre-Arranged Drill Marks.....                               | 07/04 |
| Trailer Hitch Installation .....   | 07/04 |
| Impact Sensor (Shock Sensor) Activation .....                              | 07/04 |
| Impact Sensor (Shock Sensor) Location .....                                | 07/04 |
| 2005MY Legacy/Outback H-4 & H-6 Model Relay Location .....                 | 07/04 |
| Sedan Spoiler Tether Location .....  | 07/04 |
| 2005MY Key and Remote Transmitter New Vehicle Check-In Procedure .....     | 08/04 |
| Non-Aero Cross Bar Kit.....  | 09/04 |
| Sub-Woofer Wiring Harness Re-Routing.....                                  | 11/04 |
| Engine Block Heaters .....   | 11/04 |
| Immobilizer Information .....  | 12/04 |
| Immobilizer Registration & Cell Phones .....                               | 12/04 |
| 2005MY Legacy Air Filtration Retrofit Kit.....                             | 04/05 |
| Don't Get Alarmed .....  | 05/05 |
| Keyless Remotes.....   | 06/05 |
| 2005MY Legacy & Outback Air Filter Installation .....                      | 07/05 |
| Navigation Screen Removal for Subaru B9 Tribeca .....                      | 07/05 |
| B9 Tribeca Special Edition 2005 (Accessory Information).....               | 07/05 |
| Immobilizer Security Codes.....  | 08/05 |
| False Shock Sensor Activation.....   | 08/05 |
| B9 Tribeca False Alarm Activation.....                                     | 10/05 |
| 2006MY Legacy/Outback Impact Sensor Installation.....                      | 11/05 |
| EC Mirror Configuration & Application.....                                 | 01/06 |

## 15-Accessories

|   |       |
|---|-------|
| Auto-Dimming Compass Mirror (P/N H501SAG100).....                           | 03/06 |
| 2006MY Forester Impact Sensor Adjustment.....                               | 03/06 |
| Forester Crossbar Noise.....  | 04/06 |
| Keyless Entry Remote Inoperative .....                                      | 05/06 |
| Navigation Display Illumination in Cold Weather .....                       | 05/06 |
| 2006 Immobilizer Component Replacement Guide.....                           | 07/06 |
| XM Satellite Radio Installation Instructions.....                           | 08/06 |
| Immobilizer Code Requests .....   | 11/06 |
| “Teaching Codes” With an Immobilizer System.....                            | 11/06 |
| Special 2007MY Issue: B9 Tribeca Accessories .....                          | 12/06 |
| XM Satellite Radio “Re-Pinging”.....  | 01/07 |
| Horn Beeps Erratically When Using RES System.....                           | 01/07 |
| NAV System Software Update Availability.....                                | 03/07 |
| Immobilizer Programming & RES Parts Information.....                        | 03/07 |
| Immobilizer Interface Programming.....                                      | 03/07 |
| Remote Engine Start System- Start Attempt Failure .....                     | 04/07 |
| OnStar Analog System Phase-Out Information.....                             | 05/07 |
| 2007-08 MY Remote Engine Start Information.....                             | 07/07 |
| Remote Engine Start Programming Problems .....                              | 08/07 |
| Sirius Satellite Radio Diagnostic Flow Chart .....                          | 08/07 |
| 2008 MY Impreza Outback Sport & 5-Door Roof Rack Accessory Cross Bars ..... | 09/07 |
| NAV / Aftermarket RES System Interference .....                             | 09/07 |
| Satellite Radio Diagnosis Quick TIP.....                                    | 09/07 |
| Immobilizer “Invalid Teaching Code” Message.....                            | 10/07 |
| 2008 M/Y Impreza Accessory TIPS .....                                       | 10/07 |
| Understanding the Security System Indicator Light.....                      | 11/07 |
| RES System “Quick TIPS”.....  | 12/07 |
| More Immobilizer Helpful Hints.....   | 01/08 |
| Tribeca Crossbar Rattling Noise.....  | 01/08 |
| Erratic Horn Operation.....   | 02/08 |
| Audio System Upgrades: XM / Sirius / iPod Interface .....                   | 03/08 |
| Important Information Regarding The iPod Interface .....                    | 03/08 |
| RES Troubleshooting Guides .....  | 03/08 |
| Dealer Accessibility to Immobilizer Security and Key Codes .....            | 04/08 |
| 2009 MY Forester Accessory Installation TIPS .....                          | 05/08 |
| Impreza Shock Sensor Installation .....                                     | 07/08 |
| Immobilizer Teaching Codes, 2005-09, Breaking the Code .....                | 07/08 |
| Remote Engine Start Troubleshooting Guides .....                            | 08/08 |
| 2009 M/Y Forester Wheel Arch Molding Installation Guide.....                | 08/08 |
| 2009 M/Y Forester Puddle Light Connectors .....                             | 09/08 |
| Quick Tip: Hands-Free Installation, 2009 M/y Forester & Impreza.....        | 09/08 |
| Are You NOT Hearing Voices? .....   | 09/08 |
| Reminder: RES Kits Are Not Interchangeable.....                             | 10/08 |
| 2009 M/Y Forester Trailer Hitch / Arch Molding Information.....             | 10/08 |
| iPod Interface Information, 2008-09 MY Impreza & 2009 M/Y Forester .....    | 11/08 |
| Immobilizer Code / Subaru Lock Info Site (SLIS) Information.....            | 11/08 |
| 2009 Forester Satellite Radio-Equipped Tuner Clarification.....             | 11/08 |
| iPod Interface Charging Information.....                                    | 12/08 |
| Back-Up Sensor False Alarms, 2008-09 Tribeca .....                          | 12/08 |
| Low Speaker Volume, 2008 M/Y & Later Impreza & Forester.....                | 12/08 |
| Accessory Bluetooth “No Caller ID” Message .....                            | 02/09 |
| Audio / NAV Unit Removal Precautions.....                                   | 03/09 |

## 15-Accessories

|   |       |
|---|-------|
| RES Antenna Ring Replacement Information .....                                  | 04/09 |
| 2008-09 M/Y Impreza & 2009 M/Y Forester Wind Noise When Using Ski Carrier ..... | 04/09 |
| Revised Impreza Roof Rack Crossbar .....  | 05/09 |
| 2010 M/Y Legacy & Outback Keyless Entry Inoperative .....                       | 07/09 |
| 2010 M/Y Legacy & Outback Denso A/C Compressor Warning .....                    | 08/09 |
| iPod Charging Information .....   | 08/09 |
| 2010 M/Y STI Satellite Radio Information.....                                   | 09/09 |
| 2010 M/Y Legacy & Outback RES Reminders .....                                   | 09/09 |
| 2010 M/Y Tribeca Radio Removal w/ Center Dash Speaker .....                     | 10/09 |
| 2010 M/Y Tribeca Back-Up Sensor Kit Applicability .....                         | 11/09 |
| 2010 M/Y Legacy Sedan Erratic Alarm Activation .....                            | 11/09 |
| Navigation Discs, There IS A Difference! .....                                  | 12/09 |
| Teaching Codes... A Reminder .....  | 01/10 |
| Remote Engine Start Programming.....  | 01/10 |
| Remote Keyless Entry Fob Supersession .....                                     | 02/10 |
| 2.5L Accessory Block Heater Installation Precaution .....                       | 03/10 |
| 2007 - 09 RES Performance Issues in Cold Weather .....                          | 03/10 |
| Electrical Problem? Check That Compass Mirror Harness .....                     | 03/10 |
| 2001 – 04H6 A/C Compressor Short-Cycling Reminder .....                         | 04/10 |
| Keyless Entry Inoperative After Starting Engine with RES .....                  | 04/10 |
| Decreased Radio Volume in Reverse.....  | 05/10 |
| Satellite Radio Artist / Song Information Not Scrolling.....                    | 05/10 |
| Helpful Bluetooth Information and FAQ's.....                                    | 06/10 |
| 2011 M/Y Legacy / Outback Bluetooth Microphone Inoperative.....                 | 07/10 |
| Excessive A/C Pressures .....   | 07/10 |
| Remote Engine Start (RES) Troubleshooting Reminder.....                         | 07/10 |
| 2009 – 10 Forester 6 CD Changer Audio Unit Information .....                    | 07/10 |
| No or Reduced Sound from Rear Speaker Concerns .....                            | 08/10 |
| Thule Cargo Box Replacement Keys and Lock Cylinders .....                       | 08/10 |
| 2010 – 11 M/Y Outback Rocker Trim Removal.....                                  | 08/10 |
| RES Service Kit Reminders .....   | 09/10 |
| 2011 M/Y Impreza Bluetooth / Subwoofer Interference .....                       | 09/10 |
| Mobile Internet Installation Information.....                                   | 09/10 |
| Media Hub Installation Reminder .....   | 09/10 |
| TomTom Navigation System Information .....                                      | 11/10 |
| Deformed Cargo Mats .....   | 11/10 |
| 2011 M/Y Forester Block Heater Installation Instruction Change .....            | 12/10 |
| Navigation “Hard Keys” Flashing / Screen Issues .....                           | 12/10 |
| RES System Key / Remote Registration Information.....                           | 12/10 |
| Kenwood Navigation System Troubleshooting Guide Released.....                   | 12/10 |
| Aftermarket GPS Signal Interference Issues.....                                 | 12/10 |
| 2011 Legacy / Outback Revised Dash Speaker Grilles .....                        | 01/11 |
| Sunroof Motor Replacement Precaution.....                                       | 01/11 |
| Updated RES and TomTom Troubleshooting Guides .....                             | 01/11 |
| Updated Subwoofer Harness Now Available .....                                   | 02/11 |
| 2011 M/Y Outback Compass Mirror “Lock-Up”.....                                  | 02/11 |
| No sound Heard When Using Bluetooth.....  | 03/11 |
| No Sound Output from the Audio Unit.....  | 04/11 |
| Crackling Sound from the Speakers w/ Key off .....                              | 04/11 |
| Radio Volume Changes by Itself While Driving .....                              | 04/11 |
| iPod Scrolling With TomTom Audio System.....                                    | 05/11 |
| Block Heaters and DTC P0126.....  | 05/11 |

## 15-Accessories

|   |       |
|---|-------|
| Panasonic Audio Unit Exchange Procedure Change .....  | 06/11 |
| Tribeca Rear A/C Inoperative or Poor Performance .....  | 07/11 |
| Rattling Noise from Right Side of Engine .....  | 07/11 |
| Troubleshooting Guides on STIS.....   | 07/11 |
| 2011 M/Y Impreza, Crank / No Start, Security Light Flashing .....   | 08/11 |
| Bluetooth Connection Concern, Can You Hear Me Now? .....  | 09/11 |
| Bumper Corner Molding Installation Information .....  | 09/11 |
| Blank or “White Screen” Navigation Display.....   | 09/11 |
| Use of Aftermarket Engine Under-Covers .....  | 11/11 |
| Engine Block Heaters and DTC P0126 (Updated) .....  | 11/11 |
| 2012 M/Y Impreza Immobilizer Changes.....   | 01/12 |
| 2010-11 M/Y Legacy / Outback Bluetooth Inoperative.....   | 01/12 |
| 2012 M/Y Impreza Audio Unit Exchange Information.....   | 01/12 |
| 2012 M/Y Impreza Remote Engine Start Programming Information.....   | 01/12 |
| Rear Seat Entertainment Troubleshooting and User Guides.....  | 02/12 |
| 2010 and Later (Non-Interface) RES Diagnosis, Don’t Overlook This Step.....                                 | 02/12 |
| 2012 M/Y Impreza RES Key Fob Flashing .....   | 03/12 |
| Fujitsu-Ten Navigation Units and SD Cards- Important Information .....                                      | 04/12 |
| 2010-12 M/Y Outback Cargo Mat Precaution .....  | 04/12 |
| Revised Home-Link Mounting Adapter.....   | 04/12 |
| Fujitsu-Ten Navigation Screen Display .....   | 05/12 |
| 2013 BRZ Antitheft Security/Alarm System Activation.....  | 07/12 |
| Push Button Start Vehicles Equipped With Remote Engine Start.....   | 09/12 |
| Accessories and Eyesight .....  | 10/12 |
| 2013 Smart Engine Start .....   | 10/12 |
| Resources For XM Traffic Inquiries/Concerns.....  | 11/12 |
| Bluetooth Information .....   | 12/12 |
| 13MY Legacy/Outback Navigation Volume Adjustment.....   | 01/13 |
| Wheel Locks.....  | 01/13 |
| Voice Clarity .....   | 03/13 |
| F-10 Diagnostics .....  | 03/13 |
| Voice Recognition .....   | 03/13 |
| 2014 Forester and 2013 Legacy Keyless Access and Keyless Entry .....  | 05/13 |
| Navigation Voice Guidance .....   | 05/13 |
| 2014 Forester Speaker Kit Installation.....   | 05/13 |
| F-10 Audio/Navigation Units-No power or Display.....  | 08/13 |
| Major RES (Remote Engine Start) Differences 2007 to 2014.....   | 09/13 |
| HomeLink Mirror Programming Information.....  | 01/14 |
| 2010-14 Outback Rear Bumper Under guard Accessory Reminder.....   | 03/14 |
| 2015 Legacy and Outback Keyless Entry Audible Signal Feature.....   | 08/14 |
| 2015 Legacy/Outback XM Reverting to Preview Channel .....   | 11/14 |
| 2015 Legacy/Outback, Starlink , iHeart Radio Application Information .....                                  | 12/14 |
| Damaged USB Ports .....   | 02/15 |
| Selectable Run Time for 2015 Remote Engine Start.....   | 03/15 |
| Remote Engine Start (RES) Inoperative, No Response from Remote on Push-Button<br>(Smart) Start Models ..... | 05/15 |
| Use of Aftermarket Accessory Engine/Fuel Economy Monitors .....   | 07/15 |
| Subaru STARLINK telematics Retailer PDI Process .....   | 08/15 |
| Gen 1 F10 Navigation System-Red Light Alert Function .....  | 08/15 |
| 2015MY Legacy & Outback, GPS Signal Loss w/F10 Navigation System.....                                       | 10/15 |
| Accessory Floor Mat Reminders and Precautions .....   | 11/15 |
| Accessory Bumper Cover/Installation Tips and Best Practices.....  | 11/15 |

## 15-Accessories

|   |       |
|---|-------|
| Identifying Fujitsu-Ten Navigation Units.....   | 11/15 |
| New F-10 Gen 2.1 Audio/Navigation System and Siri.....  | 11/15 |
| Why Do My Outside Mirror Approach Lights Appear Green.....  | 01/16 |
| Accessory Door Edge Guard Removal Process.....  | 03/16 |
| Bluetooth Operation and Diagnosis.....  | 04/16 |
| Clarion Audio Units and Audiobook CD's.....   | 04/16 |
| Audio/ Navigation Head Unit Quick Reference Information.....  | 04/16 |
| 2013 WRX or STI Special Edition Graphics.....   | 05/16 |
| Door Edge Guards / Installation Tips and Best Practices.....  | 05/16 |
| Auto Dimming and Home Link Accessory Mirror Wiring Harness Troubleshooting Reminder.....                | 07/16 |
| Microphone Not Working? Check the Telematics System.....  | 07/16 |
| 2017 Forester Telematics Fuse Change Information.....   | 09/16 |
| Keyless Access with Push Button Start Vehicles-Erratic Beeping When Entering the Vehicle.....           | 09/16 |
| Long Range Remote Start FAQ.....  | 09/16 |
| RES Inoperative? Check the RES Antenna.....   | 11/16 |
| Display Audio (Non Navigation) Clock Not Synchronized.....  | 12/16 |
| No Back Up Camera After Radio Removal.....  | 12/16 |
| Clock Settings.....   | 12/16 |
| 2017 Auto-Dimming Outside Mirror Limited Movement.....  | 01/17 |
| 2017MY Forester Wheel Arch Molding Installation.....  | 01/17 |
| 2017 MY Impreza, Remote Engine Start (RES) Remote Fob Registration Tips.....                            | 02/17 |
| RES Hood Switch.....  | 02/17 |
| 2017MY Impreza Audio Unit Stays Powered Up After Key Off ... Or Does It?.....                           | 02/17 |
| 2017 MY Impreza Remote Engine Start (RES) Time-out Function.....  | 02/17 |
| 2017MY Impreza- Serial Numbers On Gen 3 Harman Audio Units.....   | 03/17 |
| 2017MY Impreza Key Start RES Tips.....  | 03/17 |
| Bluetooth Concerns?.....  | 05/17 |
| Does this Accessory work with this car?.....  | 05/17 |
| LED Lighting.....   | 06/17 |
| Combination Meter Replacement.....  | 07/17 |
| Eyesight Programming.....   | 08/17 |
| Long Range RES Quirks.....  | 08/17 |
| Eyesight Diagnostic Tips.....   | 09/17 |
| Iphone Contact Options.....   | 10/17 |
| Navigation and Head Unit Diagnosis.....   | 10/17 |
| New Questionnaire for Harman Gen 3 Audio/Navigation concerns.....                                       | 11/17 |
| Long Range RES Transmitter Programming.....   | 12/17 |
| 2017 and Later Impreza, Inoperative Long-Range RES Remotes (Fobs).....                                  | 01/18 |
| Remote Engine Start Hood Switch Installation Review for 2017-2018MY Impreza/2018MY Crosstrek Models ... | 02/18 |
| Thule Roof Rack Wind Noise Complaints.....  | 03/18 |
| 2017MY+ Impreza/Crosstrek (Turn Start) Remote Engine Start Registration.....                            | 04/18 |
| Remote Start Quick Reference.....   | 04/18 |
| 2014-2018MY Forester, Rear-View Mirror Removal Helpful Hints.....                                       | 05/18 |
| 2014 Keyless Access with Push Button Start Vehicles – Erratic Beeping when Entering the Vehicle.....    | 05/18 |
| Air Conditioning Season is Here.....  | 06/18 |
| Contact Pictures and Head Units.....  | 06/18 |
| Harman Version 4 Application.....   | 08/18 |
| DCM Information.....  | 08/18 |
| Combination Meter Replacement.....  | 09/18 |
| Fujitsu/Denso 10 iPhone Contact Picture Display – Update.....   | 10/18 |
| Sirius XM List and Voice Tuning Concerns on Gen 2 & 2.1 Denso (D10) Audio Units.....                    | 10/18 |
| 2019MY Impreza/Crosstrek Remote Engine Start (Key Start) – Control Module Installation.....             | 10/18 |

## 15-Accessories

|   |       |
|---|-------|
| Air Conditioning Leak Revisited.....  | 11/18 |
| 2019 Forester Remote Engine Start Changes and Precautions.....                      | 12/18 |
| 2019 Impreza Sport Remote Engine Start Climate Control Settings.....                | 12/18 |
| Reporting Inaccurate Navigation Map Data.....                                       | 01/19 |
| Unexpected / Abnormal Stop While Operating Remote Engine Start.....                 | 01/19 |
| 19MY Remote Engine Start – Push Button Start.....                                   | 02/19 |
| Use of Aftermarket Accessory Engine / Fuel Economy Monitors.....                    | 03/19 |
| Basic Diagnostics for Remote Engine Start (RES) Systems.....                        | 03/19 |
| Testing and Diagnosis of the Telematics Wifi Hotspot and Appointment Scheduler..... | 03/19 |



## 16-Automatic Transmission

### 16-Automatic Transmission

|  |       |
|--|-------|
| Metallic Noise on Light Acceleration- 4EAT Equipped Vehicles .....                       | 05/91 |
| 3AT Oil Strainer Screen Deterioration .....  | 05/91 |
| 4EAT Slow Engagement .....   | 06/91 |
| Legacy Transmission Oil Cooler Flushing .....  | 06/91 |
| ECVT Transfer Cover Gasket/Erratic 4WD Dash Lamp Illumination .....                      | 06/91 |
| 4EAT Failure After Replacement of Reduction Shaft .....                                  | 06/91 |
| FT4WD Binding On Corners .....   | 08/91 |
| ECVT Main Drive Shaft Seal Ring .....  | 09/91 |
| Justy ECVT Technical Information Supplement .....  | 10/91 |
| Legacy A/T Oil Pump Cover Bolt Torque Clarification .....                                | 11/91 |
| A/T Pressure Checking Tip .....  | 11/91 |
| A/T Thrust Bearing Identification .....  | 01/92 |
| Justy ECVT Cable Adjustments .....   | 01/92 |
| 4EAT Parking Pawl Campaign Full Time 4WD .....   | 03/92 |
| 4EAT Planetary & High Clutch Parts (L-Series, Legacy, XT, SVX) .....                     | 06/92 |
| 4EAT Servicing & Repairs .....   | 06/92 |
| 3AT Torque Converter Seal Failures .....   | 06/92 |
| 4EAT Servicing .....   | 07/92 |
| 4EAT Transmission Diagnosis Training Material .....                                      | 07/92 |
| All Models with 4EAT, Pump Cover Production Change .....                                 | 07/92 |
| Legacy ATF Filter Replacement .....  | 08/92 |
| ATK-50 4EAT Filter Installation .....  | 08/92 |
| Legacy and SVX 4EAT Torque Bind Complaints .....   | 10/92 |
| Aftermarket Batteries .....  | 11/92 |
| All Four-Wheel Drive Vehicles .....  | 11/92 |
| Automatic Transmission Rebuilding .....  | 12/92 |
| Justy ECVT.....  | 12/92 |
| 4EAT All Wheel Drive Complete Unit Exchange .....  | 01/93 |
| 4EAT Torque Converter Clutch Always Engaged Causing Engine Stall .....                   | 02/93 |
| 4EAT Auxiliary ATF Filter .....  | 02/93 |
| 3AT (Lock-Up) Torque Converter Engagement on FWD Loyale .....                            | 02/93 |
| 1990-1993MY All Models With 4EAT Low Temperature Operation .....                         | 03/93 |
| Modified 4EAT Pump Gasket .....  | 04/93 |
| 1992MY Legacy 4EAT ATK-50 VIN Range Clarification .....                                  | 04/93 |
| Alternate ECVT Pulley Alignment Formula .....  | 04/93 |
| 1990MY-1993MY All Models 4EAT Low Temperature Operation Correction to 03/93 Update ..... | 05/93 |
| Legacy 4EAT Squeaking Noise from Torque Converter .....                                  | 06/93 |
| Justy ECVT Valve Body Cleaning .....   | 09/93 |
| Speedometer Cable Adapter on 4EAT Transmissions .....                                    | 10/93 |
| Duty Solenoid "C" Swapping For Testing Purposes .....                                    | 12/93 |
| 3 Speed Automatic Clutch Drum Wear .....   | 01/94 |
| AWD Rear Axle Binding .....  | 02/94 |
| Legacy Torque Converter Bolt Removal .....   | 05/94 |
| High Clutch Seizure/Failure, SVX and Legacy Turbo Service Bulletin 16-58-94 .....        | 05/94 |
| 3-Speed Automatic Differential Rebuilding .....  | 05/94 |
| 4EAT Gasket and Seal Kit .....   | 06/94 |
| 3AT Malfunction .....  | 08/94 |
| 4EAT - No Movement in Any Gear .....   | 09/94 |
| 'ATF Temp' Indicator Light – 1995MY Legacy .....   | 09/94 |
| 4EAT Operation – 1995MY Legacy .....   | 09/94 |
| 1995 Legacy with Apparently Non-Existent Codes From TCU .....                            | 10/94 |

## 16-Automatic Transmission

|   |          |
|---|----------|
| 4EAT Cold Weather Operation .....   | 11/94    |
| 4EA Shift Problem Diagnostics .....   | 12/94    |
| ECVT Loss of Line Pressure .....  | 03/95    |
| 1995MY 4EAT Vehicle Noise .....   | 05/95    |
| 1995MY Subaru Legacy/Impreza Shift Lock Diagnosis .....                             | 09/95    |
| 4EAT Low or Erratic Line Pressure .....   | 09/95    |
| Repeat ECVT ECU Failures .....  | 10/95    |
| Correct Axle Ratios .....   | 11/95    |
| Over-Cautious November Update “Correct Axle Ratios” Information .....               | 12/95    |
| 1996MY Subaru Legacy ATF Cooler Hose Re-Routing .....                               | 02/96    |
| Change In Configuration of 4EAT Pinion Shaft .....                                  | 04/96    |
| 4EAT Delayed Engagement into Drive When Warm .....                                  | 05/96    |
| ‘Manual Rom ID...Error 3’ .....   | 05/96    |
| 4EAT AWD Extension Case Roller Bearing Removal .....                                | 07/96    |
| 4EAT Systems Diagnosis .....  | 07/96    |
| 4EAT Transmission Binding In Turns .....  | 08/96    |
| Late 1995MY & 1996MY Transfer Clutch Chatter .....                                  | 09/96    |
| Limited Slip Additive .....   | 11/96    |
| 4EAT Cold Weather Operation .....   | 11/96    |
| 4EAT Speed Sensors .....  | 04/97    |
| Checking Tire Pressures At PDI .....  | 05/97    |
| Remanufactured Transaxle Program .....  | 07/97    |
| Vehicle Engine RPM Goes To Zero When Coming To A Stop .....                         | 08/97    |
| 1998MY Subaru Impreza FWD Fuse Holder .....   | 11/97    |
| Rear Axle Binding On Turns - (One More Time) .....                                  | 01/98    |
| 1999MY 2.2L 4EAT Subaru Legacy Models Harsh Downshifting .....                      | 09/98    |
| 1999MY 4EAT Transmission Operation .....  | 10/98    |
| Transmission Repairs or Replacements .....  | 04/99    |
| Transmission Control Units (TCU) Part Numbers .....                                 | 09/99    |
| 1999MY and Later (Second Generation 4EAT) Trouble Codes.....                        | 02/00    |
| 4EAT Torque Bind.....   | 11/01    |
| Phase 2 4EAT (1999MY to Present) Repairs.....                                       | 03-04/02 |
| 4EAT Remanufactured Transaxle Program – A Reminder .....                            | 08/02    |
| Remanufactured Transmission Paperwork Packets .....                                 | 09-10/02 |
| 2003MY 4EAT Differential Drain Plug .....   | 11/02    |
| 2003MY Legacy 2.5GT Sport Shifter Cold Weather Operation.....                       | 01-02/03 |
| Slope Control Change for 2003-2004MY Vehicles.....                                  | 04/03    |
| 2004 Direct AT Control Valve Body Assembly Collection.....                          | 09/03    |
| (2004 Baja turbo and Forester turbo) Remanufactured Transmission Installations..... | 10/03    |
| Phase II 4EAT Stud Leak Repair .....  | 11/03    |
| Procedures for Handling Returns/Claims – Remanufactured Transmissions.....          | 03/04    |
| Phase 2 4EAT Transmission Characteristics – A Reminder.....                         | 05/04    |
| 2005MY Legacy & Outback AT Models Ring Indicator Removal .....                      | 08/04    |
| Transmission Information Worksheet .....  | 08/04    |
| 5AT Transmission Removal/Installation Precaution.....                               | 08/04    |
| 2005MY Legacy/Outback AT Models Ring Indicator Removal – Revised.....               | 10/04    |
| Inspection and Correction Methods of Connector T4/B11 .....                         | 12/04    |
| T.S.B. # 16-67-04.....  | 01/05    |
| Remanufactured Automatic Transmission Core Fluid Draining Process.....              | 03/05    |
| WWV-06 Campaign.....  | 04/05    |
| TCM Code 45 and the SSM III .....   | 01/06    |
| Phase 2 4EAT Transmission Characteristics.....                                      | 05/06    |

## 16-Automatic Transmission

|   |       |
|---|-------|
| 2004-2005MY Baja (4AT) Noise on Turns .....   | 09/06 |
| Package Changes to Remanufactured Transmissions .....   | 10/06 |
| 5A/T Remanufactured Transmission and “Learning Control” .....   | 12/06 |
| Discontinuation of Spin-On ATF Filter .....   | 08/07 |
| Direct Control 4AT Transmission Information .....   | 08/07 |
| More ATF HP Fluid Information .....   | 09/07 |
| Performing 5 AT “Learning Control” .....  | 09/07 |
| 5 A/T Turbine Speed Sensor Precaution .....   | 11/07 |
| DTC P0741 .....   | 12/07 |
| Learning Control Procedure Applicability .....  | 03/08 |
| 5AT Re-Manufactured Transmission Availability Announcement .....  | 04/08 |
| Quick Tip: Don’t Forget To Do The Learning Control! .....   | 01/09 |
| Legacy / Outback 3.0L 5 A/T Converter Bolts .....   | 03/09 |
| DTC P1714 (4AT) TPS Power Supply Circuit .....  | 03/09 |
| DTC P0712, AT Fluid Temperature Sensor Low Input, D4AT .....  | 06/09 |
| 2010 M/Y Legacy & Outback Lineartronic™ .....   | 09/09 |
| 5AT Turbine Speed Sensor Reminder .....   | 11/09 |
| “Binding on Turns” A Reminder .....   | 12/10 |
| 4EAT Cold Weather Shift Characteristics Reminder .....  | 01/11 |
| Servicing the CVT Front Differential Fluid .....  | 02/11 |
| A/T Light Flashing but No DTC Stored (DTC P0712); Erratic Shifting Complaint .....  | 03/11 |
| 2011 M/Y Tribeca 5A/T, Flywheel Cover .....   | 11/11 |
| DTC P0890 “A/T Self-Shut Relay Diagnosis (Low)” .....   | 12/11 |
| CVT Replacement Reminder .....  | 01/12 |
| 2012 M/Y Impreza CVT Valve Body Replacement Information .....   | 01/12 |
| A/T Shifting Concerns? Measure Those Tires! .....   | 02/12 |
| Generation 1 CVT Transmission Servicing .....   | 02/13 |
| CVT Torque Converters .....   | 02/14 |
| Cold Weather CVT Operation, Engine RPM, and Cabin Heat .....  | 04/14 |
| Automatic Transmission Fluid Usage Chart .....  | 04/16 |
| Binding On Turns and Other Transmission Issues .....  | 11/16 |
| CVT Fluid .....   | 06/17 |
| Damaged Transmission and Front Differential Cases due to over-torque of fill/drain plugs .....                                  | 09/17 |
| Allowable Repairs to CVT Assemblies .....   | 10/17 |
| CVT Application and Generation Chart .....  | 03/18 |
| Torque Converter Relearn .....  | 03/18 |
| CVT Repairs .....   | 09/18 |
| Service Manual Correction: Rear Transmission Crossmember/Transmission Mount Removal –<br>Impreza and Crosstrek CVT Models ..... | 10/18 |

## 17-SRS Air Bag

|  |       |
|--|-------|
| SVX (SRS) Supplemental Restraining System “Air Bag” .....                  | 01/92 |
| Legacy Models Equipped With Air Bag .....                                  | 06/92 |
| 1989MY-92MY Passive Restraint Seatbelt System .....                        | 03/93 |
| 1993MY Legacy “SRS” Airbag Light Stays On .....                            | 04/93 |
| 1993MY Impreza “SRS” Airbag Light Stays On .....                           | 05/93 |
| Diagnostic Information for Subaru SRS Systems .....                        | 12/93 |
| Passive Restraints .....   | 04/94 |
| Checking Air Bag Harnesses .....   | 09/94 |
| Security System in 1994MY SVX with Dual SRS System .....                   | 10/94 |
| 1995MY Subaru Legacy Passenger SRS .....                                   | 06/95 |
| Diagnosing SRS (Air Bag) Codes .....                                       | 07/95 |
| Removal of Passenger’s Air Bag Module .....                                | 04/96 |
| Deployed SRS Air Bags .....  | 06/96 |
| Passenger’s Side Air Bag .....   | 11/96 |
| De-Powered Air Bags .....  | 02/98 |
| All 1998MY Model Air Bag Applicability .....                               | 03/98 |
| Availability of Retrofit Air Bag ‘On - Off’ Switches .....                 | 08/98 |
| Subaru Vehicles Equipped with SRS Side Airbags .....                       | 08/00 |
| 10 Year SRS Inspections.....   | 08/00 |
| Diagnosing SRS (Air Bag) Codes.....  | 10/00 |
| Subaru Vehicles Equipped with SRS Side Airbags .....                       | 07/01 |
| 2002MY Impreza SRS Harness Change.....                                     | 10/01 |
| 2003MY Forester SRS Codes 41 or 42 .....                                   | 07/03 |
| Air Bag Connector .....  | 09/03 |
| Service Bulletin 17-09-04 .....  | 12/04 |
| SRS Codes 41 & 42.....   | 03/05 |
| ODS DTC Code 28 – Spacer Kit .....   | 04/06 |
| 2010 Legacy / Outback Seat Belt Twist .....                                | 03/10 |
| Front Passenger SRS Frontal Airbag (ODS) Indicator Light Information ..... | 08/11 |
| WQA-37 Forester Rear Center Seat Belt Recall Supplemental Information..... | 04/12 |

## 18-Service Manual Corrections

### 18-Service Manual Corrections

|  |       |
|--|-------|
| Legacy Knock Sensor .....  | 09/91 |
| Service Manual Shuffle .....   | 12/91 |
| Diagnosing SVX Trouble Code 37 O2 Sensor LH .....                                    | 03/92 |
| Loyale Passive Restraint and 3-Point Seat Belt Timer Locations .....                 | 04/92 |
| XT6 Electronic-Controlled Motor Drive Power Steering Service Manual Supplement ..... | 04/92 |
| Service Bulletin Manual Supplement Volume 12 Correction .....                        | 05/92 |
| 1992MY Legacy Service Manual Correction .....  | 10/92 |
| 1995MY Subaru Legacy Service Manual Corrections .....                                | 03/95 |
| 1995MY Legacy Service Manual Revision .....  | 07/95 |
| 1996MY Legacy Service Manual Supplement .....  | 09/95 |
| Impreza Service Manual Supplement .....  | 12/95 |
| Service Bulletin Manual & Service Helpline Update Supplement .....                   | 12/95 |
| 1998MY Impreza Service Manual .....  | 11/97 |
| Copying Pages from Service Manuals .....   | 03/98 |
| Correction to Subaru Forester Service Manual .....                                   | 04/98 |
| Evaporative System Diagnosis T.R.B. Corrections .....                                | 08/99 |
| 2000MY Subaru Legacy & Impreza Service Manuals.....                                  | 01/00 |
| Rear Wheel Alignment Specification Correction .....                                  | 01/00 |
| 2000MY Subaru Legacy Service Manual Correction .....                                 | 02/00 |
| Service Bulletin 13-74-00 Correction .....   | 08/00 |
| Service Manual Corrections, 2001MY Forester and Legacy .....                         | 08/00 |
| Service Manual Correction 2001MY Legacy .....  | 08/00 |
| Correction to Service Bulletin 10-70-00.....   | 03/01 |
| Updated Service Manual Information .....   | 02/11 |
| STIS: Help Us to Help You .....  | 05/11 |
| WVX-34 Reminder .....  | 01/13 |
| WQA-37 Information.....  | 01/13 |
| Errors in Service Manuals, What to Do .....  | 12/18 |