



Service Bulletin

Bulletin No.: PIT6526

Date: June, 2026

PRELIMINARY INFORMATION

Subject: Fog Lamp Control Unavailable In Radio Display

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
GMC	Acadia	2026		ALL	ALL	ALL	ALL

Involved Region or Country	North America
Additional Options (RPO)	4SB (AT4)
Condition	Following a K9 Body Control Module update a customer or technician may discover that the fog lamp control is no longer available to toggle in the radio display.
Cause	Engineering is currently investigating.

Correction

Do not attempt any repairs for this concern.

Engineering is currently investigating. In the meantime, please continue to drive your vehicle.

This PI will be updated or replaced with a TSB once a determination has been

Version	1
Modified	06/05/2026 Created on

