



Mitsubishi Motors North America Inc.

Warranty Bulletin

SUBJECT: Modified Hood for Hood Flutter – 2022 Outlander – Claims Coding	USA	Canada	P. Rico	Mexico
	X			
	Issue Date		May 1st 2026	
	Bulletin Number		WB2026-008	

RELATED TECHNICAL SERVICE BULLETIN

TSB-26-42A-002

WARRANTY CLAIM SUBMISSION / COVERAGE APPLICATION

Mileage/Time	Labor operation code	Labor Description	Nature Code	Cause Code	Time Allowance
Within 5 years / 60K miles	425110FN	Engine hood and W/STRIP replacement & Hood damper adjustment	54E	990	6.3 Hrs
Outside of 5 years / 60k miles & Repaired Between May 1 st 2026 - October 31 st 2027	B0063720	** Engine hood and W/STRIP replacement & Hood damper adjustment			6.3 Hrs

**** Special Coverage**, check the Superscreen for eligibility of Hood Flutter Extension on certain MY22 Outlanders providing additional time to make repairs between May 1st 2026 – October 31st 2027 with no mileage limitation.

Warranty Extensions (Note: These are Not Recalls or Service Campaigns)
HOOD FLUTTER EXTENSION VALID FROM - (MAY 1ST 2026 - OCT 31ST 2027) TSB-26-42A-002
VEHICLE HAS PREVIOUS HISTORY OF HOOD REPLACEMENT WITH A COUNTERMEASURE HOOD. DUPLICATE REPAIRS OF HOOD MAY RESULT IN CLAIM CHARGEBACK.

As a convenience, both the extension and prior hood claim history are noted on the Superscreen under the Warranty Extension header. This convenience does not eliminate the requirement to inspect the hood for physical indications and/or search claim history.

Rental coverage Limitations – if required, loaner/ rental vehicles can be utilized for a maximum of 3 days during the repair. Should extenuating circumstances arise, please contact your District Aftersales Manager.

Paint Blending – May be necessary for certain colors and in the event of paint fade on a case by case basis.

If you have any questions, please call the Warranty Information Line @ 1.800.380.2324. You may also email us at WarrantyWebHotline@mmsa.com.

MMNA WARRANTY DEPARTMENT