

2022 MY F-150 Lightning

Accessory Protocol Interface Module - SYNC

SYNC-26.2.8.3

Software Update 12 - Center Touchscreen

Accessory Protocol Interface Module

"*The capacity available for preconditioning may be limited in extremely hot or cold temperatures. Reducing the use of cabin heating or cooling as you approach a fast charger can increase the capacity available to heat or cool the battery.

To view your past software updates, or if you've had multiple updates completed recently, visit: <https://www.ford.com/support/software-updates>"

1

SYNC-26.2.8.3

"This software update contains the following key changes:

- Apple Maps EV Routing in CarPlay can now precondition your vehicle's battery for DC Fast Charging. Simply route to a compatible fast charger in Apple Maps, and your vehicle will automatically warm or cool the battery to ensure optimal charging performance when you arrive.*
- When using Connected Navigation, you can now indicate that you have a Fast Charging Adapter by turning on the Fast-Charging-Adapter-needed toggle. With this enabled, compatible NACS fast chargers, including designated Tesla Superchargers, will appear when searching for charging stations and planning your route, while turning it off will exclude stations that require an adapter.
- New for 12" SYNC 4 screens: Video Streaming and Stingray Karaoke! Enjoy videos or sing along to on-screen lyrics while parked. When driving, passengers can scan a QR code to follow karaoke lyrics on their mobile devices. You can find these new apps in your Apps drawer.
- In line with our commitment to transparency, we've updated your privacy settings to include more choices for certain uses of connected vehicle data, like product improvement. You can now easily manage these preferences under the Connectivity settings menu on your touchscreen.
- The Phone List icon is now available in the top menu bar, giving you quick access to all of your connected phones. Simply tap the icon to view and switch between your paired devices.
- We've improved the reliability of Apple CarPlay and Android Auto to deliver more consistent launches and better overall integration with SYNC.
- We've restored the Auto Hold toggle to your Controls menu, which was inadvertently removed in a previous update. You'll find it within the Controls menu."

