

REFERENCE:	TSB: 23-017-26 GROUP: 23 - Body	Date:	June 11, 2026	REVISION:	—
VEHICLES AFFECTED:	2026 (KM) Jeep Cherokee This bulletin applies to vehicles built on or after January 19, 2026 (MDH 0119XX) and on or before March 18, 2026 (MDH 0318XX).			MARKET APPLICABILITY: <input checked="" type="checkbox"/> NA <input type="checkbox"/> MEA <input type="checkbox"/> SA <input type="checkbox"/> IAP <input type="checkbox"/> EE <input type="checkbox"/> CH NOTE: This bulletin applies to the North America market.	
CUSTOMER SYMPTOM:	Customers may comment on the following: <ul style="list-style-type: none"> The left headlamp is horizontally misaligned or incorrect. 				
CAUSE:	Headlamp Aiming				

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 26-084, date of issue June 11, 2026. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.

REPAIR SUMMARY:

This bulletin is to properly aim the left headlamp.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
08-50-34-9F	Headlamp Alignment - Inspect and Aim / Adjust (0 - Introduction)	6 - Electrical and Body Systems	0.3 Hrs.
Failure Code	ZY	Service Action	

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RSU VIN list, perform the repair. If any vehicle not on the VIN list exhibits any of the symptom listed above in the customer symptom section, perform the Repair Procedure.

REPAIR PROCEDURE:

1. Perform the headlamp aiming procedure. Refer to the detailed service procedures available in DealerCONNECT/Service Library under: Service Info > 08 - Electrical / 8L - Lamps and Lighting / Lamps/ Lighting - Exterior / Standard Procedure.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.