



GM Over-The-Air (OTA) Software Update

Update Title	GM Update 661.51
Associated Field Action(s)	N26-254438 N25-252612 N25-253467 N25-252442
Release Notes	<ul style="list-style-type: none">• Fixes to help ensure proper functionality for heating and cooling features.• Improvements to night mode lights for shifting gears.• Fixes for Daytime Running Lamps turning on when set to Off.• Fixes to help prevent erroneous missing key messages on driver display.• Fixes for accuracy of low tire pressure alert.• Fixes for speed threshold for pedestrian alerts.• Improvements to start reliability and reduced check engine light activation.• Improvements to turbo system diagnostics.• Improvements to reliability when extending the running boards on your vehicle.
Model Year	2024
Make	Chevrolet GMC
Model	<u>Silverado 1500</u> <u>Sierra 1500</u>
Components	BCM (Body Control Module) ARB (Articulated Running Boards) ECM (Engine Control Module)