



GM Over-The-Air (OTA) Software Update

Update Title	GM Update 662.20
Associated Field Action(s)	N25-252723 N26-255029 N25-254125 N26-254766 N25-251815 N26-255986 N25-251797 N25-253034 N26-255317 N26-255335 N24-249047
Release Notes	<ul style="list-style-type: none">• Fixes to help ensure successful vehicle software updates.• The active cabin ventilation feature will operate more reliably.• Additional protection for the health of your battery and updates to help prevent excessive battery drain and overheating.• Improvements to provide more accurate speed limit detection on the driver's display.• Improvements to the availability of driver assistance features and fewer notifications or warnings.• Fixes to help ensure driver assistance features remain functional when the windshield freezes.• Fixes to help prevent loss of Performance Data Recorder functionality and to protect battery health.• The Transmission Fluid Life gauge will reset properly and show a more accurate reading.• The eAWD indicator will activate less frequently during normal driving conditions.• Fixes a known iPhone 15 charging issue that affects some devices
Model Year	2025
Make	Chevrolet
Model	<u>Corvette</u>

Components	AOS (Automatic Occupant Sensing Module) BCM (Body Control Module) ELM (Exterior Lighting Module) FCM (Front Camera Module) ICS_Info (Integrated Center Stack) ICCM (Integrated Chassis Control Module) PDR (Performance Data Recorder) TCM (Transmission Control Module) TPIM (Traction Power Inverter Module) WCM (Wireless Charger Module)
-------------------	---