


TSIB 26-05 Rev A		June 11, 2026
TO:	All Operators	
TITLE:	New Dampened Crankshaft Pulley Availability	
APPLICABILITY:	This Product Improvement is only applicable to J4500 coaches built prior to Q2-2026, that were equipped with a shock-spring loaded-belt tensioner	

This bulletin introduces an optional product improvement to the A/C compressor drive system. This is not a retrofit or mandatory campaign. The improved pulley system is available for customers who wish to reduce noise and vibration characteristics and may be installed at the customer’s discretion.

Field evaluations have shown that the updated pulley system reduces noise and vibration transmitted from the refrigerant compressor through to the coach frame on vehicles in service. This improvement may enhance passenger comfort and overall NVH performance, particularly in rear seating areas.

If you believe you may be interested in this improvement for your coaches please contact your local MCI parts representative to acquire pricing. Please reference PN 6507829 - Kit - Belt Drive, A/C Compressor (Product Improvement).



* New main parts

Figure 1: Dampened crankshaft pulley



Direct any inquiries regarding this bulletin to:

Kevin Robinson

Manager, Vehicle Systems and FSAR

Service Engineering

C 204.430.8826

kevin_robinson@newflyer.com

New Flyer