

Technical Awareness - 223/297 Seat Belt Lamp & Chime

For awareness, after SW update of control unit, IC223, on models 223 and 297, seat belt lamp and chime remains on. Thank you for your patience while we find a solution.