


Title:	PACCAR MX-13 Engine Oil Specification Correction			
Number:	SB_790	Release Date:	06/02/2026	
Revision Number:	Not Applicable	Revision Date:	Not Applicable	
Chassis Type:	All Chassis			
Component Description:	Not Applicable			
Warranty:	1-Year Limited Base Warranty			

This is a Service Bulletin. Parts and labor associated with the information outlined in this bulletin are listed for informational purposes only and are not covered under warranty. Parts associated with this information can be purchased through the local dealer network.

Purpose:

To notify dealers and customers that the engine oil specification listed on certain Federal (FED) Tags for units equipped with PACCAR MX-13 engines may be incorrect, and to ensure proper maintenance practices are followed.

Issue Overview:

Certain units may have been delivered with a Federal (FED) Tag indicating 15W-40 CK-4 engine oil. This specification is incorrect for PACCAR MX-13 engines and may lead to improper maintenance if followed.

Correct Specification:

10W-30 CK-4 is the correct specification for the engine oil in the MX13 engine. **This is noted accurately in the Operator's manual as well as on the engine.**

Required Action:

Engines were filled with the correct oil at the factory; this is a documentation/labeling correction only. Use of incorrect oil may impact engine performance, durability, and warranty coverage.

Dealers should inform their customers that the correct engine oil specification is 10W-30 CK-4 only and the Operator's Manual should always be referenced for the most accurate and up-to-date maintenance requirements.

If a new Fed Tag is requested, please place an order on www.pierceparts.com and submit for warranty.