

GPOP - Issue Review System

Part Number: 68320915A\$, 68340016A\$, 68477074A\$, 68721722A\$

Part Description: A/C Compressor

Issue Description: For concerns of an inoperative A/C system (no relay activation, no compressor engagement, or no response to commands), technicians need to utilize Star Online Publication S262400007 prior to component replacement. Failure to follow this star online publication may result in repeat repairs or misdiagnosis.