

9100841

06/25/2026

MY 21-27, 22-27 DD 22-23 DF 22-24 DX
21-27, 25-27 DJ 21-27 D2

GPOP - Issue Review System

Part Number: 68305624A\$, 68312648A\$, 68368120A\$

Part Description: Front Prop Shaft

Issue Description: If customer concern diagnosis leads to suspect u-joint issue with the prop shaft, u-joint service kit should be utilized to fix concern. Prop shaft replacement would not be required.