

ROCKET 3 REAR BRAKE BLEED REQUIREMENT FOLLOWING EXTENDED STORAGE

Please be advised of an important care requirement outlined in the Rocket 3 Owner's Handbook regarding preparation following extended vehicle storage.

For any Rocket 3 model that has been stored for a period exceeding four months, the rear brake system must be bled prior to returning the motorcycle to service. This requirement is specified within the Owner's Handbook and must be followed to ensure proper brake system performance.

Dealers are requested to ensure that all applicable motorcycles are prepared in line with the handbook guidance before being returned to customer use or activated for sale.

CLEANING AND STORAGE

T3

Preparation after Storage

To prepare the motorcycle after storage, do the following:

- ▼ Install the battery (if removed) (see page 156).
- ▼ If the motorcycle has been stored for more than four months, change the engine oil (see page 126).
- ▼ If the motorcycle has been stored for more than four months, bleed the rear brakes.
- ▼ Check all the points listed in the Daily Safety Checks section.
- ▼ Before starting the engine, remove the spark plugs from each cylinder.
- ▼ Put the side stand down.
- ▼ Crank the engine on the starter motor several times until the oil pressure light goes out.
- ▼ Refit the spark plugs, tightening to 12 Nm, and start the engine.
- ▼ Check and if necessary correct the tyre pressures.
- ▼ Clean the entire vehicle thoroughly.
- ▼ Check the brakes for correct operation.
- ▼ Test ride the motorcycle at low speeds.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.