



## Can-Am Onroad MY25-26 Ryker Prop Shaft - 163234

---

We are currently investigating an issue identified in the field affecting the propulsion shaft

### **Problem:**

We are currently investigating an issue identified in the field affecting the propulsion shaft

### **Inspection Procedure:**

During PDI preparation, please ensure that the propulsion shaft is correctly installed on the vehicle. The circlip must be securely engaged in the gearbox to prevent any axial movement