



Open Campaign **Notice**

We'll make the necessary repairs at no cost to you—schedule your appointment today.

Service Action 60BD - Panoramic Glass Roof Corner Bonding

This notice applies to your vehicle:

MODEL

MODEL YEAR

VIN ending in:

Some vehicles with a panoramic glass roof produced during a limited production period may have bonding issues at the corners of the glass roof.

Under this service action, your authorized Volkswagen dealer will inspect the roof corner bonding and re-bond the entire glass roof, if needed, at no cost to you.

- Inspection will take about an hour
- If re-bonding is needed, your dealer will provide the estimated time for completion

Please contact your authorized Volkswagen dealer without delay to schedule this work. This service action will be available free of charge only until June 30, 2031.

Schedule service online

Find a dealer

Volkswagen Customer Protection

To check your vehicle's eligibility for repair under this or any other recall/service campaign, please visit www.vw.com/lookup and enter your Vehicle Identification Number (VIN) into the Recalls and Service Campaigns Lookup tool.

"Volkswagen" and the Volkswagen logo are registered trademarks of Volkswagen AG.

Volkswagen Customer CARE Center

3800 Hamlin Road
Auburn Hills, MI 48326

[View in Browser](#) | [Privacy Policy](#) | [Unsubscribe](#)