



Connection offline

Technical Service Bulletin

Transaction No.: 2010479/17

69-19-01 - Airbag / Pyrotechnic Safety Belt Deployment Inquiries (U.S. Only)

Condition

Applicable Vehicles					
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
All	1990-2027	All	All	All	All

Revision Table			
Instance Number	Published Date	Version Number	Reason For Update
2010479/17	6/11/26	69-19-01	Update to model year applicability.
2010479/16	1/9/24	69-19-01	Update to contact information.
2010479/15	2/2/23	69-19-01	Update to model year applicability.
2010479/14	11/8/21	69-19-01	Update to model year applicability.
2010479/13	1/22/19	V691901	Update contact information.
2010479/1	2/7/05	V690503	Original publication.



NOTICE

Important Information to all Dealership personnel:

Please promptly report any incident of uncommon or exceptional airbag / pyrotechnic safety belt deployment to:

Peter Green

Volkswagen Group of America, Inc.

1950 Opportunity Way, Suite 1500, Reston, VA.

(703) 636-3686 Office

Peter.Green@vw.com

Technical Background

Information only.

Production Solution

No production change required.

Service

Please have the following information available before placing a call:

- Customer description of the incident
- Repair order containing:
 - Dealer information
 - VIN
 - Mileage
 - Customer Information (Name, Address, Phone Number)
- Current location of the car including a phone number, stock or location number, and person in charge
- Digital photographs of any vehicle damage including the following areas:
 - Chassis
 - Suspension
 - Wheels
 - Tires
 - Body
- 6150/X & 6160/X and ODIS Service with current online updates scan of airbag and engine control units stored in electronic format. VIN & Customer name are to be included. Do not clear any fault data

If an accident had occurred:

- Digital photographs of the accident scene
- Police reports



Based on the above information, we may want to inspect this vehicle.

- Please advise owners who request information about airbag or safety belt systems to call Customer Care Center at 1 (800) 822-8987.



NOTICE

We highly recommend that you never deliver to the customer a vehicle with: (i) a deployed airbag, (ii) a deployed pyrotechnic safety belt, or (iii) an illuminated airbag malfunction indicator light.

Warranty

Information Only.

Required Parts and Tools

No Special Parts required.

No Special Tools required.

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.

© 2026 Volkswagen Group of America, Inc. / Volkswagen Group Canada Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc. / Volkswagen Group Canada Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.