

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment
A3, S3, and RS 3	2022 – 2026	All	Not applicable
Q3	2026		

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised header (Added Model) Revised <i>Condition</i> (Added Model Table)
1	03/31/2025	Initial publication

Customer States:

There are no keys which have been adapted to the vehicle.

(Example: All vehicle keys were lost)

Workshop Findings:

A new set of keys or a replacement key is to be initialized for the vehicle.

The immobilizer cannot be adapted. No data can be read from the Electronic Central Electrical control module, J519 (address word 0009) currently installed.

Technical Background

If the vehicle has been locked, it must be unlocked using the keyless access locking and starting system so that data can be read from the Electronic Central Electrical control module, J519 (address word 0009).

If this is not possible due to no programmed keys being available, the Electronic Central Electrical control module, J519 (address word 0009) must also be replaced for reasons relating to protection from manipulation.

Production Solution

Not applicable.

Service

If no already programmed keys are available, the Electronic Central Electrical control module, J519 (address word 0009) must also be replaced for reasons relating to protection from manipulation.

Warranty

This damage is due to outside influence and is not covered by any Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2077458**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, LLC / Audi Canada Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, LLC / Audi Canada Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.