

Installation and Conversion Instructions

911 (992)

20/25 ENU 6699

6

CFK KIT 992.2 GT3

Vehicle Type: **992.2 GT3**

Model Year: **As of 2025**

Cause: **Retrofitting**



Information

- Some of the repair illustrations show only one side of the vehicle or a similar component.
- Naturally, some steps also have to be performed on the opposite side of the vehicle as well.



Information

Please pass all this information on to the customer.

Also give the customer a copy of the first pages of these Installation and Conversion Instructions, including the legal regulations.

Parts Info:	992.044.855.40	1x	Carbon kit (complete)
	992.044.855.41	1x	Carbon air intake for rear
	992.044.855.42	1x	Carbon air outlet for bonnet
	992.044.855.45 ¹	1x	Air outlet for bonnet, CFRP LH
	992.044.855.46 ¹	1x	Air outlet for bonnet, CFRP RH
	992.044.855.47 ²	1x	Air intake trim, CFRP
	992.044.855.48 ²	1x	Brake light trim, CFRP
	992.044.855.49 ²	1x	Service flap, CFRP

¹ Included in the set Carbon air outlet, bonnet.

² Included in the set Carbon air outlet, rear.

Work procedure: 1 Replacing air outlet for bonnet. ⇒ *Workshop Manual 'Removing and installing front lid (air guide trim)'*

2 Replacing air intake (trim) & brake light trim. ⇒ *Workshop Manual 'Removing and installing rear lid'*

3 Replace the rear service flap. ⇒ *Workshop Manual 'Removing and installing rear lid (flap)'*

55 22 19 27: Removing and installing left air guide trim

Labor time: **54 TU**

55 22 19 28: Removing and installing right air guide trim

Labor time: **54 TU**

55 90 19 00: Removing and installing rear lid

Labor time: **67 TU**

Includes: CFRP air intake trim, CFRP brake light trim, CFRP service flap.

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2026 Porsche Cars North America, Inc.