

Parts Information

D791

13

Parts Withdrawal - Front Bumper Panel

Replaces all previous bulletin bearing this number.

Attention: Porsche Parts Managers/Parts Personnel

Porsche Cars North America requests return of the following part(s) to PCNA if in stock at your Porsche Center:

Part Number	Description	Instructions
99350531102G2X	Front Bumper Panel	Affected parts exhibit a wavy surface above the license plate that is detectable by touch. The parts exhibit a wavy surface in the area directly above the license plate. The waviness can be felt by hand and remains visible after painting. Reworking of defective parts is not possible. Please reference photo below.



To avoid restocking charges and receive full credit, follow these steps:

- Please enter a return in PPL by Wednesday, July 1, 2026.
- Please use **GR13D791** as a purchase order number.
- Parts returned to PCNA without a return delivery note will be sent back to the Porsche Center at Porsche Center's expense.
- Return requests received after the specified return date **will not be processed** and the parts will not be accepted for return. Parts will be coded non-returnable from that date on.
- These parts must be physically returned by close of business day on **Monday, July 6, 2026**, to your facing PDC.

Thank you for your cooperation in this matter.

Porsche Cars North America