



Service Bulletin

Bulletin No.: PIT6532

Date: July, 2026

PRELIMINARY INFORMATION

Subject: Flapping Ticking Noise From Rear Cab Area

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 1500	2019 - 2026		All	All	All	All
Chevrolet	Silverado 2500 HD	2020 - 2026		All	All	All	All
Chevrolet	Silverado 3500 HD	2020 - 2026		All	All	All	All
GMC	Sierra 1500	2019 - 2026		All	All	All	All
GMC	Sierra 2500 HD	2020 - 2026		All	All	All	All
GMC	Sierra 3500 HD	2020 - 2026		All	All	All	All

Involved Region or Country	North America
Condition	Some customers may comment on a flapping or ticking-type noise coming from behind the rear seat area when driving at low speeds, opening or closing a door, or during other normal vehicle operation. The noise may vary depending on ambient weather conditions, HVAC blower speed, and whether the system is in recirculation or fresh air mode.
Cause	This condition may be caused by the pressure relief valve (PRV) rubber flaps moving due to changes in cabin pressure, road inputs, or door operation.

Correction

If the pressure relief valves are confirmed to be properly installed and secure, this condition is considered normal operation. No repairs should be performed. It is recommended to compare the vehicle to a like vehicle with the same cab and box configuration to verify the characteristic.

Version	1
Modified	07/06/2026 - Created on

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION**

Copyright 2026 General Motors. All Rights Reserved.