

GPOP - Issue Review System

Part Number: 68574848A\$, 68597253A\$, 68597254A\$, 68600340A\$, 68728136A\$,
68728137A\$, 68741950A\$

Part Description: Cluster Assembly

Issue Description: When the technician connects to the vehicle via Witech, they observe Stored and/or Pending DTC in the IPC for KM49, LB, KM74 Programs. The instrument cluster should not be replaced based solely on the presence of stored or pending DTCs in the IPC. Replacement should only be considered if the stored or pending DTC becomes active during the troubleshooting and diagnostic process.