

Service Alert

Mazda North American Operations
Irvine, CA 92618-2922



Subject: CHECK ENGINE LIGHT ON AND MESSAGE IN INSTRUMENT CLUSTER WITH DTC P0DAB:17 AND/OR P0DAB:00	Service Alert No.: SA-058/26
	Last Issued : 08/25/2026

BULLETIN NOTES

This Service Alert supersedes the previously issued SA(s) listed below. The changes are noted in Red.

Previous SAs:	Date(s) Issued:
SA-001/25	10/16/25, 05/15/25, 04/17/25 and 01/09/25
SA-082/24	12/13/24

APPLICABLE MODEL(S)VINS

2024 CX-90 MHEV (inline6) with VINS between JM3KK*****100044 - 170926 (produced between December 27, 2022 - April 24 2024)

DESCRIPTION

This Service Information is no longer valid and has been unpublished. Refer to: MSP66 - ENGINE WARNING ILLUMINATION WITH DTC P0DAB - 2024-2026 CX-90 AND 2025-2026 CX-70

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.