

GPOP - Issue Review System

Part Number: 6GA801A8\$\$

Part Description: Shifter

Issue If shifter is having trouble shifting between 1st and 2nd gear, then adjust cables as
Description: described in service library.