

Fuji Heavy Industries U.S.A., Inc. c/o Subaru of America Subaru Plaza PO Box 6000 Cherry Hill, NJ 08034-6000 856-488-8500 856-488-8669 fax

Brian DeAscentiis Regulatory Activities Manager Direct Dial: (856) 488-3465 Fax: (856) 488-8669

E-mail: bdeascentiis@subaru.com

July 10, 2013

Ms. Kelly Schuler, Safety Defect Analyst National Highway Traffic Safety Administration Recall Management Division - NVS-215 1200 New Jersey Ave. SE Washington, DC 20590

Re: NHTSA 49 CFR, Part 573.6 Quarterly Defect Report

Dear Ms. Schuler:

Enclosed are the Quarterly Reports for recall campaigns currently conducted by Subaru of America, Inc., which are submitted on behalf of Fuji Heavy Industries, Ltd., Japan. These reports are submitted in accordance with the terms of voluntary campaigns similar to reports required in 49 CFR, Part 573.6.

This submission includes reports for the safety recall / service programs listed below:

NHTSA Recall No.	SOA Recall
13V078	WVV-32 Safety Recall
13V077	WVW-33 Safety Recall
11V464	WVX-34 Safety Recall
12V047*	WVZ-36 Safety Recall
12V099	WQA-37 Safety Recall
12V602	WQE-41 Safety Recall
13V061	WQF-42 Safety Recall
13V110	WQG43 Safety Recall
13V159	WQH44 Safety Recall
13V194	WQI45 Safety Recall

Please note that reports identified with an asterisk (*) are for the sixth and final quarterly reporting period.

Subaru of America will continue to send subsequent mailings for returned mail, which contains valid owner name and address information in order to attain the highest completion rates for campaigns.

Please contact me if you have any questions or comments regarding these reports.

Sincerely,

SUBARU OF AMERICA, INC.

Brian DeAscentiis

Regulatory Activities Manager

Enclosures

Vehicle Safety Recall Quarterly Report Information Required per 49 CFR Part 573.6

Report Date: July 10, 2013 Calendar Quarter: 2nd

Safety Recall Quarterly Report from 4/13 through 6/13 **Reporting Quarter: 1st**

Manufacturer: Subaru of America, Inc. Report Author: Brian DeAscentiis

Phone: (856) 488-3465

Recall Subject: Subaru Carpeted Floor Mats

1. NHTSA Safety Recall Campaign Number: 13V-159

Also, for completeness, if your company has assigned a code number to this campaign, please provide vour code: WOH-44

- (a) The date notification to purchasers began: Defect Advisory Letter 4/26/13; 2. Remedy Notification Letter 6/5/13
 - (b) The date notification of purchasers was completed: Defect Advisory Letter 4/26/13; Remedy Notification Letter 6/5/13
- 3. The Total Number of Items Involved: 10.133
 - Part 573 submission on April 18, 2013 indicated that approximately 10,137 vehicles were estimated to potentially contain the defect.
 - A Final analysis on 4/25/13 identified 10,133 vehicles that potentially contain the defect.

The total number of vehicles involved in the subject campaign (including all items sold or distributed to purchasers. dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

(a) Total Number Inspected and Remedied: 2,975 4.

Total number of vehicles which were inspected and/or otherwise repaired or remedied.

(b) Total Number Inspected & NOT REQUIRING REMEDY: 0

Total number of vehicles involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5. Vehicles Determined to be Unreachable

> Total Number Exported: N/A Total Number Stolen: N/A Total Number Scrapped: N/A **Total Number Unable to Notify: 171**

Total Number Otherwise Unreachable: N/A