OMB Control No.: 2127-0004

Recall Quarterly Report

14V-577

Manufacturer Name: Subaru of America, Inc.

NHTSA Recall No. / MFR Recall No.: 14V-577 /WQN-50

Recall Subject: Trailer Hitch Assembly may be Incorrectly Torqued

Owner Notification Beginning Date : OCT 07, 2014

Owner Notification End Date: APR 15, 2015



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	APR 16, 2015	2015-1	56	46	0	0
1	JAN 19, 2015	2014-4	56	42	0	0

This Document Last Updated: APR 17, 2015

Definitions:

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the $3^{\rm rd}$ quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

 $Total\ Removed:\ Products\ that\ have\ been\ scrapped,\ stolen,\ or\ exported.$