



URGENT VEHICLE NOTIFICATION
YOUR AIRBAG MAY
NOT BE SAFE

**Stop what you're doing and call now to
avoid potential injury or death.**

CALL 1-844-758-9245

Details on back 

1T1 P1 **** ***** ** AUTO**3-DIGIT 453
John Smith
123 Street Rd
Anywhere, OH 12345-1234

Presort Std
US Postage
PAID
Dallas, TX
Permit No. 919

URGENT SAFETY RECALL NOTICE

YOUR AIRBAG NEEDS TO BE REPAIRED



Figure 1. Proper airbag deployment



Figure 2. Driver side airbag deployment with inflator rupture.

WE HAVE DISCOVERED A SAFETY DEFECT IN YOUR 2001 HONDA ACCORD.

The driver's front airbag inflator could produce excess pressure upon deployment, causing the inflator to rupture. Fragments from ruptured inflators could hit you or others in the vehicle. Past ruptures like this **HAVE KILLED** or **INJURED** vehicle drivers. Due to the severity of this defect, your vehicle has been recalled and must be repaired. The repair will be done free of charge. Contact us without delay to address this important safety issue.



This important safety recall repair needs to be scheduled immediately. If you do not have this issue repaired, your safety is at risk.

CALL YOUR RECALL RESOLUTION TEAM NOW:

1-844-758-9245

Monday through Friday, 8a.m. to 7p.m. CST. We will schedule an appointment with you to have this Safety Recall resolved at no charge.

For your convenience we have provided the last digits of your VIN below. Please refer to this number when scheduling your free appointment to verify your identity and vehicle.

*Thank You,
Honda Recall Resolution Team*

VEHICLE INFORMATION

2001 Honda Accord
VIN XXXXXXXXXX

DEALERSHIP INSTRUCTIONS:

Please reference Campaign [CID].

H-FL DAB 3RV

FOR YOUR SAFETY CALL

1-844-758-9245



HONDA