## OMB Control No.: 2127-0004

## **Recall Quarterly Report**

17V-132

**Manufacturer Name:** Subaru of America, Inc.

NHTSA Recall No. / MFR Recall No.: 17V-132 /WTN-74

**Recall Subject:** Rearview Camera Display may not Function Properly

**Owner Notification Beginning Date : MAR 27, 2017** 

Owner Notification End Date: MAR 27, 2017



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
5	APR 20, 2018	2018-1	25,567	24,825	185	0
4	JAN 08, 2018	2017-4	25,567	24,593	185	0
3	OCT 06, 2017	2017-3	25,567	24,156	185	0
2	JUL 14, 2017	2017-2	25,567	22,964	185	0
1	APR 12, 2017	2017-1	25,567	16,828	0	0

This Document Last Updated: APR 26, 2018

## **Definitions:**

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the  $3^{rd}$  quarter of 2012). Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.