

U.S. Department of Transportation

National Highway Traffic Safety Administration

December 7, 2017

Mr. Keith Fisher Engineer-Corporate Compliance Forest River, Inc. P.O. Box 3030 55470 County Road 1 Elkhart, IN 46515

Subject: Carbon Monoxide May Enter Passenger Cabin

Dear Mr. Fisher:

This letter serves to acknowledge Forest River, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

1200 New Jersey Avenue SE Washington, DC 20590

NEF-150KS

17V-724

Makes/Models/Model Years:

FOREST RIVER/DYNAMAX/2017-2018

Mfr's Report Date: November 17, 2017

NHTSA Campaign Number: 17V-724

Components:

ENGINE AND ENGINE COOLING: EXHAUST SYSTEM

Potential Number of Units Affected: 581

Problem Description:

Forest River, Inc. (Forest River) is recalling certain 2017-2018 Dynamax recreational vehicles, models ISC24FWM, ISC24FWMCD and ISC24CBM. If the vehicle is parked with the engine running, carbon monoxide may enter the passenger cabin through open windows or other openings in the floor.

Consequence:

If carbon monoxide enters the passenger cabin, it can increase the risk of injury or death.

Remedy

Forest River will notify owners, and dealers will install stainless steel exhaust tips to lengthen the exhaust, free of charge. The recall is expected to begin January 15, 2018. Owners may contact Forest River customer service at 1-574-262-3474. Forest River's number for this recall is 55-0565.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



We have received Forest River's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Kelly Schuler who may be reached by phone at (202) 366-5227, or by email at kelly.schuler@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian

Chief, Recall Management Division Office of Defects Investigations Enforcement

