

U.S. Department of Transportation

National Highway Traffic Safety Administration

January 12, 2018

Mr. Francesco Valentini Head of Homologation MV Agusta USA, LLC Via Giovanni Macchi 144 Varese 21100 NEF-150JK 17V-839

1200 New Jersey Avenue SE Washington, DC 20590

Subject: Front Brake Master Cylinder Failure

Dear Mr. Valentini:

This letter serves to acknowledge MV Agusta USA, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

MV AGUSTA/F4/2015-2016

Mfr's Report Date: December 22, 2017

NHTSA Campaign Number: 17V-839

Components:

SERVICE BRAKES, HYDRAULIC:FOUNDATION COMPONENTS:MASTER CYLINDER

Potential Number of Units Affected: 27

Problem Description:

MV Agusta USA, LLC (MV Agusta) is recalling certain 2015-2016 F4 RC and F4 RR motorcycles. These motorcycles are equipped with Brembo front brake master cylinders that may fail.

Consequence:

If the front brake master cylinder fails, the loss of front braking ability can increase the risk of a crash.

Remedy

MV Agusta will notify owners, and dealers will replace the front brake master cylinder piston, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact MV Agusta customer service at 1-215-781-1770. MV Agusta's number for this recall is 18RC01.

Notes

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Jennifer Kruger who may be reached by phone at (202) 366-2461, or by email at jennifer.kruger@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian

Chief, Recall Management Division Office of Defects Investigations

Enforcement

