

U.S. Department of Transportation

National Highway Traffic Safety Administration

January 29, 2018

Mr. Chris Grigorian Outside Counsel For Dainese S.p.A. Via dell'Artigianato 35 Molvena (VI) 36060

Subject: Chin Bar may Detach in a Crash

Dear Mr. Grigorian:

This letter serves to acknowledge Dainese S.p.A.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

1200 New Jersey Avenue SE Washington, DC 20590

NEF-150SM

18E-006

Makes/Models/Model Years:

AGV/CARBON MODULAR HELMET/9999

Mfr's Report Date: January 24, 2018

NHTSA Campaign Number: 18E-006

Components:

EQUIPMENT: MOTORCYCLE: HELMETS

Potential Number of Units Affected: 325

Problem Description:

Dainese S.p.A (Dainese) is recalling certain AGV Carbon Modular motorcycle full-face, flip-up helmets, model AGV 580. The glue applied to the screws that secure the chin bar components together may have contacted the chin base polycarbonate material causing it to deteriorate prematurely.

Consequence:

The deteriorated polycarbonate material may result in the chin base detaching during an impact, increasing the risk of injury.

Remedy:

Dainese will notify owners, and dealers will replace the helmets, free of charge. The recall is expected to begin February 1, 2018. Owners may contact Dainese customer service at 1-855-327-5639.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Sarah Mcshane who may be reached by phone at (202) 366-7401, or by email at sarah.mcshane@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian

Chief, Recall Management Division Office of Defects Investigations

Enforcement

