U.S. Department of Transportation National Highway Traffic Safety Administration

August 14, 2018

Mr. Rob Lailey Industrias Martinrea de Mexico SA de CV Carretera Antigua a Arteaga No 2653 Col. Aurora Saltillo C.P. 25298

Subject: Brake Hose Corrosion May Cause Brake Fluid Leak

Dear Mr. Lailey:

This letter serves to acknowledge Industrias Martinrea de Mexico SA de CV's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years: INDUSTRIAS MARTINREA/BRAKE HOSE/9999

Mfr's Report Date: July 17, 2018

NHTSA Campaign Number: 18E-055

Components: SERVICE BRAKES, HYDRAULIC:FOUNDATION COMPONENTS:HOSES, LINES/PIPING, AND FITTINGS

Potential Number of Units Affected: 3,931

Problem Description:

Industrias Martinrea de Mexico SA de CV (Martinrea) has submitted a Defect Information Report based upon decisions made by Chrysler (FCA US LLC) and Ford Motor Company to conduct recalls (numbers 18V277 and 18V389 respectively). The brake circuit hose assemblies located between the master cylinder and the hydraulic control unit, may have been manufactured without anticorrosion plating on the coupling fittings, or "ferrules," of the hoses. This can lead to premature corrosion, and result in a brake fluid leak.

Consequence:

A brake fluid leak can reduce brake effectiveness, increasing the risk of a crash.

Remedy:

Martinrea is working with the affected vehicle manufacturers. Dealers for those manufacturers will replace the brake hoses, free of charge. Chrysler owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is U41. Ford owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 18S19.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Image: A state of the state

1200 New Jersey Avenue SE Washington, DC 20590

> NEF-150MR 18E-055

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, an item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As required in Part 573.6(c)(6), in the case of a defect, please provide a chronology of all of the principal events behind the defect determination.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Michelle Rice who may be reached by phone at (202) 366-1060, or by email at michelle.rice@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian Chief, Recall Management Division Office of Defects Investigations Enforcement

