

August 14, 2018

Mr. Mario Piccioni Chief Quality Officer Brembo S.p.A. Via Brembo 25 Curno (Bg) 24040

Subject: Brake Pad Friction Material may Detach

Dear Mr. Piccioni:

This letter serves to acknowledge Brembo S.p.A.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years: BREMBO/REAR BRAKE PADS/9999

Mfr's Report Date: July 18, 2018

NHTSA Campaign Number: 18E-057

Components: SERVICE BRAKES, HYDRAULIC:FOUNDATION COMPONENTS:DISC:PADS

Potential Number of Units Affected: 3,026

Problem Description:

If the rear brake pad friction material detaches, it may lengthen the distance needed to stop the motorcycle, increasing the risk of a crash.

Consequence:

If the brake pad friction material detaches it can, inhibit braking ability, increasing the risk of injury and crash.

Remedy:

Brembo will work with the affected vehicle manufacturers and distributors, and replace the defective brake pads, free of charge. The manufacturer has not yet provided a notification schedule.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



1200 New Jersey Avenue SE Washington, DC 20590

> NEF-150MR 18E-057

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Michelle Rice who may be reached by phone at (202) 366-1060, or by email at michelle.rice@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian Chief, Recall Management Division Office of Defects Investigations Enforcement

