

U.S. Department of Transportation

National Highway Traffic Safety Administration

November 30, 2018

Mr. Stephen Forgas Iowa Mold Tooling Co., Inc. 2307 Oregon Street Oshkosh, WI 54902 1200 New Jersey Avenue SE Washington, DC 20590

NEF-150MR 18E-105

**Subject:** Transmitter Failure Causing Crane Movement

Dear Mr. Forgas:

This letter serves to acknowledge Iowa Mold Tooling Co., Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

### Makes/Models/Model Years:

**IMT/WIRELESS TRANSMITTER/9999** 

Mfr's Report Date: November 16, 2018

NHTSA Campaign Number: 18E-105

## **Components:**

**ELECTRICAL SYSTEM** 

Potential Number of Units Affected: 20

# **Problem Description:**

Iowa Mold Tooling Co., Inc. (IMT) is recalling certain Omnex Proportional Wireless Transmitters, part numbers 70733882 and 70733883, used for controlling cranes. These wireless transmitters have a diode that can fail, possibly causing the crane to move in an unintended manner.

### **Consequence:**

If the crane moves in a way that was not intended, it can increase the risk of injury to those nearby.

## Remedy:

IMT will notify owners, and IMT Distributors will replace the transmitter, free of charge. The recall is expected to begin December 14, 2018. Owners may contact IMT customer service at 1-800-554-4421.

#### **Notes:**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Michelle Rice who may be reached by phone at (202) 366-1060, or by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian

Chief, Recall Management Division Office of Defects Investigations

Enforcement

