

U.S. Department of Transportation

National Highway Traffic Safety Administration

July 9, 2018

Mr. Todd Fronckowiak Assistant Director, Global Automotive Safety Compliance Ford Motor Company Fairlane Plaza South, Suite #500 330 Town Center Drive Dearborn, MI 48126-2738 NEF-150JK 18V-389

1200 New Jersey Avenue SE Washington, DC 20590

Subject: Brake Hose Corrosion May Cause Brake Fluid Leak

Dear Mr. Fronckowiak:

This letter serves to acknowledge Ford Motor Company's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

FORD/F-650 SD/2018 FORD/F-750 SD/2018

Mfr's Report Date: June 11, 2018

NHTSA Campaign Number: 18V-389

Components:

SERVICE BRAKES, HYDRAULIC: FOUNDATION COMPONENTS: HOSES, LINES/PIPING, AND FITTINGS

Potential Number of Units Affected: 1,474

Problem Description:

Ford Motor Company (Ford) is recalling certain 2018 Ford F-650 and F-750 trucks. The brake circuit hose assemblies located between the master cylinder and the hydraulic control unit, may have been manufactured without anti-corrosion plating on the coupling fittings, or "ferrules," of the hoses. This can lead to premature corrosion, and result in a brake fluid leak.

Consequence:

A brake fluid leak can reduce brake effectiveness, increasing the risk of a crash.

Remedy:

Ford will notify owners, and dealers will replace the brake hose assemblies, free of charge. The recall is expected to begin July 9, 2018. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 18S19.

Notes

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



We have received Ford's proposed owner notification letter and have approved it for distribution.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Jennifer Kruger who may be reached by phone at (202) 366-2461, or by email at jennifer.kruger@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian

Chief, Recall Management Division Office of Defects Investigations

Enforcement

