OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

## 18V-001

**Manufacturer Name:** Erwin Hymer Group North America, Inc.

Submission Date: JAN 02, 2018 NHTSA Recall No.: 18V-001 Manufacturer Recall No.: 17E062000



#### **Manufacturer Information:**

Manufacturer Name: Erwin Hymer Group North America,

Inc.

Address: 100 Shirley Avenue

Kitchener Ontario 00 N2B 2E1

Company phone: 1-844-413-8245

## **Population:**

Number of potentially involved: 5,185 Estimated percentage with defect: NR

#### **Vehicle Information:**

Vehicle 1: 2012-2018 All Makes All Models

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information : Walter Kidde Portable Equipment is recalling certain models of Plastic Handle Fire

Extinguishers. Erwin Hymer Group North America, Inc., used models E10 and EH10 between January 2, 2012 to August 15, 2017 in all their Roadtrek, Hymer, Sunlight

and Carado models.

Production Dates: JAN 02, 2012 - AUG 15, 2017

#### **Description of Defect:**

Description of the Defect: These extinguishers may become clogged, preventing the extinguisher from

discharging as expected or excessive force may be needed to activate the

extinguisher.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: If the fire extinguisher does not function properly, it can increase the risk of

injury or death in the event of a fire.

Description of the Cause : NR Identification of Any Warning NR

that can Occur:

## **Supplier Identification:**

## **Component Manufacturer**

Name: Walter Kidde Portable Equipment, Inc.

Address: NR

Mebane NORTH CAROLINA

**Country: United States** 

## **Chronology:**

Received a notice from Kidde on October 5 notifying us of the defect and to purge our inventory, In late November we spoke with our representative who provided us instructions on how to notify our customers.

### **Description of Remedy:**

Description of Remedy Program: Consumers should contact Kidde Customer Service at their toll-free

number at 1-855-271-0773 from 8:30 a.m. to 5:00 p.m. ET Monday

through Friday, 9:00 a.m. to 3:00 p.m ET Saturday and Sunday. Or online at www.kidde.com and click on "Product Safety Recall" for more information

on how to obtain a replacement fire extinguisher, free of charge.

How Remedy Component Differs NR

from Recalled Component:

was Corrected in Production: October 5, 2017. All units manufactured after October 5, 2017 will contain

the replacement extinguisher.

#### **Recall Schedule:**

Description of Recall Schedule: NR

Planned Dealer Notification Date : JAN 08, 2018 - JAN 22, 2018 Planned Owner Notification Date : JAN 08, 2018 - FEB 05, 2018

<sup>\*</sup> NR - Not Reported