

Recall Quarterly Report**18V-012**

Manufacturer Name : Subaru of America, Inc.
NHTSA Recall No. / MFR Recall No. : 18V-012 /TKA-18
Recall Subject : Passenger Frontal Air Bag Inflator May Explode
Owner Notification Beginning Date : FEB 09, 2018
Owner Notification End Date: MAR 09, 2018



| Report # | Submission Date | Report Quarter | Recall Population | Total Remedied | Total Unreachable | Total Removed |
|----------|-----------------|----------------|-------------------|----------------|-------------------|---------------|
| 2 | JUL 12, 2018 | 2018-2 | 64,179 | 35,369 | 0 | 1,655 |
| 1 | APR 20, 2018 | 2018-1 | 64,179 | 23,401 | 0 | 1,887 |

This Document Last Updated : JUL 13, 2018

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.