

Representative Letter – Customer letters are brand, model and model year specific; listing the 17-digit VIN and are personalized.



IMPORTANT SAFETY RECALL

March 2018

This notice applies to your vehicle, VIN: _____

Dear General Motors Customer:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Toyota has decided that a defect, which relates to motor vehicle safety, exists in all 2010 model year Pontiac Vibe vehicles not previously recalled for this condition. The Pontiac Vibe was manufactured by New United Motor Manufacturing, Inc. (NUMMI), a joint venture between Toyota and General Motors. As a result, GM is conducting a safety recall. We apologize for this inconvenience. However, we are concerned about your safety and continued satisfaction with our products.

IMPORTANT
<ul style="list-style-type: none"> Your vehicle is involved in GM safety recall 17477. Schedule an appointment with your GM dealer. This service will be performed for you at no charge.

Why is your vehicle being recalled? The subject vehicles are equipped with front passenger air bag inflators which may have been manufactured in such a way as to have a potential for the intrusion of moisture over time. This could create excessive internal pressure when the air bag is deployed and cause the inflator to explode. In the event of an inflator explosion, sharp metal fragments could pass through the airbag cushion material, striking the vehicle occupants and result in serious injury or death.

What will we do? Your GM dealer will replace your vehicle's front passenger air bag inflator. This service will be performed for you at **no charge**. The repair will take approximately one hour. Because of service scheduling requirements, it is likely that your dealer will need your vehicle for a longer period of time.

What should you do? You should contact your GM dealer to arrange a service appointment as soon as possible.

Until the repair is performed, the front passenger seat should NOT be occupied.

Do you have questions? If you have questions or concerns that your dealer is unable to resolve, please contact the appropriate Customer Assistance Center at the number listed below.

Division	Number	Text Telephones (TTY)
Pontiac	1-800-620-7668	1-800-833-7668
Puerto Rico – English	1-800-496-9992	
Puerto Rico – Español	1-800-496-9993	
Virgin Islands	1-800-496-9994	

If after contacting your dealer and the Customer Assistance Center, you are still not satisfied we have done our best to remedy this condition without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll-free Vehicle Safety Hotline at 1.888.327.4236 (TTY 1.800.424.9153), or go to <http://www.safercar.gov>. The National Highway Traffic Safety Administration Campaign ID Number for this recall is 18V025.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Maryann L. Combs
Vice President
Global Vehicle Safety

GM Recall Number: 17477