

January 17, 2018

Mr. David Kim Tesla, Inc. 45500 Fremont Blvd Fremont, CA 94538

Subject: Passenger Frontal Air Bag Inflator May Explode

Dear Mr. Kim:

This letter serves to acknowledge Tesla, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years: TESLA/MODEL S/2013

Mfr's Report Date: January 9, 2018

NHTSA Campaign Number: 18V-031

Components: AIR BAGS:PASSENGER SIDE FRONTAL

Potential Number of Units Affected: 17,846

Problem Description:

Tesla, Inc. (Tesla) is recalling all 2013 Model S vehicles equipped with certain air bag inflators assembled as part of the passenger frontal air bag modules used as original equipment or replacement equipment. In the event of a crash necessitating deployment of the passenger frontal air bag, these inflators may explode due to propellant degradation occurring after long-term exposure to absolute humidity and temperature cycling.

Consequence:

An inflator explosion may result in sharp metal fragments striking the driver or other occupants resulting in serious injury or death.

Remedy:

Tesla will notify owners, and Tesla Service Centers will replace the passenger frontal air bag modules, free of charge. The recall is expected to begin in early March 2018. Owners may contact Tesla customer service at 1-877-798-3752. Tesla's number for this recall is SB-18-20-001.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



1200 New Jersey Avenue SE Washington, DC 20590

> NEF-150JK 18V-031

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Jennifer Kruger who may be reached by phone at (202) 366-2461, or by email at jennifer.kruger@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian Chief, Recall Management Division Office of Defects Investigations Enforcement

