U.S. Department of Transportation National Highway Traffic Safety Administration

January 17, 2018

Mr. John Turley Honda (American Honda Motor Co.) 1919 Torrance Blvd Torrance, CA 90501

Subject: Passenger Frontal Air Bag Inflator May Explode

Dear Mr. Turley:

This letter serves to acknowledge Honda (American Honda Motor Co.)'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years: ACURA/RL/2009-2012 HONDA/ELEMENT/2009-2011

HONDA/RIDGELINE/2009-2013

Mfr's Report Date: January 9, 2018

NHTSA Campaign Number: 18V-041

Components: AIR BAGS:PASSENGER SIDE FRONTAL

Potential Number of Units Affected: 24,945

Problem Description:

Honda (American Honda Motor Co.) is recalling certain 2010-2012 Acura RL, 2010 Honda Element, and 2010-2013 Honda Ridgeline vehicles ever registered in the states of Alabama, California, Florida, Georgia, Hawaii, Louisiana, Mississippi, South Carolina, Texas, Puerto Rico, American Samoa, Guam, the Northern Mariana Islands (Saipan), and the U.S. Virgin Islands or "Zone A."

Additionally, Honda is recalling certain 2010 Acura RL, 2010-2011 Honda Element and Honda Ridgeline vehicles ever registered in the states of Arizona, Arkansas, Delaware, District of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, and West Virginia or "Zone B."

If not included in zones A or B above, Honda is recalling certain 2009 Acura RL, Honda Element, and Honda Ridgeline vehicles ever registered in the states of Alaska, Colorado, Connecticut, Idaho, Iowa, Maine, Massachusetts, Michigan, Minnesota, Montana, New Hampshire, New York, North Dakota, Oregon, Rhode Island, South Dakota, Utah, Vermont, Washington, Wisconsin, and Wyoming or "Zone C."

These vehicles are equipped with certain air bag air bag inflators assembled as part of the frontal air bag modules, and used as original equipment or replacement equipment (such as after a vehicle crash necessitating replacement of the original air bags), may

NHTSA

1200 New Jersey Avenue SE Washington, DC 20590

> NEF-150SM 18V-041

explode due to propellant degradation occurring after long-term exposure to lower absolute humidity, temperature and temperature cycling.

Consequence:

An inflator explosion may result in sharp metal fragments striking the driver or other occupants resulting in serious injury or death.

Remedy:

Honda will notify owners, and dealers will replace the passenger frontal air bag inflator, free of charge. The recall is expected to begin February 12, 2018. Owners may contact Honda customer service at 1-888-234-2138. Honda's numbers for this recall are U0H, and G0I.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

We have received Honda's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Sarah Mcshane who may be reached by phone at (202) 366-7401, or by email at sarah.mcshane@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian Chief, Recall Management Division Office of Defects Investigations Enforcement

