

# Recall Quarterly Report

# 18V-082

**Manufacturer Name :** Volkswagen Group of America, Inc.  
**NHTSA Recall No. / MFR Recall No. :** 18V-082 / 69R6  
**Recall Subject :** Driver's Frontal Air Bag Inflator May Rupture  
**Owner Notification Beginning Date :** FEB 23, 2018  
**Owner Notification End Date:** OCT 04, 2018



| Report # | Submission Date | Report Quarter | Recall Population | Total Remedied | Total Unreachable | Total Removed |
|----------|-----------------|----------------|-------------------|----------------|-------------------|---------------|
| 4        | JAN 30, 2019    | 2018-4         | 97,440            | 80,337         | 623               | 37            |
| 3        | OCT 29, 2018    | 2018-3         | 97,440            | 59,919         | 752               | 40            |
| 2        | JUL 30, 2018    | 2018-2         | 97,440            | 43,764         | 900               | 40            |
| 1        | APR 27, 2018    | 2018-1         | 97,440            | 8,981          | 0                 | 0             |

This Document Last Updated : JAN 31, 2019

## Definitions :

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.