OMB Control No.: 2127-0004

Recall Quarterly Report

18V-103

Manufacturer Name: Mitsubishi Motors North America, Inc. **NHTSA Recall No. / MFR Recall No.:** 18V-103 /SR-18-004

Recall Subject: Wiper Link Can Corrode Due to Moisture Exposure

Owner Notification Beginning Date: MAR 27, 2018

Owner Notification End Date: MAR 27, 2018



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	APR 26, 2018	2018-1	158,651	12,660	0	1,792

This Document Last Updated: APR 27, 2018

Definitions:

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3^{rd} quarter of 2012).

Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.