

**Recall Quarterly Report****18V-118**

**Manufacturer Name :** Hyundai Motor America  
**NHTSA Recall No. / MFR Recall No. :** 18V-118 /173  
**Recall Subject :** Steering Wheel May Detach from Steering Column  
**Owner Notification Beginning Date :** MAR 26, 2018  
**Owner Notification End Date:** APR 17, 2018



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	OCT 26, 2018	2018-3	41,070	37,142	233	0
2	JUL 27, 2018	2018-2	41,070	35,502	233	0
1	APR 18, 2018	2018-1	41,070	17,303	0	0

This Document Last Updated : OCT 29, 2018

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.