

U.S. Department of Transportation

National Highway Traffic Safety Administration

March 1, 2018

Ms. Celina Tyler Thor Motor Coach P. O. Box 1486 Elkhart, IN 46515 1200 New Jersey Avenue SE Washington, DC 20590

NEF-150MR 18V-120

Subject: Seat Belt Bracket Strength Insufficient/FMVSS 210

Dear Ms. Tyler:

This letter serves to acknowledge Thor Motor Coach's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

THOR/OUTLAW/2018-2019

Mfr's Report Date: February 19, 2018

NHTSA Campaign Number: 18V-120

Components:

SEAT BELTS: REAR:BUCKLE ASSEMBLY

Potential Number of Units Affected: 65

Problem Description:

Thor Motor Coach (TMC) is recalling certain 2018-2019 Outlaw recreational vehicles, model 29J. The sofa seat belt bracket may not meet the strength requirements and may not adequately restrain an occupant in the event of a crash. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 210, "Seat Belt Assembly Anchorages."

Consequence:

If the bracket does not meet the strength requirements, the anchorage may fail in the event of a crash, increasing the risk of injury.

Remedy:

TMC will notify owners, and dealers will install a new bracket, free of charge. The recall is expected to begin April 19, 2018. Owners may contact TMC customer service at 1-877-855-2867. TMC's number for this recall is RC000151.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



Under 49 U.S.C. § 30112(a), it is illegal for anyone, including a manufacturer, distributor, dealer, or retailer to sell an item of equipment or vehicle that fails to comply with all applicable Federal motor vehicle safety standards.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Michelle Rice who may be reached by phone at (202) 366-1060, or by email at michelle.rice@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian

Chief, Recall Management Division Office of Defects Investigations

Enforcement

