

April 9, 2018

Ms. Jennifer Shute Sr Mgr Safety Recall Execution Chrysler (FCA US LLC) 800 Chrysler Drive CIMS 482-00-91 Auburn Hills, MI 48326

Subject: Rear Liftgate May Open Unexpectedly

Dear Ms. Shute:

This letter serves to acknowledge Chrysler (FCA US LLC)'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years: ALFA ROMEO/STELVIO/2018

Mfr's Report Date: March 29, 2018

NHTSA Campaign Number: 18V-203

**Components:** STRUCTURE:BODY:HATCHBACK/LIFTGATE

Potential Number of Units Affected: 12,595

## **Problem Description:**

Chrysler (FCA US LLC) is recalling certain 2018 Alfa Romeo Stelvio vehicles. Water may Leak into the wiring connectors for the rear liftgate and the liftgate-opening switch, causing corrosion.

## **Consequence:**

Corrosion at the connectors may cause the liftgate to unintentionally open while moving at speeds of less than 3 miles per hour, allowing cargo to fall out of the vehicle, creating a road hazard and increasing the risk of a crash.

## **Remedy:**

Chrysler will notify owners, and dealers will install additional protection against water leaking into the liftgate wiring connectors and switch, free of charge. The recall is expected to begin May 18, 2018. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is U34.

## Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



1200 New Jersey Avenue SE Washington, DC 20590

> NEF-150SM 18V-203

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Sarah Mcshane who may be reached by phone at (202) 366-7401, or by email at sarah.mcshane@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian Chief, Recall Management Division Office of Defects Investigations Enforcement

